HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



TYPE OF SUBSTRUCTURE ABUTMENTS: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION BENTS: CONCRETE PILE BENT ON PILE FOUNDATION PIERS: NOT APPLICABLE Scour EVALUATION Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. INSPECTION PROCEDURES	BRIDGE ID NUMBER: 92SR1180017	COUNTY: WEAKLEY
CROSSING: OVERFLOW COUNTY SEQUENCE: 1 LATITUDE:: N 36.43622 DEGREES LONGITUDE: W 88.71711 DEGREES TYPE OF SUPERSTRUCTURE MAIN SPAN: CONCRETE - TEE BEAM APPR. SPAN: NOT APPLICABLE TYPE OF SUBSTRUCTURE ABUTMENTS: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION BENTS: CONCRETE PILE BENT ON PILE FOUNDATION PIERS: NOT APPLICABLE SCOUR EVALUATION Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. INSPECTION PROCEDURES	BRIDGE OWNER: STATE OF TENNESSEE	ROUTE: SR118
LATITUDE:: N 36.43622 DEGREES LOG MILE: 10.14 LONGITUDE: W 88.71711 DEGREES YEAR BUILT: 1954 TYPE OF SUPERSTRUCTURE MAIN SPAN: CONCRETE - TEE BEAM APPR. SPAN: NOT APPLICABLE ABUTMENTS: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION BENTS: CONCRETE PILE BENT ON PILE FOUNDATION PIERS: NOT APPLICABLE SCOUR EVALUATION Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. INSPECTION PROCEDURES	ROAD NAME: SR118	SPECIAL CASE: 0
LONGITUDE: W 88.71711 DEGREES YEAR BUILT: 1954 TYPE OF SUPERSTRUCTURE	CROSSING: OVERFLOW	COUNTY SEQUENCE: 1
TYPE OF SUPERSTRUCTURE MAIN SPAN: CONCRETE - TEE BEAM APPR. SPAN: NOT APPLICABLE TYPE OF SUBSTRUCTURE ABUTMENTS: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION BENTS: CONCRETE PILE BENT ON PILE FOUNDATION PIERS: NOT APPLICABLE SCOUR EVALUATION Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. INSPECTION PROCEDURES	LATITUDE:: N 36.43622 DEGREES	LOG MILE: 10.14
MAIN SPAN: CONCRETE - TEE BEAM APPR. SPAN: NOT APPLICABLE TYPE OF SUBSTRUCTURE ABUTMENTS: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION BENTS: CONCRETE PILE BENT ON PILE FOUNDATION PIERS: NOT APPLICABLE SCOUR EVALUATION Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. INSPECTION PROCEDURES	LONGITUDE: W 88.71711 DEGREES	YEAR BUILT: 1954
TYPE OF SUBSTRUCTURE ABUTMENTS: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION BENTS: CONCRETE PILE BENT ON PILE FOUNDATION PIERS: NOT APPLICABLE Scour EVALUATION Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. INSPECTION PROCEDURES		TYPE OF SUPERSTRUCTURE
ABUTMENTS: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION BENTS: CONCRETE PILE BENT ON PILE FOUNDATION PIERS: NOT APPLICABLE SCOUR EVALUATION Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. INSPECTION PROCEDURES	MAIN SPAN: CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE
BENTS: CONCRETE PILE BENT ON PILE FOUNDATION PIERS: NOT APPLICABLE SCOUR EVALUATION Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. INSPECTION PROCEDURES		TYPE OF SUBSTRUCTURE
PIERS: NOT APPLICABLE SCOUR EVALUATION Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. INSPECTION PROCEDURES	ABUTMENTS: CONCRETE STUB ABUTMENT ON CO	DNCRETE PILE FOUNDATION
SCOUR EVALUATION SCOUR EVALUATION Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. INSPECTION PROCEDURES	BENTS: CONCRETE PILE BENT ON PILE FOU	INDATION
Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition.	PIERS: NOT APPLICABLE	
has been installed and is in good condition. INSPECTION PROCEDURES		SCOUR EVALUATION
	Bridge is scour critical; bridge foundations detended has been installed and is in good condition.	ermined to be unstable for calculated scour conditions. Rip-rap protection
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection? [] BridgeWatch Alert	What Initiated the Call-out Inspection?	[] BridgeWatch Alert

- [] TDOT District or Local Maintenance Personnel
- [] THP or Local Law Enforcement Personnel
- [] Other: _

Things to check on a bridge during floods:

- [] Span movement horizontally as well as vertically
 - 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck.
 - 2. Check for plumb of piers or bents.
- [] Check for embankment erosion
- [] Check for drift build-up on piers or bents
- [] Check pier exposure, if possible, and compare to previous inspection
- [] Review the latest bridge inspection report versus current field conditions

If Closure is recommended:

- [] Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.
- [] Contact: (1) District Maintenance Supervisor (if bridge is State maintained)
 - (2) City or County Highway Maintenance Official (if bridge is not State maintained)
 - (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate
 - (4) TDOT Regional Bridge Engineer
- [] The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.

PUBLICATION DATE

07-Nov-24

BRIDGE ID 92SR1180017



- [] The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.
- [] The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.

CONTACT PERSONNEL:	TELEPHONE NUMBER:
REGION BRIDGE ENGINEER	(731) 234-9561
DISTRICT MAINTENANCE SUPERVISOR	(731) 571-8883
TENNESSEE HIGHWAY PATROL	(731) 423-6635

[] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.

COMMENTS: _____

Suggested List of Equipment to conduct the Inspection:

Latest Bridge Inspection Report

Scour POA Report with the above Checklist

Bridge Design Plans, if available

Tape measure with weight

Plumb bob

Range Pole

A 1000 Foot Roll of yellow Polyethylene Barricade Tape printed with the following message:

SAFETY HAZARD KEEP AWAY

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)

PUBLICATION DATE