
SHELBY COUNTY



BRIDGE MAINTENANCE RECOMMENDATIONS

COUNTY: SHELBY

LOCATION: 79-SR057-08.18-R

CO. SEQ.: 1 SPEC. CASE: 0



REPAIR LIST NO.: CROSSING: 1240

DATE ADDED: 11/05/2004 FED. BRIDGE NO.: 79102400111 REVISED: 03/04/2013

MAINT. DIST.: 79

FACILITY CARRIED:			57 EB	NUMBER OF MAIN SPANS:	4		
HIGHWAY SYSTEM:	13-NHS URBAN		E SYS.	NUMBER OF APPROACH SPANS:	0		
BRIDGE WIDTH (CURB TO CURB):		53 FT	9 IN	BRIDGE LENGTH (FT):	243		
BRIDGE WIDTH (OUT TO OUT):		59 FT	8 IN	MAXIMUM SPAN LENGTH (FT):	79		
APPROACH ROADWAY (W/SHOULDERS):		60 FT	0 IN	SKEW ANGLE (DEGREES):	69		
	•						
MAINTAINED BY:							
MAIN SPAN MATERIAL:							
MAIN SPAN DESIGN TYPE:		STRINGER/MULTI-BEAM OR GIRDER					
APPROACH SPAN MATERIAL:			OTHER OR NOT APPLICABLE				
APPROACH SPAN DESIGN TYPE:							
INSPECTION DATE:	03/04/2013		GENERAL CONDITION:				
EVALUATION DATE:	04/19/2011	STRUCTURALLY DEFICIENT:					
PPRM PIN NUMBER:							
H TRUCK RATING @ INV.:	20 TONS	SUFFICIENCY RATING: 6					

SUGGESTED ROUTINE MAINTENANCE AND COMMENTS				
REPAIR CONCRETE BEAM "G" SPAN NO.1				
REPAIR DIAPHRAGMS IN SPAN NO.2				
REPLACE CONCRETE RISER BLOCKS AT BENT NO.1				
CLEAN AND SEAL ROADWAY EXPANSION JOINTS.				

GENERAL COMMENTS:

03-04-2013 UNDERPASS IS UNDER CONSTRUCTION. ABUTMENT # 1 EARTHQUAKE DEVICES NOT CONNECTED.

Evaluation Status:

Bridge Condition Coding Form

Revised 03/05/2013

8.18

Log Mile:

79 County: DEPARTMENT OF TRANSPORTATION **Route:** SR057 Bridge Number: 791024001111 (Includes Item 5A) **Special Case:** 0 **Feature Intersected: I240 County Sequence:** 1

CODE ONLY THOSE VALUES WHICH HAVE CHANGED

NO CHANGE BUT STILL EVALUATE

TEM#	DESCRIPTION	VALUE			
90	LAST INSPECTION DATE	03	1		
	EARLIEST DATE OF	01/03/2015			1
	NEXT REGULAR INSPECTION	/ /			
10	MINIMUM V.C. OVER DECK	99	FT. FT		IN. IN.
520	(ROADWAY + SHOULDERS) MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS)	99	FT. FT	99	IN. IN.
36	TRAFFIC SAFETY FEATURES Br. Rail Trans. Appr. Rail Te 1 1 1	rmina 1	l SPI	EED LI 40	МІТ
41	STRC OPEN/CLOSED/POSTED A K P		A		_
58	DECK		4		
59	SUPERSTRUCTURE		5		
60	SUBSTRUCTURE		5		
61	CHANL/CHANL PROTECTION		N		
62	CULVERT AND RETAIN WALL		N		
71	WATERWAY ADEQUACY				
72	APPROACH RDWY ALIGNMENT		6		
521	OVERALL CONDITION	(POO	R	
	LATITUDE 17 LONGITUD N 35 ° 6.1133 ′ W 89 ° 52.2217	_			_
	EAM LEADER SIGNATURE		/ REVIEV	/ W.D.475	

CONDITION CODING GUIDELINES

(Values for Coding Items 58, 59, 60 and 62)

- N NOT APPLICABLE
- 9 EXCELLENT CONDITION
- **VERY GOOD CONDITION NO** PROBLEMS NOTED.
- 7 GOOD CONDITION SOME MINOR PROBLEMS.
- SATISFACTORY CONDITION MINOR DETERIORATION OF STRUCTURAL ELEMENTS.
- 5 FAIR CONDITION ALL PRIMARY STRUCTURAL ELEMENTS ARE SOUND BUT MAY HAVE MINOR SECTION LOSS, CRACKING, SPALLING OR SCOUR.
- 4 POOR CONDITION ADVANCED SECTION LOSS, DETERIORATION, SPALLING OR SCOUR.
- 3 SERIOUS CONDITION LOSS OF SECTION, **DETERIORATION, SPALLING OR SCOUR HAVE** SERIOUSLY AFFECTED PRIMARY STRUCTURAL COMPONENTS. LOCAL FAILURES ARE POSSIBLE. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT.
- CRITICAL CONDITION ADVANCED **DETERIORATION OF PRIMARY STRUCTURAL** ELEMENTS. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT OR SCOUR MAY HAVE REMOVED SUBSTRUCTURE SUPPORT. UNLESS **CLOSELY MONITORED IT MAY BE** NECESSARY TO CLOSE THE BRIDGE UNTIL CORRECTIVE ACTION IS TAKEN.
- "IMMINENT" FAILURE CONDITION MAJOR **DETERIORATION OR SECTION LOSS** PRESENT IN CRITICAL STRUCTURAL COMPONENTS OR OBVIOUS VERTICAL OR HORIZONTAL MOVEMENT AFFECTING STRUCTURAL STABILITY. BRIDGE IS **CLOSED TO TRAFFIC BUT CORRECTIVE** ACTION MAY PUT IT BACK IN LIGHT SERVICE.
- FAILED CONDITION OUT OF SERVICE AND BEYOND CORRECTIVE ACTION.



DIRECTION OF ROUTE



APPROACH 1 ASPHALT



SPAN 1 CONCRETE TOP DECK PATCHED



VIEW ACROSS DECK



BRIDGE NUMBER



SPAN 1 JOINT



SPAN 1 JOINT SPALLING



SPAN 2 LEFT BRIDGE MOUNT SIGN NUMBER



SPAN 2 JOINT



SPAN 3 JOINT



SPAN 3 RIGHTSIDE BRIDGE MOUNT SIGN NUMBER



APPROACH 2 ASPHALT



OPPOSITE DIRECTION OF ROUTE



SPAN 3 BRIDGE MOUNT SIGN



ABUTMENT 2 SLOPE PAVING MISSING



ABUTMENT 2



BENT 3 REAR



BENT 2 REAR



BOTTOM DECK SPAN 3



RIGHT ELEVATION SPAN 3



LEFT ELEVATION



BENT 2 CAP SPALLING



BENT 3 CAP BEGINNING TO SPALL



SPAN 4 BACKWALL SPALLING



SPAN 4 BEAM A SPALLING



SPAN 4 BEAM B SPALLING



SPAN 4 BEAM C SPALLING



SPAN 4 BEAM D SPALLING



SPAN 4 BEAM E SPALLING



SPAN 4 BEAM F SPALLING



SPAN 4 BEAM G SPALLING



SPAN 4 BEAM H SPALLING



SPAN 4 BEAM I SPALLING



SPAN 2 LEFT BRIDGE MOUNT SIGNS



LEFT ELEVATION SPAN 2



RIGHT ELEVATION SPAN 2



BOTTOM DECK SPAN 2



BENT 1



BENT 1 CAP SPALLING



BENT 1 RISER BLOCKS SPALLING



BENT 1 CAP SPALLING



SPAN 1 BEAM G SPALLING



ABUTMENT 1 EQ PLATE MISSING



ABUTMENT 1

Bridge ID#: 79-SR057-08.18



ABUTMENT 1 BEARING UNDER BEAM A PLATE MISSING



ABUTMENT 1 PLATE NOT BOLTED TO BEAM F,H,I TIP



SPAN 2 BEAM A SPALLING



SPAN 2 DIAPHRAGM SPALLING



SPAN 2 BETWEEN CONCRETE I BEAM A&B SPALLED TO STEEL/DELAMINATED



SPAN 2 BETWEEN CONCRETE I BEAM A&B SPALLED TO STEEL/DELAMINATED

Bridge ID#: 79-SR057-08.18 Date: 03/14/2013



SPAN 2 BETWEEN CONCRETE I BEAM A&B SPALLED TO STEEL/DELAMINATED



BRIDGE NUMBER



SPAN 2 BETWEEN CONCRETE I BEAM B&C SPALLING AND DELAMINATED



SPAN 2 BETWEEN CONCRETE I BEAM C&D RANDOM SPALLED AREAS



SPAN 2 BETWEEN CONCRETE I BEAM C&D RANDOM SPALLED AREAS



SPAN 2 BETWEEN CONCRETE I BEAM D&E DELAMINATED WITH NO SPALLING



SPAN 2 BETWEEN CONCRETE I BEAM F&G SPALLED TO STEEL/DELAMINATED FIRST 1/3 OF SPAN



SPAN 2 BETWEEN CONCRETE I BEAM J&K SPALLED TO STEEL/DELAMINATED FIRST 1/3 OF SPAN



SPAN 2 LAST/3RD IF SPAN BETWEEN CONCRETE I BEAM H&I BEGINNING TO SPALL WITH EFFLORESCENCE



SPAN 3 LAST/3RD IF SPAN BETWEEN CONCRETE I BEAM A&B SPALLED TO STEEL/DELAMINATED



SPAN 3 LAST/3RD IF SPAN BETWEEN CONCRETE I BEAM A&B SPALLED TO STEEL AND DELAMINATED



SPAN 3 LAST/3RD IF SPAN BETWEEN CONCRETE I BEAM A&B SPALLED TO STEEL AND DELAMINATED



SPAN 3 LAST/3RD IF SPAN BETWEEN CONCRETE I BEAM A&B SPALLED TO STEEL AND DELAMINATED



SPAN 3 BETWEEN CONCRETE I BEAM E&F BOTTOM DECK PAINTED FOR DELAMINATION



SPAN 3 BETWEEN CONCRETE I BEAM E&F BOTTOM DECK PAINTED FOR DELAMINATION



SPAN 3 BETWEEN CONCRETE I BEAM F&G BOTTOM DECK PAINTED FOR DELAMINATION

Photographs

Date: 03/14/2013

Bridge ID#: 79-SR057-08.18



SPAN 3 BETWEEN CONCRETE I BEAM J&K HAS PATCHED AREAS

BRIDGE INSPECTION REPORT

Form BIR 3.0	Field Report No.: 21	Date: <u>3 / 4/13</u>
(Rev. 9-22-98)	Previous Report No.: 20	Date: <u>4/14//1</u>
DT-0069	Co. Seq <u>01</u> Plans: YES (
Bridge No. 79I02400111 Bridge Location Eleven Digit No.	No. <u>79 - SR057 - 0818</u> Co. Route Log Mile	79 - 10240 - 1544 OVER/UNDER PASS
Road Name	Feature Intersected	CITY
Year Constructed 1960	County Shelby Maint. D	Dist: <u>45</u> Maint.Resp: <u>02</u>
Year Widened Year Rehabil		
	Structure	Name (If Named)
<u>FEATURES</u>		<u>INSPECTORS</u>
Wearing Surface Concrete (Timber () Asp		1. LEWIS
Flared Width Yes () No (Median W	(idth Open () None (Closed ()	2. LOVE
Navigational Control Yes () No (Y Bridge	Skew <u>R</u> ° LT()RT()	3. JONES
Structure Type (Main Span) CONCRETE I.	BEAM	4. LEECH
Structure Type (Appr.Spans)		5. C. YOUNG
No. Main Spans 4 No. Approach	Spans	6.
Maximum Span Length 79.0 (**.* ft.)	7.
Total Length 245.0 (**.* ft.		8.
Total Length Z 10.0	•	
WIDTHS (*.* ft.)	<u>CLEARANCES</u>	
Deck Out-to-Out 60.0	Min. Vertical Clearance over Dec	k(ftin.)
Roadway Curb/Curb 55.0	Min. Vertical Under Clearance	(ftin.)
Roadway Rail/Rail	Min. Lateral Under Clearance Rt.	(*.* ft.)
Sidewalk Rt. Lt.	Min. Lateral Under Clearance Lt.	(*.* ft.)
*Approach Roadway 48.0	FRACTURE CRITICAL:	
*(Does Not Include Shoulders)	(If Yes, Include BIR 3.9)	
Approach Shoulder Rt. 3.0		
Lt. 3.0	NBIS Bridge Length (<25 ft.)	(ftin.)
UNDERWATER INSPECTION	· · · · · · · · · · · · · · · · · · ·	
To Be Performed By:	Date	
DOT FIELD TEAM () CONTRACT DIVERS ()	NONE REQUIRED (🏏	
Change in Structural Condition: Yes () No	Major Repairs Made:	Yes() No(🗸
	ITE: UNDERPASS IS UNDER	CONSTRUCTION.
LATITUDE: N35 ° 6.1133 '		
LONGITUDE: W89 ° 52.2216 '	BRIDGE RATING: () ()	(/ ()
G.P.S. Location	BRIDGE RATING: () () GOOD FAIR	•
	GOOD PAIR	TOOK OKITIOAL
Supervising Bridge Inspector:	les -	

Form	BIR 3.1
(Rev.	9-22-98)
DT-00	080

Bridge Location No.	79	-	SR057	-	8.18 -	
-	Co		Route		Log Mile	

MAR Date	V	4	20	
-------------	---	---	----	--

P	ER	F	DR	RM	Α	NC	Έ	E١	/AL	UAT	rion

Time of Day Inspected				AM		Weather C	ondition	s_52	2° SUNNY	
Vehicles Observed	ALL									
LIVE LOAD BEHAVIO	R									
Substructure		Y	ES	NC	2	-		Co	mments	
Horiz./ Vert. Defl		()	(v	1					
Vibration	,	()	(,	}					
Superstructure		•	•	•	•					
Horiz./ Vert. Defl		()	(سلا					
Vibration		()	(}					
APPROACH	F	Ratin	ng	-				Co	mments	
Alignment	G	Ð	Р	С						
Slab	G	F	Р	С		NA				
Joints	G	F	Р	С		NA				
Pavement	G	Ð	Р	С		•				
Embankment	0	F	Р	С						
Drains	G	F	Р	С		NA				
TRAFFIC SAFETY FEA	TUF	RES	3							
		Rati		-	STA	NDARD/ SU	3-STAND	ARD	Comments	
Bridgerailing	G	Ê	Р	С		(W	()			
Transitions	(G)	F	Ρ	С		(Y	()			
Guardrail	Ğ	B	Р	С		()	()			
Guardrail Terminal	9	F	Р	С		(<i>V</i>	()			
SIGNING					YE	ES NO	NEEDEI	D	Weight Limit Posted	
Paddleboards					() (8	()		YES () NO (
Vertical Clearance (<14'-	-6")			() (4	()		Gross	Tons
NARROW ()					() (8	()		2 Axle	_ Tons
ONE LANE BRIDGE	Ξ ()			() (1	()		3 or more Axles	Tons
Other Signs or Plaq	ues:									
Comments Regardir Problems with Signi		٦y								

Date _____

SUBSTRUCTURE

PILES TO BE REPLACED

<u>ABUTMENTS</u>	Rating	Comments	PILE(S)	ABUTMENT
Caps Breastwall Wings Backwall Plumb Footing Pites 21562 846 Embankment Bearing Slope Paving Rip Rap Earthquake De	© F P C G F P C G F P C	ABUT #1- PLATE! BOLTS MI ABUT #2- SECTION MISSING ABUT #1- NOT CONNECTED	ssinc (?) ====================================
PIERS			PILE(S)	PIER
Caps Columns Plumb Footings Piles Bearing Web Earthquake De	G F P C G F P C G F P C G F P C G F P C vices G F P C	NA		
BENTS			PILE(S)	BENT
_	GPPCGFPCGFPC	BENT #1 - SPALLED UNDE		
	Piles Need Replacer			
	CUT VEGETATION CLEAR DRIFT ATIONS:	NO(YES()		

Inspection Team's Summary Bridge Location No. 79 - SR057 - 08.18 Inspection Date 03/04/13 Bridge Rating POOR

THIS 4 SPAN CONCRETE I BEAM BRIDGE IS IN POOR CONDITION.
THE APPROACH PAVEMENT HAS FINE CRACKS AND A SPALL AREA.
THE CONCRETE WEARING SURFACE HAS FINE CRACKS.
THE JOINT HEADER ON SPAN 1 IS SPALLING AND MATERIAL TORN.
THE BOTTOM DECK HAS FINE CRACKS, PATCHED AREAS AND SPALL
TO STEEL AREAS.

SPAN 1 CONCRETE I BEAM(G) IS SPALL TO STEEL.

SPAN 4 CONCRETE I BEAM A-I AT END OF BEAMS ARE BEGINNING TO SPALL.

SPAN 2 DIAPHRAGM SPALL TO STEEL.

THE CONCRETE SUBSTRUCTURE HAS FINE CRACKS, BEGINNING TO SPALL AND SPALL TO STEEL.

ABUTMENT 2 SECTION OF SLOPEPAVMENT MISSING DUE TO CONSTRUCTION, ABUTMENT 1 PLATE AND BOLT MISSING. ABUTMENT 1 EQ NOT CONNECTED.

BENT 1 RISER CLOCK SPALLING UNDER CONCRETE I BEAM A&B, THE VERTICAL CLEARANCE IS UNDER CONSTRUCTION.

SPAN 2&3 HAS WOODEN FORMS LEFT IN PLACE FOR POTENTIAL FOR CONCRETE TO FALL ON TO ROADWALL.

BENT 2 CAP HAS SECTION BEGINNING TO SPALL THAT COULD FALL INTO ROADWAY.

NOTE: BRIDGE IS RATED POOR DUE TO UNKNOWN CONDITION OF SPAN 2&3 BOTTOM DECK UNDER PLYWOOD FORMS.

RANDY LOVE	
INSPECTOR	

CROSS SECTION: YES () NO (X) PONTIS: YES (X) NO ()

79 BRIDGE NO.: 79I02400111 SR057 0818 DATE: CO. ROUTE LOG MILE L/R SKEW **APPROACH #2** AC, D CONG 48 AG APPROACH #1 **RATING** COMMENTS **ELEMENT** APROACHTIBULLT IN CURUE G P C **ALIGNMENT** SEE (2) AND FINECRALAS G P C APPROACH PAVEMENT **APPROACH SLAB** G-F-P-C SEF 3 G P C APPROACH GUARDRAIL **℃**F P C **EMBANKMENT** GFPC **DRAINS** GFP C APPROACH JOINT **SIGNS** GFPC


	2-57-8,				
Bridge No. Co	o. Route Log	g Mile R/L	Skew	SPA	AN. NO
	i	V	0		
<u></u>		c.NG			
	J CON	IC, PATCH			DJCINI HEADER SPALLING Z" Z" 4" AND
ELEMENT	RATING		COMMENT		MATERZAL TORI
TOP DECK	GO P C	SFE @	FINEC	RACHS	
PARAPET	G P C	FINE	FINE CI	•	
DRAINS	Ø F P C				
JOINTS	G F C C	SEEO			
	GFPC				

Bridge No. ________ SKEW R\L ______ Span No. ______


n pateholar 0 1 3 5 pm/1 To stree Fine chacks + Potch and + see (12) Not CONNECTAL CTB (A) ٢ (COMMENTS G Ì 1 ட OSPUT TO Steel GROWING Drain LOOKING AHEAD I.O/DIA X 2"/H 1 **LOOKING BACK** Ш Ω ſ G F P C G(F)P C G FOC G(P)PC RATING O > .) Ω DIA. (5) 877 03 CONC. I BEAM
A --- Z **BOTTOM DECK** BACKWALLS ⋖ ELEMENT

 $\frac{79-57-8.18}{\text{Bridge No. Co. Route Log Mile R/L Skew}}$

SPAN. NO. 2




ELEMENT	RATING	COMMENT
TOP DECK	O F P C	
PARAPET	G P C	FZNE CRACKS
DRAINS	G F P C	
JOINTS	⊘ FPC	
STON	O FPC	




 $\frac{79-57-8,18}{\text{Bridge No. Co. Route Log Mile R/L Skew}}$

SPAN. NO. 3




ELEMENT	RATING	COMMENT
TOP DECK	Ø F P C	
PARAPET	G ⊕ P C	FINE CRACKS
DRAINS	GFPG	
JOINTS	GFPC	
SIGN	Ø F P C	

Span No. 73




	79-	57	- 8, 18		
Bridge No.	Ċo.	Route	Log Mile	R/L	Skew

SPAN. NO.




· · · · · · · · · · · · · · · · · · ·		
ELEMENT	RATING	COMMENT
TOP DECK	G Ø P C	FINE CHACKS
PARAPET	G ⊕ P C	
DRAINS	GF P C	
JOINTS	G FP C	
	GFPC	

Bridge No. _________ SKEW R\L ______ Span No. ________




MAR 0 4 2011



See Plans For Elev.


best worth-		State Conduction of the Conduc		
			GR. LINE	
· · · · · · · · · · · · · · · · · · ·		LOOKING	AHDAO	1
	ELEMENT	RATING	COMMENT	liew of
	BEARING	© F P C		C4P
4.				arv - stage s
	CAP	G P C	FINE CRACK	
	COLUMN A	© F P C		
	B	Ø F P C		-
		+DGFPC		
	Riser Blocks	OFPC		
	FOOTING	G F P C	NIV	- 13
				•
	E.Q.	GFPC		
. •				
	*			
	The state of the s			




ELEMENT		RATING	COMMENT
BEARING	من و دود د د د د د د د د د د د د د د د د	© F P C	
-			
CAP		G P C	SPALLED / SPALLED TO STEEZ / FINE (RACKS
			BEGINNING TO SPALL
COLUMN	A	G F P.C	
	В	© F P C	
	C	© F P C	
	۵	G	
FOOTING		GFPC	N/V

Riser B	locks	GFDC	SPALLED TO STEEL UNDER CIR "A" " "B
CONC. PARA	PET	B	FINE CRACKS
E.Q.		OF PC	
84.2			

See Plans For Elev.



ELEMENT	RATING	COMMENT
BEARING	GFPC	
CAP .	G F P C	the cracks , see Buckside
COLUMN A	G F P C	
В		
G	GFPC	
FCOTING	GFPC	NN
Riser Blocks	(GFPC	
E.Q	(C) = PC	
Parapet	(F)	Fine clacks
V		



1	1	A
RATING	COMMENT	
G F P C		D Chipprelares
		5"01ax 4"D
G(F) P C	SCE (2) B) fine CYNKS	Ospulling "
		1'HX I'WX \$110
G P C	see(1)	3 Begining to gas
		Begining +0 spr
		fall involding
	•	ZINXIH
GFPC	W//	
(A) F PC		and and the state of the state
(3).		
CERC		
7.15		
(F)	CNECCIA	
	WILLS ALL'S	Constitution of the Consti
	GFPC GFPC	GFPC GFPC SCE (2)(3), fine Cracks GPPC SEED GFPC GFPC GFPC

LOOKING Ahead

The state of the s			à
ELEMENT	RATING	COMPENT	
BEARING	G F P C	DegM+ & Zwxe"H	>50V/)
		Zwxe"H	•
CAP	GFPC	See Dy fine wacks	
COLUMN A	G F P C		
В	GFPC		
C4D	G F P C		
FOOTING	GFPC	W	• •
Riser Blocks	G(F)PC	f.necralus	
E.Q.	GFPC		
Darapet	(F)	F.necracks	

LOOKING Back

~·· •				A
,	ELEMENT	RATING	COMENT	
2 P	BEARING	GFPC		
_				
	CAP	GFPC		
	COLUMN A	GFPC		
	В	GFPC		
	C	G F P C		. ,
	FOOTING	G F P C	top to	wit-
			15CC TIC	W/T
	Riser Blocks	GFPC		

***	E, 9.	OFPC		
	•		•	

				5	
			LOOKING	Ahead	
·					The state of the s
	\int				The second secon
and the second of the second	ELEMENT	RATING		COLLENT	
, T.	BEARINGS	GFPC			O Slope pur missing 30/WX45/L (under construction
	CAP	GFP C	EME CYALKS		moshy
	PILING	GFPC	NN		30 WX 45 L
	WINGS	GFPC			(under construction
	VEG.	GPPC			
	EMBANKMENT	GFPC	*	•	
	RIP RAP	GFPC			
	SLOPE PAVIN		see0		
	E. Q.	(PE & C			
	Riser	6			
	RIOCKS				



Bridge Number:

(Includes Item 5A)

Feature Intersected:

Underpass Condition Coding Form

Revised 03/05/2013

County: 79 Route: I0240 Special Case: 0 **County Sequence:** 1 Log Mile: 15.57

CODE ONLY	THOSE	VALUES	WHICH HAVE	CHANGED
CODE ONLI	THOSE	VALUES	WILLCHILLAND	CHANGED

79I024001112

SR 57 EBL / I240

ITEM#	DESCRIPTION	ſ			VAL	UE		UN	DERPASS SAFETY FEAT	URES
90	LAST INSPECTI EARLIEST DATE NEXT REGULAR INSP	E OF				2013 2015 /]	515	(A) TYPE UNDERPASS BAI COMBINATION OF M & CONCRETE BARRIE RAIL	ETAL
10	MINIMUM V.C. DECK (ROADWAY + SI						IN. IN.		Revised Barrier Type (B) ADEQUACY OF	e 1
520	MINIMUM V.C. (EXCLUDES SHO					5			BARRIER OR RAIL	
47	TOTAL HORIZONTAL			65		6	IN. IN.		(C) ADEQUACY OF TRANSITIONS	0
54	UNDERCLEARA MINIMUM VER' (EXCLUDES SHO	FICAL UNDERC	LEARAN	ICE					(D) ADEQUACY OF TERMINALS	0
	(Excepts on	Circle One: H	R		FT.		IN.	554	VERTICAL CLEARANCE LISTED ON HEIGHT	
55	MINIMUM LATI UNDERCLEARA SIDE				FT.		IN.		POSTING FT FT	IN. IN.
56	MINIMUM LATI UNDERCLEARA SIDE				FT.		IN.	16		° 52.2217
521	OVERALL CON	DITION		POOR					HEIGHT POSTED AT BOTH APPROACHES?	YES[] NO[] N/A[]
555	COMMENTS _									
	_ _ _									

BRIDGE MAINTENANCE RECOMMENDATIONS

COUNTY: SHELBY

LOCATION: 79-I0240-15.57-

SPEC. CASE: 0 CO. SEQ.: 1

MILEPOST: 15.58

CROSSING: SR 57 EBL / I240 FED. BRIDGE NO.: 79102400111



N

REPAIR LIST NO.:

DATE ADDED:

MAINT. DIST.: 79		REVISED:	03/04/2013
FACILITY CARRIED:	FAP 57	NUMBER OF MAIN SPANS:	
HIGHWAY SYSTEM: 02-	INTERSTATE URBAN	NUMBER OF APPROACH SP	ANS:
BRIDGE WIDTH (CURB TO CURB):	N/AFT IN	BRIDGE LENGTH (FT):	243
BRIDGE WIDTH (OUT TO OUT):	$\overline{\mathrm{N/A}}\mathrm{FT}$ IN	MAXIMUM SPAN LENGTH (FT): 79
APPROACH ROADWAY (W/SHOULDERS):	187 FT 11 IN	SKEW ANGLE (DEGREES):	N/A
MAINTAINED BY:			
MAIN SPAN MATERIAL:		PRESTRESSED CONCRETE	
MAIN SPAN DESIGN TYPE:	STRINGER/	MULTI-BEAM OR GIRDER	
APPROACH SPAN MATERIAL:			
APPROACH SPAN DESIGN TYPE:			
INSPECTION DATE: 03/04/20	13 G	ENERAL CONDITION:	POOR
EVALUATION DATE: 04/19/20	11 S	TRUCTURALLY DEFICIENT:	
PPRM PIN NUMBER:			
H TRUCK RATING @ INV.: TO	NS S	UFFICIENCY RATING:	
HIGHWAY SYSTEM: BRIDGE WIDTH (CURB TO CURB): BRIDGE WIDTH (OUT TO OUT): APPROACH ROADWAY (W/SHOULDERS): MAINTAINED BY: MAIN SPAN MATERIAL: MAIN SPAN MATERIAL: APPROACH SPAN MATERIAL: APPROACH SPAN MATERIAL: APPROACH SPAN MATERIAL: APPROACH SPAN DESIGN TYPE: INSPECTION DATE: 03/04/2013 EVALUATION DATE: 04/19/2011 PRESTRESSED CONCRETE STRINGER/MULTI-BEAM OR GIRDER GENERAL CONDITION: STRUCTURALLY DEFICIENT: PRESTRESSED CONCRETE STRINGER/MULTI-BEAM OR GIRDER STRUCTURALLY DEFICIENT:			
		MMENDATIONS	

GENERAL	COMMENTS:
CLITTICIL	COINILITIES.

Page 1 of 2 INSPECTION REF	ORT FOR UNDERPASS ROU Field Report No.		
(Rev. 9-22-98)			
DT-1443			
Bridge No. 79102400111_	Underpass	Location No. 79	
Eleven Digit No.		Co. over/	Route Log Mile
or	 D Route Log Mi	under	- I0240 - 1544 Route Log Mile
Railroad/Walkway Co	Route Log Mi Structure Name (I		1,0000
CountyShelby	Structure Marrie (i		
Year Constructed	 Year Rehabili	tated	
Year Widened			
GEOMETRIC FEATURES UNDER BRI		ss otherwise noted) (1)
Divided Highway LEFT RDWY (RIGHT RDWY	() N.A. ()	
Type of Wearing Surface CONC	RETE (_), ASPHAL	T(X) GRAVEL (
Width of Approach Traveled Roadway	<u> </u>	oes Not Include Sh	noulders)
Width of Median if Divided Highway	<i>Ho</i> ft.		
Approach Shoulder Width	<u>/_5</u> ft. Ri	ght	ft. Left
*Horizontal Clearance Under Bridge	<i>&&</i> ft.	\mathcal{L}	in.
*Distance Between Pier Protection	, n	-14	ft. Left
Guardrail and Substructure	ft. Ri		ft. Left
*Width of Sidewalk Under Bridge	ft. Ri		
*Minimum Vertical Clearance:	ft	in.	
*Show on Sketch	UNDERPASS IS	UNDER CONSTRUC	TIOM
TRAFFIC SAFETY FEATURES FOR L			
	ST	ANDARD SUB-ST	ANDARD NON EXIST
Pier Protection Railing or Parapet	GFPC	()	()
Approach Guardrail Transitions	GFPC	()	()
Approach Guardrail	GFPC	()	()
Approach Guardrail Terminal	GFPC	() ()	()
	_		
SIGNING FOR UNDERPASS ROUTE		EDED ()	INSPECTORS
Paddleboards YES	S () NO () NE	:EDED ()	
Vertical Clearance (<14'-6") YE	S () NO () NE		LEWIS
VE	S () NO () NE S () NO () NE		
One Lane Passage	3 () NO (4) NE	3.	
		1	
Other Underpass Signs Needed		4.	

	Field Report No	ROUTE Mage Nos LU
Form BIR 3.0A	Previous Report No.	
(Rev. 9-22-98) DT-1443		
Bridge No. 79I02400111_	Underpass Location No.	79 - SR057 - 0818 -
Eleven Digit No.	over/	Co. Route Log Mile
or	under	79 - I0240 - 1544
Railroad/Walkway Co	. Route Log Mile	Co. Route Log Mile
CountyShelby	Structure Name (If Named)	
Year Constructed		
Year Widened	Year Rehabilitated	
GEOMETRIC FEATURES UNDER BRI	DGE (*.* ft. unless otherwise	noted)
Divided Highway LEFT RDWY ((3)
	RETE() ASPHALT(X) GRAV	'EL ()
Width of Approach Traveled Roadway	36 ft. (Does Not Inclu	
Width of Median if Divided Highway	76 ft.	
Approach Shoulder Width	18,5 ft. Right	//ft. Left
*Horizontal Clearance Under Bridge	ft	<i>6</i> IN.
*Distance Between Pier Protection		
Guardrail and Substructure	ft. Right	ft. Left
*Width of Sidewalk Under Bridge	ft. Right	ft. Left
*Minimum Vertical Clearance:	ftin.	
*Show on Sketch	: underpas is under	enetruction
TRAFFIC SAFETY FEATURES FOR L	JNDERPASS ROUTE	
		B-STANDARD NON EXIST
Discontinuo Dailing or Paranet	GFPC ()	()
Pier Protection Railing or Parapet	GFPC ()	()
Approach Guardrail Transitions	GFPC ()	()
Approach Guardrail	G F P C ()	()
Approach Guardrail Terminal		
SIGNING FOR UNDERPASS ROUTE		INSPECT <u>ORS</u>
Paddleboards YES	S() NO (NEEDED ()	INSPLOTONO
Vertical Clearance (<14'-6") YES	S () NO (NEEDED ()	1. LEWIS
Narrow Passage YES	S() NO(X NEEDED()	2.
One Lane Passage	S () NO (NEEDED ()	3.
Other Underpass Signs Needed		4

Page 2 of 2	Page No
Form BIR 3.0A (Continued)	Date
	derpass Location No. 79 - SR057 - 0818 - Co. Route Log Mile
	ECK FORMS AT SPAN #2 # #3
FOR BRIDGE MOUNT SIGNS	
Comments Regarding any Problems with Signing:	·
BRIDGE FEATURES (*.* ft.)	
Bridge Skew °	
Structure Type (Main Span)	No. Main Spans
Structure Type (Appr.Spans)	No. Appr. Spans
Maximum Opan Longar	Total Length(ft.)
Width of Bridge Car to Car ()	Right Angle to Centerline of Bridge)
Width of Bridge Along Skew(ft.)	(If Unable to Measure at Right
Number of Lanes/Tracks on Bridge	Angle to Centerline of Bridge)
BRIDGE CONDITION: G F C	
	lling on Roadway Beneath YES (YNO ()
Does Potential Exist for Elements from Bridge Fa	illing of Roadway Beneath
Does Potential Exist Because of Deteriorated Co	ndition or Failure of Major Member YES()NO (イ
Comment on any Conditions of Bridge that would	2.44
SPAN # 2: #3 HAS WOODEN FORM	2 Contraction of the contraction
POTENTIAL FOR CONCRETE TO FALL ON	
# Z CAP HAS A SECTION REGINNING	TO SPALL THAT COULD FALL

Note: If Underpass Route is Divided Highway, Use Two of These Forms, One for Each Roadway.


MINIMUM PICTURES REQUIRED

- 1. Elevation View of Bridge on Both Sides Showing Underpass
- 2. View Showing Both Approaches to Bridge
- View Showing Safety Features
 View Showing Any Problems

BIR 3.10 Rev. 06/22/01 ET-1510


BRIDGE LOC. NO. <u>79 SR057 0818 - CO. ROUTE L. M. L/R</u>

DATE:




79I02400111 79 SR057 0818 SKEW: --R
BRIDGE NO.: CO. ROUTE L.M. L/R

Direction of Route



SIDE OF BRIDGE



51.0 5,780 509.6 9250 _ m 3 ~ 1,625 160


448 Jump Jum

ABUT WENT D

TOTAL

0

STANDARD 3 A HANDRAIL - STO



79 - 57 - 8,18

013