
SHELBY COUNTY



BRIDGE MAINTENANCE RECOMMENDATIONS

COUNTY: SHELBY LOCATION: 79-SR057-08.09-L CO. SEQ.: 1 SPEC. CASE: 0

Г



 CROSSING: 1240 & 1240 EXIT RAMP
 REPAIR LIST NO.:
 2

 FED. BRIDGE NO.: 79102400112
 DATE ADDED:
 10/05/1994

 MAINT. DIST.: 79
 REVISED:
 03/04/2013

FACILITY CARRIED: FAU			57 WB	NUMBER OF MAIN SPANS:	5
HIGHWAY SYSTEM:	13-NHS URBA	N, STATE	SYS.	NUMBER OF APPROACH SPANS:	0
BRIDGE WIDTH (CURB TO CUR	RB):	40 FT	0 IN	BRIDGE LENGTH (FT):	285
BRIDGE WIDTH (OUT TO OUT)	: -	54 FT	1 IN	MAXIMUM SPAN LENGTH (FT):	68
APPROACH ROADWAY (W/SHOUI		40 FT	0 IN	SKEW ANGLE (DEGREES):	76
	—				
MAINTAINED BY:				STATE HIGHWAY AGENCY	
MAIN SPAN MATERIAL:				PRESTRESSED CONCRETE	
MAIN SPAN DESIGN TYPE:	STR	INGER/	MULTI-BEAM OR GIRDER		
APPROACH SPAN MATERIAL:		OTH	IER OR NOT APPLICABLE		
APPROACH SPAN DESIGN TYPE:			OTH	IER OR NOT APPLICABLE	
INSPECTION DATE:	03/04/2013		G	ENERAL CONDITION:	POOR
EVALUATION DATE:	04/19/2011		S	TRUCTURALLY DEFICIENT:	YES
PPRM PIN NUMBER:					
H TRUCK RATING @ INV.:	20 TONS		S	UFFICIENCY RATING:	62.7

SUGGESTED ROUTINE MAINTENANCE AND COMMENTS
REPAIR CONCRETE BEAM "C & D" SPAN NO.5
PATCH BOTTOM OF DECK IN SPAN NO.3
CLEAN AND SEAL ROADWAY EXPANSION JOINTS.
REPAIR SIDEWALK AT APPROACH NO.1 RT & LT & 2 RT & LT
UNDERPASS SUBSTRUCTURE PROTECTION GUARDRAILS ARE SUBSTANDARD

GENERAL COMMENTS:

03-04-2013 I-240 MAINLINE OF UNDERPASS IS UNDER CONSTRUCTION. SPAN # 1, 2, & 3 LIGHTING COVER PLATE MISSING.



TEAM LEADER SIGNATURE

Bridge Condition Coding Form

Revised 03/05/2013

	STATE OF TENNES				Juli	ig r		County:	79
				24001121]	Route:	SR057
	bridge Number: cludes Item 5A)		7910	24001121				Special Case:	0
Featu	ire Intersected:	I24	0 & 124	0 EXIT RA	MP			County Sequence:	1
Fvo	duation Status:	NO CHAN	CF BU	TSTILLE	VALT	АТЕ		Log Mile:	8.09
								0	
		<u>SE VALUES V</u>			CHA				r
	DESCRIPTIO			ALUE	-			ODING GUIDELINES g Items 58, 59, 60 and 62)	-
90	LAST INSPECT			6/04/2013	4	()			
	EARLIEST DA' NEXT	IE OF	01	/03/2015					
	REGULAR INS	PECTION	/	/ /			OT APPLI		
10	MINIMUM V.C	. OVER	99	FT. 9	9 IN.			T CONDITION	
10	DECK (ROADWAY + S			FT.	IN.	~	CRY GOOD OBLEMS	D CONDITION - NO NOTED.	
520	MINIMUM V.C		99	FT. 9	9 IN.			DITION - SOME MINO	
	(EXCLUDES SI	HOULDERS)		FT	IN.			ORY CONDITION - MI	
36	TRAFFIC SAFE	ETY FEATURES					EMENTS		11
	Br. Rail Trans	s. Appr. Rail	Fermina	I SPEED	LIMIT	5 FA	IR COND	ITION - ALL PRIMARY	7
	1 1	1	1	40)			AL ELEMENTS ARE SO MINOR SECTION LOS	
								, SPALLING OR SCOUL	
41	STRC OPEN/CI	LOSED/POSTED		Α		4 PO	OR CON	DITION - ADVANCED S	ECTION
	A l	K P				LO	SS, DETE	RIORATION, SPALLIN	
58	DECK			4			OUR.		
	-							ONDITION - LOSS OF S ATION, SPALLING OR (
59	SUPERSTRUCT	ГURE		5		HA	VE		
								AFFECTED PRIMARY AL COMPONENTS. LO	
60	SUBSTRUCTU	RE		6		FA	ILURES A	ARE POSSIBLE. FATIG	UE CRACKS
							AY BE PR	R SHEAR CRACKS IN (ESENT.	CONCRETE
61	CHANL/CHAN	L PROTECTION		Ν		-		CONDITION - ADVANC	
								ATION OF PRIMARY S' . FATIGUE CRACKS IN	
62	CULVERT ANI	D RETAIN WALL		Ν		SH	EAR CRA	CKS IN CONCRETE M	AY BE
								R SCOUR MAY HAVE I FURE SUPPORT. UNLE	
71	WATERWAY A	ADEQUACY		Ν		CL	OSELY N	IONITORED IT MAY B	E
								Y TO CLOSE THE BRID VE ACTION IS TAKEN.	
72	APPROACH RI	DWY ALIGNMEN	Т	8			KKECII	EACTION IS TAKEN.	
						-		FAILURE CONDITION	
521	OVERALL CO	NDITION	(POOR				ATION OR SECTION LO	
521	OVERIEL CO			TOOK				NTS OR OBVIOUS VER	
								AL MOVEMENT AFFE AL STABILITY, BRIDO	
	LATITUDE	17 LONGITU				CL	OSED TO	TRAFFIC BUT CORRI	ECTIVE
	N 35° 6.2450'	W 89 ° 52.188	83'			AC	TION MA	AY PUT IT BACK IN LIG	JHI SEKVIC
-								NDITION - OUT OF SEI	RVICE AND
			_	1 1	_	BE	YOND CO	ORRECTIVE ACTION.	

REVIEW DATE



Bridge ID#: 79-SR057-08.09 Date: 03/04/2013 Date: 03/04/2



APPROACH 1 ASPHALT

Bridge ID#: 79-SR057-08.09

Date: 03/04/2013



APPROACH 1 RIGHT SIDEWALK SETTLED

Bridge ID#: 79-SR057-08.09

Date: 03/04/2013



SPAN 5 JOINT

Bridge ID#: 79-SR057-08.09

Date: 03/04/2013



Bridge ID#: 79-SR057-08.09

Date: 03/04/2013



APPROACH 2 RIGHT SIDEWALK SETTLED

Bridge ID#: 79-SR057-08.09

Date: 03/04/2013



SPAN 5 COVER PLATE MISSING ON LIGHT



ABUTMENT 1

Bridge ID#: 79-SR057-08.09

Date: 03/04/2013



LEFT ELEVATION SPAN 2

Bridge ID#: 79-SR057-08.09

Date: 03/04/2013





BENT 2 FRONT

Bridge ID#: 79-SR057-08.09

Date: 03/04/2013



RIGHT ELEVATION SPAN 3



Bridge ID#: 79-SR057-08.09

Date: 03/04/2013





BENT 3 FRONT



RIGHT ELEVAITON SPAN 4



Bridge ID#: 79-SR057-08.09

Date: 03/04/2013



SPAN 5 DIAPHRAGM SPALLING



SPAN 5 BEAM D SPALLING

Bridge ID#: 79-SR057-08.09

Date: 03/04/2013



SPAN 5 BEAM C SPALLING



SPAN 5 BEAM C SPALLING

MAR 042013

BRIDGE INSPECTION REPORT

Form BIR 3.0	Field Report No.: 21	Date: 3/4/13
(Rev. 9-22-98)	Previous Report No.: 20	_ Date: <u>4/14///</u>
DT-0069	Co. Seq <u>01</u> Plans: YES	(X) NO()
Bridge No Bridge Location	No. <u>79 - SR057 - 0809</u>	79 - 10240 - 1573 A
Eleven Digit No.	Co. Route Log Mile	OVER/UNDER PASS
Road Name	Feature Intersected	CITY
Year Constructed 1958	County Shelby Maint.	Dist: <u>45</u> Maint.Resp: <u>02</u>
Year Widened Year Rehabil		·
	Structur	e Name (If Named)
<u>FEATURES</u>	abolt () Danth (in)	INSPECTORS
Wearing Surface Concrete (Timber () As		1. LEWIS
	/idth Open()None()Closed()	2. LOVE
Navigational Control Yes () No (Sridge		3. JONES
Structure Type (Main Span) CONCRETE I.	BEAM	4. LEECH
Structure Type (Appr.Spans)		5. C. YOUNG
No. Main Spans 5 No. Approach	Spans	6
Maximum Span Length 75.5(**.* ft	.)	7
Total Length 294.5 (**.* ft	.)	8
	CLEARANCES_	
<u>WIDTHS</u> (*.* ft.)	Min. Vertical Clearance over De	ck (ftin.)
Deck Out-to-Out 54.5		
Roadway Curb/Curb 40.0	Min. Vertical Under Clearance	GRAMP
Roadway Rail/Rail	Min. Lateral Under Clearance R	
Sidewalk Rt. 6.0 Lt. 6.0	Min. Lateral Under Clearance Lt	<u>9,0'</u> (*.* ft.)
*Approach Roadway <u>40.0</u> *(Does Not Include Shoulders)	FRACTURE CRITICAL: (If Yes, Include BIR 3.9)	
Approach Shoulder Rt.		
Lt	NBIS Bridge Length (<25 ft.)	(ftin.)
UNDERWATER INSPECTION	na an a	
To Be Performed By:	Date	<u></u>
DOT FIELD TEAM () CONTRACT DIVERS ()	NONE REQUIRED (
Change in Structural Condition: Yes () No	(Major Repairs Made	∋: Yes() ΝΟ(♥
<u>COMMENTS:</u> 분	TE: IZ40-MAINLINE OF UT	JOER PASS 1 IS
· · · · · · · · · · · · · · · · · · ·	WOER CONSTRUCTION.	
LATITUDE: N35 ° 6.2450		
LONGITUDE: W89 ° 52.1883	BRIDGE RATING: () ()) (/ ()
G.P.S. Location	GOOD FAIL	R POOR CRITICAL
Supervising Bridge Inspector:	l.	
	1	
VU	-	

Form BIR 3.1	·	0 4 2013
(Rev. 9-22-98) DT-0080	Bridge Location No. 79 - SR057 - 8.09 - Date Co. Route Log Mile	
PERFORMANCE EVA	LUATION	
Time of Day Inspecte	ed 11:30 And Weather Conditions 54° SUNNY	
Vehicles Observed	ALL TYPES	
LIVE LOAD BEHAVI	OR	
Substructure	YES NO Comments	
Horiz./ Vert. De	fl. () ()	
Vibration	() (4)	
Superstructure		
Horiz./ Vert. De	fl. () (Y	<u></u>
Vibration	() (<i>V</i>	
APPROACH	Rating	
Alignment	© F P C	
Stab SIDEWALK	GFOC APPROACH #1:#2 LT : PT- SETTLED (005)	
Joints	GFPC <u>NA</u>	
Pavement	G 🖗 P C	
Embankment	© F P C	
Drains	Ö FPC	
TRAFFIC SAFETY FE	ΔΤΙΒΕς	
	Rating STANDARD/ SUB-STANDARD Comments	
Bridgerailing	G (F) P C (Y) ()	
Transitions	(GFPC () ()	
Guardrail	G (F P C ()	
Guardrail Terminal	GFPC (4 ()	· · ·
SIGNING	YES NO NEEDED Weight Limit Posted	
Paddleboards	$()$ $(\mathcal{F}())$ YES $()$ NO (\mathcal{F})	
Vertical Clearance	(<14'-6") () () () Gross	Tons
NARROW ()	() () () 2 Axle	Tons
ONE LANE BRIDG	E() () () () 3 or more Axles	Tons
Other Signs or Plac	jues: None	
Comments Regard		
Problems with Sign		
· · · · · · · · · · · · · · · · · · ·		
		· · · · · · · · · · · · · · · · · · ·

Form BIR 3.2			MAR 0420
(Rev. 9-22-98)	Bridge Location No.	79 - SR057 - 8.0	09 - Date
DT-0081		Co. Route Log	Mile
DECK	Rating		Comments
Wearing Surface	G(F)P(
Deck - Structural Condition	GF®		DELAMINATED (243)
Curbs Median Sidewalks Parapet Railing Paint Drains Lighting Standards	G F P (G F P (G P (G P (G F P (<u>SPAN # 1, #3</u>	3, 5#5 - COMER PLATE MISSING(
Utilities	GFPC		
Joint Leakage -Expansion Joints	G F Р С G F Ф С		MATERIAL TORN ! MISSING (03
SUPERSTRUCTURE			
Bearing Devices	GFPC	;	
Beams C.T.B	G F 🕑 (SPAN # 5 B	BEAM "L" ; "O" (244)
Girders	GFPC	·	
PCCS	GFPC	<u> </u>	·
BOLTS (PCCS)	GFPC) <u> </u>	
Floor Beams	GFPC)	
Stringers	GFPC	.	
Diaphragms	GOPC	`	
Bracing	GFPC	;	
Trusses - General	GFPC		
Portals	GFPC		
Bracing	GFPC	.	
Paint EQ	F P C)	
Alignment of Members	s GFPC)	
TEXTURE COAT			
Condition Rating	GFPC	Fading	GÔPC
Overall Appearance	G 🖗 P C	그는 같은 것은 것을 알았는 것을 많다.	ting YES () NO ()
Staining Rating	G P C	알려온 승규가 감독하는 것 같아.	
Comments		neeus repaintin(g YES() NO() Scaling Rating G F P C
RECOMMENDATION	ne de la composición de la composición Sec		
	♥• <u> </u>	<u></u>	
			CLEAN DRAINS ()

.

Form BIR 3.3 (Rev. 9-22-98) DT-0082 <u>SUBSTRUCTURE</u>	Bridge Location No	<u>79 - SR057 - 8.09 -</u> Co. Route Log Mile	MAR 0 4 2 PILES TO BE REPLACED
ABUTMENTS	Rating	Comments	PILE(S) ABUTMENT
Breastwall Wings Backwall Plumb Footing Piles Embankment Bearing Slope Paving	G F P C G F P C		
PIERS			PILE(S) PIER
Caps Columns Plumb Footings Piles Bearing Web Earthquake Devices	G F P C G F P C	1A	
CUT V	G F P C G F P C Reed Replacement: EGETATION R DRIFT	NO (YYES () NO () YES (Y HEA NO (YES ()	PILE(S) BENT

Inspection Team's Summary

Bridge Location No.79 -SR057 - 08.09 Inspection Date 03/04/13

Bridge Rating POOR


THIS 5 SPAN CONCRETE I BEAM BRIDGE IS IN POOR CONDITION. THE APPROACH PAVEMENT AND CONCRETE WEARING SURFACE HAVE FINE CRACKS. SPAN 1,3&5 COVER PLATES ARE MISSING FROM LIGHTS. SPAN 3 BOTTOM DECK HAS DELAMINATION AND SPALLING. SPAN 5 CONCRETE I BEAM(C&D) SPALLED TO STEEL AND BROKEN. THE CONCRETE SUBSTRUCTURE HAS FINE CRACKS AND BEGINNING TO SPALL. THE MAIN LANE VERTICAL CLEARANCE IS UNDER CONSTRUCTION. THE MINIMUM VERTICAL ON RAMP IS 16'5". NOTE: APPROACH 1&2 LEFT AND RIGHT SIDEWALK SETTLED. SPAN 5 JOINT MATERIAL TORN AND MISSING. THERE IS POTENTIAL FOR CONCRETE TO FALL IN ROADWAY SPAN 2 BOTTOM HAS DELAMINATION AND BENT 3 HAS BEGINNING TO SPAL THAT COULD FALL IN ROADWAY.


RANDY LOVE

INSPECTOR

CROSS SECTION: YES () NO (X) PONTIS: YES (X) NO ()

MAR 042013






	ELEMENT	RATING	COMMENT
X	TOP DECK	⊕ FPC	
	PARAPET	G €P C	Fine Cracks
	DRAINS	GFPC	N/H
	JOINTS	GÊ₽ C	Light scattered debris
	hails	G F P C	
	Sidewalk	GEPC	
	Light	GFOC	Cover NISSING
	- - -		

MAR 0 4 2013

79-57-8.09 Bridge No. RT.

SKEW

Span No. ____





MAR 0 3-201 19 57 8,09 Bridge No. Co. Log Mile Route R/L Skew SPAN. NO. cont ELEMENT RATING COMMENT G P C TOP DECK Fine Cracks PARAPET GFP C NA GFPC DRAINS NA GFPC JOINTS Rails OFPC Sidewalt GOPC Fine coacles

MAR 042013


Bridge No. 79-57-8.09 SKEW R\L

Span No. ____







MAR 0 4 2013




MAR 0 4 2013





MAR 042013 79 57 8,09 Bridge No. Co. Log Mile R/L Skew SPAN. NO. 5 Route \overline{n} 70'WH Dspalling in hint Conc on hin header Shxz"Lkz" ELEMENT RATING COMMENT FINECracks GFPC TOP DECK finecracus GFP C PARAPET partially filled with debris GFP C DRAINS material torn & missing, see () G FPC JOINTS GFPC hails GBPC Enclarks Sidewalk Light cover plate missing


79-57-8,09 SKEW R\L_____ Span No. 5 Bridge No.



とう MAR @420移


BR. NO. <u>79</u> <u>57</u> <u>8</u>,09

ABUTAR 0 4 2013




	ELEMENT	RATING	· · · · · · · · · · · · · · · · · · ·	CONTENT
¥.	BEARINGS	GFPC		
· · ·	CAP	GEPC	FINE CRACKS	
	PILING	GFPC	NIV	
	WINGS	GPC	FINE CRACK	
•	VEG.	GFDC	HEAVY GROWTH+	
	EMBANKMENT	©F P C		
	RIP - RAP	GFPC	NA	
	SLOPE PAVING	GPC	FINE CRACKS	
	<i>Ε. φ</i> .	GFPC		
	.			

BR. NO. <u>79 57 8,09</u> BENT NO. <u>MAR 0</u> 4 2013



BR. NO. <u>29</u> <u>57</u> <u>8</u> 09 BENT NO. <u>MAR 0 4 2013</u>



BR. NO. <u>79 57 8.09</u>


BENT NO. 3 MAR 0 4 2013

B C FRONT VIEW Α. с. Д. 3D -D Ż REAR VIEW C В A **s** -ELEMENT RATTNG COMMENT D Begin + 25 parl JuxiL GFPC BEARINGS COLUMNS A B G F P C G F P C G F P C C E CO, Fine Gracks GFP C CAP E.Q. OFPC fine cracks Parapet GEPC

and the second second

BR. NO. <u>79 57</u> 8.09

BENT NO. MAR 0 1 2013



BR. NO. <u>79</u> <u>57</u> <u>B.09</u> ABUT. NO. 2 MAR 0 4 2013 LOOKING <u>BACK</u>

	ELEMENT	RATING	COMMENT
**	BEARINGS	GFPC	
	CAP	GFPC	fine exactly W/W
·	PILING	GFPC	M/N
	WINGS	GFPC	u de la construcción de la constru La construcción de la construcción d
	VEG.	GFPC	
•	EMBANKMENT	GFPC	
•	RIP-RAP-	GFPC	
	SLOPE PAVIN		Enecrairs
	E.Q. (OFPC	
	• • •		



Underpass Condition Coding Form

Revised 03/05/2013

				Juii	5			County:	79
MENT OF TRANSF	ORIAIION							Route:	I0240
Bridge Number		791024001124					Special Case:	0	
udes Item 5A)		1710						County Sequence:	1
re Intersected:		SR 57	WBL / I24()				Log Mile:	15.73
ONLY THOS	E VALUES	WHIC	CH HAVE	CHA	NGE	D			
DESCRIPTION	1			VALU	E		UN	NDERPASS SAFETY FE	ATURES
EARLIEST DAT	E OF]	515	COMBINATION OF	METAL
DECK									'ype 1
			16					BARRIER OR RAIL	
TOTAL HORIZONTAL UNDERCLEARA	ANCE		62					(C) ADEQUACY OF TRANSITIONS	0
MINIMUM VER	TICAL UNDER	CLEAR						(D) ADEQUACY OF TERMINALS	0
	ERAL			FT		IN.	554	LISTED ON HEIGHT POSTING	E IN.
UNDERCLEARA SIDE				FT		IN.		FT.	IN.
				FT		IN.	16		LONGITUDE 89 ° 52.1883'
OVERALL CON	DITION		POOR					HEIGHT POSTED AT BOTH APPROACHES?	YES [] NO [] N/A []
	MENT OF TRANSP idge Number: [udes Item 5A) re Intersected: [ONLY THOS DESCRIPTION LAST INSPECTI EARLIEST DAT NEXT REGULAR INSP MINIMUM V.C. DECK (ROADWAY + SI MINIMUM V.C. (EXCLUDES SHO TOTAL HORIZONTAL UNDERCLEARA MINIMUM LATI UNDERCLEARA SIDE	udes Item 5A) re Intersected: ONLY THOSE VALUES DESCRIPTION LAST INSPECTION DATE EARLIEST DATE OF NEXT REGULAR INSPECTION MINIMUM V.C. OVER DECK (ROADWAY + SHOULDERS) MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS) TOTAL HORIZONTAL UNDERCLEARANCE MINIMUM VERTICAL UNDER (EXCLUDES SHOULDERS) Circle One: MINIMUM LATERAL UNDERCLEARANCE ON RIGH SIDE Circle One: MINIMUM LATERAL UNDERCLEARANCE ON LEFT	MENT OF TRANSPORTATION idge Number: 7910 idges Item 5A) re Intersected: SR 57 ONLY THOSE VALUES WHICO DESCRIPTION LAST INSPECTION DATE EARLIEST DATE OF NEXT REGULAR INSPECTION MINIMUM V.C. OVER DECK (ROADWAY + SHOULDERS) MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS) TOTAL HORIZONTAL UNDERCLEARANCE MINIMUM VERTICAL UNDERCLEAR (EXCLUDES SHOULDERS) Circle One: H R MINIMUM LATERAL UNDERCLEARANCE ON RIGHT SIDE Circle One: H R	MENT OF TRANSPORTATION ridge Number: 79I02400112A udes Item 5A) SR 57 WBL / I240 re Intersected: SR 57 WBL / I240 ONL Y THOSE VALUES WHICH HAVE DESCRIPTION LAST INSPECTION DATE 0 EARLIEST DATE OF 0 NEXT 0 REGULAR INSPECTION 16 MINIMUM V.C. OVER 16 DECK 16 (ROADWAY + SHOULDERS) 16 MINIMUM V.C. OVER DECK 16 (EXCLUDES SHOULDERS) 62 UNDERCLEARANCE 16 MINIMUM VERTICAL UNDERCLEARANCE 62 MINIMUM VERTICAL UNDERCLEARANCE 16 MINIMUM VERTICAL UNDERCLEARANCE 16 MINIMUM LATERAL Circle One: H MINIMUM LATERAL UNDERCLEARANCE ON LEFT	idge Number: 79I02400112A udes Item 5A) SR 57 WBL / I240 ONLY THOSE VALUES WHICH HAVE CHAI DESCRIPTION DESCRIPTION VALU LAST INSPECTION DATE 03/04/20 EARLIEST DATE OF 01/03/20 NEXT 01/03/20 REGULAR INSPECTION / MINIMUM V.C. OVER 16 DECK FT. (ROADWAY + SHOULDERS)	ment of transportation ridge Number: 79I02400112A udes Item 5A) re Intersected: SR 57 WBL / I240 ONLY THOSE VALUES WHICH HAVE CHANGE. DESCRIPTION VALUE LAST INSPECTION DATE 03/04/2013 01/03/2015 REGULAR INSPECTION / / MINIMUM V.C. OVER 16 FT. 3 DECK 16 FT. 7 (ROADWAY + SHOULDERS)	ment of transportation 79102400112A ridge Number: 79102400112A udes Item 5A) SR 57 WBL / I240 ONLY THOSE VALUES WHICH HAVE CHANGED DESCRIPTION VALUE LAST INSPECTION DATE 03/04/2013 EARLIEST DATE OF 01/03/2015 NEXT 01/03/2015 REGULAR INSPECTION /_/ MINIMUM V.C. OVER 16 DECK FT. (ROADWAY + SHOULDERS) FT. MINIMUM V.C. OVER DECK 16 (EXCLUDES SHOULDERS) FT. MINIMUM V.C. OVER DECK 16 FT. IN. MINIMUM V.C. OVER DECK 16 (EXCLUDES SHOULDERS) FT. MINIMUM V.C. OVER DECK 16 FT. IN. MINIMUM VERTICAL UNDERCLEARANCE FT. (EXCLUDES SHOULDERS) Circle One: H R <	MENT OF TRANSPORTATION ridge Number: 79I02400112A udes Item 5A) SR 57 WBL / 1240 ONLY THOSE VALUES WHICH HAVE CHANGED DESCRIPTION VALUE LAST INSPECTION DATE 03/04/2013 EARLIEST DATE OF 01/03/2015 NEXT REGULAR INSPECTION MINIMUM V.C. OVER 16 PECK 16 (ROADWAY + SHOULDERS) FT. MINIMUM V.C. OVER DECK 16 (ROADWAY + SHOULDERS) FT. MINIMUM V.C. OVER DECK 16 (ROADWAY + SHOULDERS) FT. MINIMUM V.C. OVER DECK 16 (ROADWAY + SHOULDERS) FT. MINIMUM V.C. OVER DECK 16 (ROADWAY = SHOULDERS) FT. MINIMUM V.C. OVER DECK 16 (EXCLUDES SHOULDERS) FT. (EXCLUDES SHOULDERS) FT. (EXCLUDES SHOULDERS) FT. (INNIMUM LATERAL UNDERCLEARANCE ON RIGHT SIDE Circle One: H MINIMUM LATERAL FT. IN. MINIMUM LATERAL FT. IN.	Route: Route: Route: Route: idge Number: ? 9102400112A Special Case: County Sequence: county Seque

REVIEW DATE

BRIDGE MAINTENANCE RECOMMENDA COUNTY: SHELBY LOCATION: 79-I0240-15.73- CO. SEQ.: 1 SPEC. CASE: (MILEPOST: 15.43		Tenr	DOT Tennessee Department of Transportation	
CROSSING: SR 57 WBL / 1240 FED. BRIDGE NO.: 79102400112 MAINT. DIST.: 79		REPAIR LIST N DATE ADDED: REVISED:	0.: N 03/04/2013	
FACILITY CARRIED: 02- HIGHWAY SYSTEM: 02- BRIDGE WIDTH (CURB TO CURB): 02- BRIDGE WIDTH (OUT TO OUT): 000000000000000000000000000000000000	FAP 57 INTERSTATE URBAN N/A FT IN N/A FT IN 166 FT 8 IN STRINGER	NUMBER OF MAIN SPANS: NUMBER OF APPROACH SP BRIDGE LENGTH (FT): MAXIMUM SPAN LENGTH (SKEW ANGLE (DEGREES): PRESTRESSED CONCRETE /MULTI-BEAM OR GIRDER	ANS:	
INSPECTION DATE: 03/04/20 EVALUATION DATE: 04/19/20 PPRM PIN NUMBER: H TRUCK RATING @ INV.: TO	11 S	ENERAL CONDITION: TRUCTURALLY DEFICIENT: UFFICIENCY RATING:	POOR	

SUGGESTED ROUTINE MAINTENANCE AND COMMENTS

SEE BRIDGE NO. 79-SR057-08.09 (79I024001121) FOR RECOMMENDATIONS.

GENERAL COMMENTS:



Underpass Condition Coding Form

Revised 03/05/2013

TATE OF TENNES				Juli	-8 -			County:	79
MENT OF TRANSF	ORIAIION							Route:	10240
Bridge Number:		79102400112B						Special Case:	0
udes Item 5A)								County Sequence:	1
re Intersected:	SI	R-57 / I-24	40 EX. RA	MP				Log Mile:	15.72
ONLY THOS	E VALUES	WHIC	H HAVE	CHA	NGE	D			
DESCRIPTION	1			VALU	E		UN	NDERPASS SAFETY FEA	ATURES
EARLIEST DAT	E OF]]	515		
DECK			16						-
								(B) ADEQUACY OF BARRIER OR RAIL	0
TOTAL HORIZONTAL UNDERCLEARA	ANCE		42					(C) ADEQUACY OF TRANSITIONS	0
MINIMUM VER	TICAL UNDER	CLEARA	NCE					(D) ADEQUACY OF TERMINALS	0
MINIMUMIAT		H R		FT		IN.	554	LISTED ON HEIGHT	E
	ANCE ON RIGH			FT		IN.		FT. FT.	IN. IN.
		,		FT		IN.	16		LONGITUDI 89° 52.1883'
OVERALL CON	DITION		POOR					HEIGHT POSTED AT BOTH APPROACHES?	YES [] NO [] N/A []
	MENT OF TRANSP idge Number: [udes Item 5A) re Intersected: [ONLY THOS DESCRIPTION LAST INSPECTI EARLIEST DAT NEXT REGULAR INSP MINIMUM V.C. DECK (ROADWAY + SI MINIMUM V.C. (EXCLUDES SH TOTAL HORIZONTAL UNDERCLEARA MINIMUM LAT UNDERCLEARA SIDE	MENT OF TRANSPORTATION idge Number: dudes Item 5A) re Intersected: SI ONLY THOSE VALUES DESCRIPTION LAST INSPECTION DATE EARLIEST DATE OF NEXT REGULAR INSPECTION MINIMUM V.C. OVER DECK (ROADWAY + SHOULDERS) MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS) TOTAL HORIZONTAL UNDERCLEARANCE MINIMUM VERTICAL UNDER (EXCLUDES SHOULDERS) Circle One: MINIMUM LATERAL UNDERCLEARANCE ON RIGH SIDE Circle One:	MENT OF TRANSPORTATION ridge Number: 79102 udes Item 5A) re Intersected: SR-57 / I-24 ONLY THOSE VALUES WHICH DESCRIPTION LAST INSPECTION DATE EARLIEST DATE OF NEXT REGULAR INSPECTION MINIMUM V.C. OVER DECK (ROADWAY + SHOULDERS) MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS) TOTAL HORIZONTAL UNDERCLEARANCE MINIMUM VERTICAL UNDERCLEARAT (EXCLUDES SHOULDERS) Circle One: H R MINIMUM LATERAL UNDERCLEARANCE ON RIGHT SIDE Circle One H R	MENT OF TRANSPORTATION ridge Number: 79I02400112B udes Item 5A)	MENT OF TRANSPORTATION idge Number: 79I02400112B udes Item 5A) SR-57 / I-240 EX. RAMP ONLY THOSE VALUES WHICH HAVE CHA DESCRIPTION VALU LAST INSPECTION DATE 03/04/2 EARLIEST DATE OF 01/03/2 REGULAR INSPECTION / MINIMUM V.C. OVER 16 DECK FT. (ROADWAY + SHOULDERS)	ment of transportation ridge Number: 79I02400112B udes Item 5A) re Intersected: SR-57 / I-240 EX. RAMP ONLY THOSE VALUES WHICH HAVE CHANGE DESCRIPTION VALUE LAST INSPECTION DATE 03/04/2013 01/03/2015 EARLIEST DATE OF 03/04/2013 01/03/2015 REGULAR INSPECTION DATE 03/04/2013 01/03/2015 REGULAR INSPECTION / / MINIMUM V.C. OVER 16 FT. 5 DECK 16 FT. 11 (ROADWAY + SHOULDERS)	ment of transportation 79102400112B ridge Number: 79102400112B udes Item 5A) SR-57 / I-240 EX. RAMP ONLY THOSE VALUES WHICH HAVE CHANGED DESCRIPTION VALUE LAST INSPECTION DATE 03/04/2013 EARLIEST DATE OF 01/03/2015 NEXT 01/03/2015 REGULAR INSPECTION /_/ MINIMUM V.C. OVER 16 DECK I6 (ROADWAY + SHOULDERS) FT. MINIMUM V.C. OVER DECK 16 (EXCLUDES SHOULDERS) FT. MINIMUM V.C. OVER DECK 16 FT. IN. MINIMUM V.C. OVER DECK 16 (EXCLUDES SHOULDERS) FT. MINIMUM V.C. OVER DECK 16 FT. IN. MINIMUM V.C. OVER DECK 16 (EXCLUDES SHOULDERS) FT. MINIMUM VERTICAL UNDERCLEARANCE IN. MINIMUM LATERAL VIDERCLEARANCE ON RIGHT SIDE Circle One: H R FT. MINIMUM LATERAL FT. IN. MINIMUM LATERAL FT. IN.	MENT OF TRANSPORTATION ridge Number: 79I02400112B indes Item 5A) SR-57 / I-240 EX. RAMP ONLY THOSE VALUES WHICH HAVE CHANGED DESCRIPTION DESCRIPTION VALUE UN LAST INSPECTION DATE 03/04/2013 515 EARLIEST DATE OF 01/03/2015 515 REGULAR INSPECTION / / MINIMUM V.C. OVER 16 FT. 5 MINIMUM V.C. OVER 16 FT. IN. MINIMUM V.C. OVER DECK 16 FT. IN.	MENT OF TRANSPORTATION Route: Route: Route: idge Number: 79102400112B udes Item 5A) County Sequence: re Intersected: SR-57 / I-240 EX. RAMP Log Mile: ONLY THOSE VALUES WHICH HAVE CHANGED DESCRIPTION VALUE UNDERPASS SAFETY FEA DESCRIPTION VALUE UNDERPASS SAFETY FEA LAST INSPECTION DATE 03/04/2013 515 (A) TYPE UNDERPASS IS CONCRETE BARR REGULAR INSPECTION / Interpretain the concrete Barrier T: MINIMUM V.C. OVER 16 FT. 5 IN. Revised Barrier T: (ROADWAY + SHOULDERS) FT. IN. (B) ADEQUACY OF BARRIER OR RAIL MINIMUM V.C. OVER DECK 16 FT. 11 IN. (C) ADEQUACY OF TRANSITIONS HORIZONTAL 42 FT. 3 IN. (C) ADEQUACY OF TERMINALS (EXCLUDES SHOULDERS) FT. IN. (D) ADEQUACY OF TERMINALS (EXCLUDES SHOULDERS) FT. IN. (D) ADEQUACY OF TERMINALS (EXCLUDES SHOULDERS) Circle One: H R FT. IN. (EXCLUDES SHOULDERS) FT. IN. STEE ON HEIGHT POSTING (ININIMUM LATERAL

REVIEW DATE

TEAM LEADER SIGNATURE

BRIDGE MAINTENANCE COUNTY: SHELBY LOCATION: 79-10240-1 CO. SEQ.: 1 S MILEPOST: 15.42		IONS		_	Tennessee Dep of Transpor	partment
CROSSING: SR-57 / I-	240 EX. RAMP			REPAIR LIST	NO.:	N
FED. BRIDGE NO.: 791	02400112			DATE ADDED:		
MAINT. DIST.: 79				REVISED:	03/	04/2013
FACILITY CARRIED:		F	'AU 57	NUMBER OF MAIN SPAN	IS:	
HIGHWAY SYSTEM:	02-IN'	TERSTATE		NUMBER OF APPROACH		
BRIDGE WIDTH (CURB TO	CURB):	N/AFT	IN	BRIDGE LENGTH (FT):		285
BRIDGE WIDTH (OUT TO (CUT):	N/A FT	IN	MAXIMUM SPAN LENGTH	I (FT):	68
APPROACH ROADWAY (W/S	HOULDERS):	39 FT	4 IN	SKEW ANGLE (DEGREES	5):	N/A
MAINTAINED BY:						
MAIN SPAN MATERIAL:				PRESTRESSED CONCRETE	- 	
MAIN SPAN DESIGN TYPE	:	STI	RINGER/	MULTI-BEAM OR GIRDER	-	
APPROACH SPAN MATERIA	L:					
APPROACH SPAN DESIGN	TYPE:					
INSPECTION DATE:	03/04/2013		G	ENERAL CONDITION:		POOR
EVALUATION DATE:	04/19/2011		S	TRUCTURALLY DEFICIEN	г:	
PPRM PIN NUMBER:						
H TRUCK RATING @ INV.	: TONS		S	UFFICIENCY RATING:		

SUGGESTED ROUTINE MAINTENANCE AND COMMENTS

SEE BRIDGE NO. 79-SR057-08.09 (79I024001121) FOR RECOMMENDATIONS.

GENERAL COMMENTS:

Page 1 of 2 INSPECTION R	EPORT FOR UNDERPASS ROL	JTE Page No.
Form BIR 3.0A	Field Report No.	Date MAR 042013
(Rev. 9-22-98)	Previous Report No.	Date
DT-1443		
Bridge No. <u>79I02400112</u>	Underpass Location No. 79 - Co.	- SR057 - 0809 - Route Log Mile
Eleven Digit No.	over/	- I0240 - 1559
Or Railroad/Walkway	Co. Route Log Mile Co.	Route Log Mile
County Shelby	Structure Name (If Named)	
Year Constructed		
Year Widened	Year Rehabilitated	<u></u>
GEOMETRIC FEATURES UNDER E	RIDGE (*.* ft. unless otherwise noted)	Ramp D
Divided Highway LEFT RDW		nurry (1)
	NCRETE () ASPHALT () GRAVEL ()
Width of Approach Traveled Roadwa		
Width of Median if Divided Highway		
Approach Shoulder Width	15 ft. Right P	ft. Left
*Horizontal Clearance Under Bridge	<u>43</u> ft. <u>3"</u>	in.
*Distance Between Pier Protection Guardrail and Substructure	3,3 ft. Right 18'	ft. Left
*Width of Sidewalk Under Bridge	ft. Right	ft. Left
*Minimum Vertical Clearance:	16 ft. <u>5</u> in.	
*Show on Sketch		
TRAFFIC SAFETY FEATURES FOR	UNDERPASS ROUTE	
TRAFFIC SALETT LATORECT OF	STANDARD SUB-STA	NDARD NON EXIST
Pier Protection Railing or Parapo	GFPC () ()	(1)
Approach Guardrail Transitions	() () () () () () () ()	()
Approach Guardrail	$ (\mathbf{G}) \mathbf{F} \mathbf{P} \mathbf{C} (\mathbf{J}) (\mathbf{H}) $	• · · · · · · · · · · · · · · · · · · ·
Approach Guardrail Terminal		
SIGNING FOR UNDERPASS ROUT		
Paddleboards	ES () NO (YNEEDED ()	NSPECTORS
Vertical Clearance (<14'-6") YI	ES () NO (related () 1.	Lewis
One Lane Passage	ES () NO (YNEEDED () 3.	
Other Underpass Signs Needed	4	
NONE		
	6.	
	[0	


Page 1 of 2 INSPECTION REPORT FOR UNDERPASS ROUTE Page No	<u>042013</u>
Form BIR 3.0A Field Report No Date	
(Rev. 9-22-98) Previous Report No Date	. <u></u>
DT-1443	
Bridge No. 79I02400112 Underpass Location No. 79 - SR057 - 0809	· _
Eleven Digit No. Co. Route Log M	ile
or under <u>79 - 10240 - 1559</u>	
Railroad/Walkway Co. Route Log Mile Co. Route Log M	lle
County Shelby Structure Name (If Named)	
Year Constructed	
Year Widened Year Rehabilitated	
GEOMETRIC FEATURES UNDER BRIDGE (*.* ft. unless otherwise noted)	
Divided Highway LEFT RDWY () RIGHT RDWY () N.A. ()	
Type of Wearing Surface CONCRETE () ASPHALT (X) GRAVEL ()	
Width of Approach Traveled Roadway <u>36</u> ft. (Does Not Include Shoulders)	
Width of Median if Divided Highway	
Approach Shoulder Width 14 ft. Right 12 ft. Left	
*Horizontal Clearance Under Bridge <u>le7</u> ft. <u>O</u> IN.	
*Distance Between Pier Protection Guardrail and Substructure	
*Width of Sidewalk Under Bridgeft. Rightft. Left	
*Minimum Vertical Clearance: ftin.	
*Show on Sketch NOTE: I240 MAINLINE IS UNDER CONSTRUCTION	
TRAFFIC SAFETY FEATURES FOR UNDERPASS ROUTE	
STANDARD SUB-STANDARD NON EX	<u>ST</u>
Pier Protection Railing or Parapet G F P C () () ()	
Approach Guardrail Transitions G F P C () ()	
Approach Guardrail Terminal	
SIGNING FOR UNDERPASS ROUTE	
Paddleboards YES () NO () NEEDED () INSPECTORS	
Vertical Clearance (<14'-6'') YES() NO() NEEDED() 1. العناد العامي العامي العامي العامي العامي العامي العامي ا	
One Lane Passage YES () NO () NEEDED () 2.	
Other Underpass Signs Needed	
4	
5	
6	

Page 1 of 2 INSPECTION REPORT FOR UNDERPASS ROUTE Page No. 0.4 2013
Form BIR 3.0A Field Report No Date
(Rev. 9-22-98) Previous Report No Date
DT-1443
Bridge No. 79I02400112 Underpass Location No. 79 - SR057 - 0809 -
Eleven Digit No. Co. Route Log Mile
or or under 79 - 10240 - 1559
Railroad/Walkway Co. Route Log Mile Co. Route Log Mile
County Shelby Structure Name (If Named)
Year Constructed
Year Widened Year Rehabilitated
GEOMETRIC FEATURES UNDER BRIDGE (*.* ft. unless otherwise noted)
Divided Highway LEFT RDWY () RIGHT RDWY (X N.A. ()
Type of Wearing Surface CONCRETE () ASPHALT (X) GRAVEL ()
Width of Approach Traveled Roadway $3L$ ft. (Does Not Include Shoulders)
*Distance Between Pier Protection Guardrail and Substructure <u>5</u> ft. Right <u>5</u> ft. Left
*Width of Sidewalk Under Bridgeft. Rightft. Left
*Minimum Vertical Clearance:ftin.
*Show on Sketch NOTE: IZED MAINLINE IS UNDER CONSTRUCTION
TRAFFIC SAFETY FEATURES FOR UNDERPASS ROUTE
STANDARD SUB-STANDARD NON EXIST
Pier Protection Railing or Parapet G F P C () () ()
Approach Guardrail Transitions G F P C () () ()
Approach Guardrail G F P C () () ()
Approach Guardrail Terminal G F P C () () ()
SIGNING FOR UNDERPASS ROUTE
Paddleboards YES () NO () NEEDED () INSPECTORS
Vertical Clearance (<14'-6") YES() NO() NEEDED() 1 、) - い
Narrow Passage YES () NO () NEEDED ()
One Lane PassageYES () NO () NEEDED () 2
Other Underpass Signs Needed
4
5
6

Page 2 of 2 Form BIR 3.0A (Continued)	<u>79 - 57</u> Co. Rou		<u>ሥ</u> ጸ፬ የእ <u>፡ 20</u> 13 Date
(Rev. 9-22-98)		an a	
DT-1443	la de la companya de	Jnderpass Location No. 79	
Other Circo or Discussion		CO.	Route Log Mile
Other Signs or Plaques:	NONE		· · · · · · · · · · · · · · · · · · ·
Comments Regarding any Problems with Signing:	NONE		
r tobierns with organity.	NONC		
	2 1		
BRIDGE FEATURES (*.* f	(.)		
Bridge Skew <u>90</u> °			_
Structure Type (Main Span)		No. Main Spans	5
Structure Type (Appr.Spans	s)	No. Appr. Spans	
Maximum Span Length	<u>75,5'</u> (ft.)	Total Length 294.5	(ft.)
Width of Bridge Out-to-Out	<u> </u>	Right Angle to Centerline of	Bridge)
Width of Bridge Along Skew	v (ft.)	(If Unable to Measure at Rig	•
Number of Lanes/Tracks or	n Bridge <u>4</u>	Angle to Centerline of Bridg	e)
BRIDGE CONDITION:	GFDC		
			·
Does Potential Exist for Ele	ments from Bridge Fa	alling on Roadway Beneath	YES (
Does Potential Exist Becau	se of Deteriorated Co	ndition or Failure of Major Me	ember YES()NO(
Comment on any Condition	s of Bridge that would	d Effect Roadway Beneath:	
SPAN # 2 BOTTOM ON	F DELK HAS	DELAMINATED SELTIONS	, ANS
BENT #3 CAP HA	S SECTIONS BE	TUNNING TO SPALL .	·
Note: If Underpass Route i	s Divided Highway, U	lse Two of These Forms, One	e for Each Roadway.

MINIMUM PICTURES REQUIRED

- 1. Elevation View of Bridge on Both Sides Showing Underpass
- 2. View Showing Both Approaches to Bridge
- 3. View Showing Safety Features
- 4. View Showing Any Problems



MAR 0 4 2013

79102400112	79 SR057	0809		SKEW:	90
BRIDGE NO.:	CO. ROUTE	L.M.	L/R		
• • •	Dire	ction of R	loute		
	anai tana atan ing ang ang ang ang ang ang ang ang ang a			>	
	•				
	F =	= FIXED			
			TION		

F = FIXEDE = EXPANSIONS = SIMPLEC = CONTINUOUS

