

HAYWOOD COUNTY

38-SR001-0289


Federal ID: 38SR0010003

Road Name: HWY 79

Crossing: BRANCH

OV/UND PASS:

Road Name 2:



BRIDGE MAINTENANCE RECOMMENDATIONS

COUNTY: HAYWOOD

LOCATION: 38-SR001-02.89-

CO. SEQ.: 1 SPEC. CASE: 0

Tennessee Department
of Transportation

CROSSING: BRANCH

FED. BRIDGE NO.: 38SR0010003

MAINT. DIST.: 38

REPAIR LIST NO.: 2

DATE ADDED: 02/04/1999

REVISED: 09/09/2019

FACILITY CARRIED:	FAP 1	NUMBER OF MAIN SPANS:	1
HIGHWAY SYSTEM:	05-STP RURAL, STATE	NUMBER OF APPROACH SPANS:	0
BRIDGE WIDTH (CURB TO CURB):	28 FT 2 IN	BRIDGE LENGTH (FT):	46
BRIDGE WIDTH (OUT TO OUT):	34 FT 5 IN	MAXIMUM SPAN LENGTH (FT):	41
APPROACH ROADWAY (W/SHOULDERS):	29 FT 10 IN	SKEW ANGLE (DEGREES):	45
MAINTAINED BY: STATE HIGHWAY AGENCY			
MAIN SPAN MATERIAL: CONCRETE			
MAIN SPAN DESIGN TYPE: TEE BEAM			
APPROACH SPAN MATERIAL: OTHER OR NOT APPLICABLE			
APPROACH SPAN DESIGN TYPE: OTHER OR NOT APPLICABLE			
INSPECTION DATE:	09/09/2019	GENERAL CONDITION:	POOR
EVALUATION DATE:	11/07/2017	STRUCTURALLY DEFICIENT:	YES
PPRM PIN NUMBER:	124503.00		
H TRUCK RATING @ INV.:	16 TONS	SUFFICIENCY RATING:	33.9

No.	RECOMMENDATIONS	REPAIR DATE	REPAIRED BY
1.	REPAIR STEEL BEAM "B & H" IN SPAN NO.1		

SUGGESTED ROUTINE MAINTENANCE AND COMMENTS

CLEAN AND PAINT ALL STRUCTURAL STEEL

CLEAR DRAINS

CLEAN AND SEAL ROADWAY EXPANSION JOINTS.

CUT AND REMOVE VEGETATION FROM CHANNEL

APPROACH GUARDRAILS ARE SUBSTANDARD

BRIDGERAILS ARE SUBSTANDARD

GENERAL COMMENTS:

BRIDGE IS ON THE IMPROVE ACT. EARLIEST LETTING DATE IS CY 2021.



STATE OF TENNESSEE
DEPARTMENT OF TRANSPORTATION

Bridge Condition Coding Form

Revised 09/10/2019

Bridge Number: 38SR00100031
(Includes Item 5A)
Feature Intersected: BRANCH
Evaluation Status: OTHER ITEM(S) HAVE BEEN CHANGED

County: 38
Route: SR001
Special Case: 0
County Sequence: 1
Log Mile: 2.89

CODE ONLY THOSE VALUES WHICH HAVE CHANGED

ITEM #	DESCRIPTION	VALUE	CONDITION CODING GUIDELINES
90	LAST INSPECTION DATE	<u>09/09/2019</u>	(Values for Coding Items 58, 59, 60 and 62)
	EARLIEST DATE OF NEXT REGULAR INSPECTION	<u>07/10/2021</u>	
10	MINIMUM V.C. OVER DECK (ROADWAY + SHOULDERS)	<u>99</u> FT. <u>99</u> IN.	N NOT APPLICABLE
520	MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS)	<u>99</u> FT. <u>99</u> IN.	9 EXCELLENT CONDITION
36	TRAFFIC SAFETY FEATURES		8 VERY GOOD CONDITION - NO PROBLEMS NOTED.
	Br. Rail Trans. Appr. Rail Terminal SPEED LIMIT	<u>0</u> <u>1</u> <u>0</u> <u>1</u> <u>55</u>	7 GOOD CONDITION - SOME MINOR PROBLEMS.
41	STRC OPEN/CLOSED/POSTED	<u>P</u>	6 SATISFACTORY CONDITION - MINOR DETERIORATION OF STRUCTURAL ELEMENTS.
	A K P	<u></u>	5 FAIR CONDITION - ALL PRIMARY STRUCTURAL ELEMENTS ARE SOUND BUT MAY HAVE MINOR SECTION LOSS, CRACKING, SPALLING OR SCOUR.
58	DECK	<u>5</u>	4 POOR CONDITION - ADVANCED SECTION LOSS, DETERIORATION, SPALLING OR SCOUR.
59	SUPERSTRUCTURE	<u>4</u>	3 SERIOUS CONDITION - LOSS OF SECTION, DETERIORATION, SPALLING OR SCOUR HAVE SERIOUSLY AFFECTED PRIMARY STRUCTURAL COMPONENTS. LOCAL FAILURES ARE POSSIBLE. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT.
60	SUBSTRUCTURE	<u>5</u>	2 CRITICAL CONDITION - ADVANCED DETERIORATION OF PRIMARY STRUCTURAL ELEMENTS. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT OR SCOUR MAY HAVE REMOVED SUBSTRUCTURE SUPPORT. UNLESS CLOSELY MONITORED IT MAY BE NECESSARY TO CLOSE THE BRIDGE UNTIL CORRECTIVE ACTION IS TAKEN.
61	CHANL/CHANL PROTECTION	<u>6</u>	1 "IMMINENT" FAILURE CONDITION - MAJOR DETERIORATION OR SECTION LOSS PRESENT IN CRITICAL STRUCTURAL COMPONENTS OR OBVIOUS VERTICAL OR HORIZONTAL MOVEMENT AFFECTING STRUCTURAL STABILITY. BRIDGE IS CLOSED TO TRAFFIC BUT CORRECTIVE ACTION MAY PUT IT BACK IN LIGHT SERVICE.
62	CULVERT AND RETAIN WALL	<u>N</u>	0 FAILED CONDITION - OUT OF SERVICE AND BEYOND CORRECTIVE ACTION.
71	WATERWAY ADEQUACY	<u>8</u>	
72	APPROACH RDWY ALIGNMENT	<u>8</u>	
521	OVERALL CONDITION	<u>POOR</u>	
16	LATITUDE	<u>N 35° 27.3083'</u>	
17	LONGITUDE	<u>W 89° 25.6033'</u>	
TEAM LEADER SIGNATURE		REVIEW DATE	

Bridge Loc. No: 38-SR001-02.89 Date: 9-9-19



BRIDGE NUMBER



APPROACH # 1 WEIGHT LIMIT SIGN 40T

Bridge Loc. No: 38-SR001-02.89 Date: 9-9-19



LOOKING AHEAD ON ROUTE



VIEW ACROSS TOP OF DECK

Bridge Loc. No: 38-SR001-02.89 Date: 9-9-19



LOOKING BACK ON ROUTE



APPROACH # 2 WEIGHT LIMIT SIGN 40T

Bridge Loc. No: 38-SR001-02.89 Date: 9-9-19



SPAN # 1 GIRDER "C" HEAVY CRACKING



STEEL I BEAM "B" HEAVY CORROSION & SECTION LOSS

Bridge Loc. No: 38-SR001-02.89 Date: 9-9-19



STEEL I BEAM "H" HEAVY CORROSION & SECTION LOSS



STEEL I BEAM "H" HEAVY CORROSION & SECTION LOSS

Bridge Loc. No: 38-SR001-02.89 Date: 9-9-19



STEEL I BEAM "B" HEAVY CORROSION & SECTION LOSS



ABUTMENT # 2

Bridge Loc. No: 38-SR001-02.89 Date: 9-9-19



SPAN # 1 STEEL I BEAM "H" HEAVY CORROSION & SECTION LOSS



SPAN # 1 BOTTOM DECK

Bridge Loc. No: 38-SR001-02.89 Date: 9-9-19



SPAN # 1 STEEL I BEAM "H" HEAVY CORROSION & SECTION LOSS



SPAN # 1 HOLE IN STEEL I BEAM "H"

Bridge Loc. No: 38-SR001-02.89 Date: 9-9-19



SPAN # 1 BOTTOM DECK SPALLING



SPAN # 1 BOTTOM DECK SPALLING BETWEEN BEAMS "B & C"

Bridge Loc. No: 38-SR001-02.89 Date: 9-9-19



SPAN # 1 HOLE IN STEEL I BEAM "H" & HEAVY CORROSION



SPAN # 1 STEEL I BEAM "H" HEAVY CORROSION

Bridge Loc. No: 38-SR001-02.89 Date: 9-9-19




SPAN # 1 STEEL I BEAM "H" HEAVY CORROSION



SPAN # 1 STEEL I BEAM "B" SECTION LOSS

Bridge Loc. No: 38-SR001-02.89

Date: 9-9-19



SPAN # 1 HOLE IN STEEL I BEAM "B"

SEP 09 2019

BRIDGE INSPECTION REPORTForm BIR 3.0
(Rev. 9-22-98)
DT-0069

Field Report No.: _____

Date: 9/9/19Previous Report No.: 24Date: 11/1/17Co. Seq 01 Plans: YES () NO ()Bridge No. 38SR0010003 Bridge Location No. 38 - SR001 - 0289
Eleven Digit No. Co. Route Log Mile

OVER/UNDER PASS

HWY 79
Road NameBRANCH
Feature Intersected

CITY

Year Constructed 1926 County Haywood Maint. Dist: 48 Maint.Resp: 02

Year Widened _____ Year Rehabilitated _____

Structure Name (If Named)

FEATURESWearing Surface Concrete () Timber () Asphalt (☒) Depth 3" (in.)Flared Width Yes () No (☒) Median Width Open () None (☒) Closed ()Navigational Control Yes () No (☒) Bridge Skew 45R ° LT () RT ()Structure Type (Main Span) C. D. G. & STEEL I. BEAM

Structure Type (Appr.Spans) _____

No. Main Spans 1 No. Approach Spans _____Maximum Span Length 41.0 (**. ft.)Total Length 41.0 (**. ft.)**INSPECTORS**

1. Ellison (T.O.)
2. Wood
3. Johnston
4. Grillispie
5. Long
6. _____
7. _____
8. _____

WIDTHS (*. ft.)Deck Out-to-Out 34.0Roadway Curb/Curb 28.0

Roadway Rail/Rail _____

Sidewalk Rt. _____ Lt. _____

*Approach Roadway 24.0

*(Does Not Include Shoulders)

Approach Shoulder Rt. 4.0Lt. 4.0**CLEARANCES**

Min. Vertical Clearance over Deck _____ (ft.-in.)

Min. Vertical Under Clearance _____ (ft.-in.)

Min. Lateral Under Clearance Rt. _____ (*. ft.)

Min. Lateral Under Clearance Lt. _____ (*. ft.)

FRACTURE CRITICAL: _____

(If Yes, Include BIR 3.9)

NBIS Bridge Length (<25 ft.) _____ (ft.-in.)

UNDERWATER INSPECTION

To Be Performed By: _____ Date _____

DOT FIELD TEAM () CONTRACT DIVERS () NONE REQUIRED (☒)Change in Structural Condition: Yes () No (☒) Major Repairs Made: Yes () No (☒)**COMMENTS:**LATITUDE: N35 ° 27.3083 'LONGITUDE: W89 ° 25.6033 '

G.P.S. Location

BRIDGE RATING: () () (☒) ()

GOOD FAIR POOR CRITICAL

Supervising Bridge Inspector: Jason Ellison

SEP 09 2019

Form BIR 3.1
(Rev. 9-22-98)
DT-0080

Bridge Location No. 38 - SR001 - 2.89 -
Co. Route Log Mile

Date _____

PERFORMANCE EVALUATION

Time of Day Inspected 16:30 Weather Conditions Clear 80°
Vehicles Observed All types

LIVE LOAD BEHAVIOR

Substructure	YES	NO	Comments
Horiz./ Vert. Defl.	()	(X)	
Vibration	()	(X)	
Superstructure			
Horiz./ Vert. Defl.	()	(X)	
Vibration	()	(X)	

APPROACH

	Rating	Comments
Alignment	(G) F P C	
Slab	G F P C	
Joints	G F P C	
Pavement	(G) F P C	
Embankment	G (F) P C	
Drains	G F P C	

TRAFFIC SAFETY FEATURES

	Rating	STANDARD/ SUB-STANDARD	Comments
Bridgerailing	(G) F P C	() (X)	
Transitions	(G) F P C	() (X)	
Guardrail	(G) F P C	() (X)	
Guardrail Terminal	(G) F P C	(X) ()	

SIGNING

	YES	NO	NEEDED	Weight Limit Posted
Paddleboards	(X)	()	()	YES (X) NO ()
Vertical Clearance (<14'-6")	()	(X)	()	Gross..... Tons
NARROW ()	()	(X)	()	2 Axle..... <u>40</u> Tons
ONE LANE BRIDGE ()	()	(X)	()	3 or more Axles.. <u>40</u> Tons

Other Signs or Plaques: _____

Comments Regarding any
Problems with Signing: _____

DECK

	Rating	Comments
Wearing Surface	(G) F P C	
Deck - Structural Condition	G (F) P C	
Curbs	G (F) P C	
Median	G F P C	
Sidewalks	G F P C	
Parapet	G F P C	
Railing	(G) F P C	
Paint	G F P C	
Drains	G F (P) C	100% filled (043)
Lighting Standards	G F P C	
Utilities	G F P C	(?)
Joint Leakage	G F (P) C	
Expansion Joints	G F P C	

SUPERSTRUCTURE

(1) Bearing Devices	G F P C	
Beams S.I.B	G F P (C)	Span #1 B&H (244)
Girders	G (F) P C	
P.C.S.	G F P C	
BOLTS (PCCS)	G F P C	
Floor Beams	G F P C	
Stringers	G F P C	
Diaphragms	G F P C	
Bracing	G F P C	
Trusses - General	G F P C	
Portals	G F P C	
Bracing	G F P C	
Paint	G F (P) C	80% missing
Alignment of Members	(G) F P C	

TEXTURE COAT

Condition Rating	G F P C	Fading	G F P C
Overall Appearance	G F P C	Needs Spot Painting	YES () NO ()
Staining Rating	G F P C	Needs Repainting	YES () NO ()

Comments _____ Scaling Rating G F P C
RECOMMENDATIONS: _____ CLEAN SEAL JOINTS ()
_____ CLEAN DRAINS ()

SEP 09 2019

Date _____

SUBSTRUCTURE

PILES TO BE REPLACED

ABUTMENTS

	Rating	Comments	PILE(S)	ABUTMENT
Caps	G F P C			
Breastwall	G <u>F</u> P C			
Wings	G <u>F</u> P C			
Backwall	G <u>F</u> P C			
Plumb	<u>G</u> F P C			
Footing	G F P C			
Piles	G F P C			
Embankment	<u>G</u> F P C			
Bearing	G F P C	N/V		
Slope Paving	G F P C			
Rip Rap	G F P C			
Earthquake Devices	G F P C			

PIERS

	Rating	Comments	PILE(S)	PIER
Caps	G F P C			
Columns	G F P C			
Plumb	G F P C			
Footings	G F P C			
Piles	G F P C			
Bearing	G F P C			
Web	G F P C			
Earthquake Devices	G F P C			

BENTS

	Rating	Comments	PILE(S)	BENT
Caps	G F P C			
Columns	G F P C			
Plumb	G F P C			
Footings	G F P C			
Piles	G F P C			
Bearing	G F P C			
Bracing	G F P C			
Earthquake Devices	G F P C			

Piles Need Replacement:

NO (X) YES ()

CUT VEGETATION

NO () YES (X)

CLEAR DRIFT

NO (X) YES ()

RECOMMENDATIONS:

STREAM CHANNEL DATA AND CONDITIONS

Stream Crossing: BRANCH

- I. 1. Type of bed material? SAND S&T
2. Has channel shifted? YES () NO (☒) NOT APPARENT ()
3. Condition of rip-rap? G F P C Est. % failed _____ % N/A (☒)
4. Overall condition of channel? G (☒) F P C
5. Item 61 - Code values 0 thru 9 according to the recording
and coding guide currently in effect: 6
6. Underwater diver inspection recommended? YES () NO (☒)
If yes, why? _____

II. Channel and bank stability conditions: (check if applicable)

1. Steep bank conditions: - Failures upstream () Failures downstream ()
2. Moderate bank erosion (☒)
3. Bank vegetation: a. low growth () b. large timber (☒) c. clear banks ()
d. dead trees upstream (☒) e. dead trees downstream (☒)
4. Sediment or gravel accumulation: YES (☒) NO () UNKNOWN ()
5. Channel altered or straightened: YES () NO (☒) UNKNOWN ()
6. Stable conditions: a. live growth (☒) b. bedrock ()
c. boulders () d. flat slopes ($\leq 2:1$) ()

III. Waterway adequacy and debris characteristics: (check if applicable)

1. Bridge deck elevations:
a. level with approach roadway. (☒)
b. higher than approach roadway. ()
c. roadway approach ≥ 2 ft. above natural ground line. (☒)
2. Abutment encroaches into channel. ()
3. Large scour (blowhole) under bridge. ()
4. Indications that flood waters overtop bridge:
NO (☒) YES () OCASSIONALLY () FREQUENTLY () UNKNOWN ()
5. Debris characteristics:
a. debris/drift present YES (☒) NO ()
b. debris/drift likely to accumulate YES (☒) NO (☒)
c. dead trees upstream (☒) dead trees downstream (☒)

IV. Comments: _____

SPECIAL INSPECTION DATA - FOR REASONS OTHER THAN FC OR SCOUR

- I. Does this bridge need a special inspection? YES () NO (☒)
II. Reason for special inspection: _____

Inspection Team's Summary
Bridge Location No. 38 - SR001 - 02.89
Inspection Date 9-9-19
Bridge Rating POOR

THIS IS A 1 SPAN CONCRETE DECK GIRDER & STEEL I BEAM BRIDGE
WITH APPROACH RAILS, BRIDGE RAILS, 4 PADDLE BOARD SIGNS & 40
TON WEIGHT LIMIT POSTED ON APPROACH # 1 & 2
THE SUPERSTRUCTURE IS STEEL & CONCRETE
THE SUBSTRUCTURE IS CONCRETE
APPROACH # 1 & 2 A/C HAS NO VISIBLE PROBLEMS
THE A/C WEARING SURFACE HAS NO VISIBLE PROBLEMS
THE BOTTOM DECK HAS HAIRLINE CRACKS WITH EFFLORESCENCE
STAINS
THE SUPERSTRUCTURE HAS HEAVY CORROSION, FINE CRACKS &
SPALLING TO STEEL
SPAN # 1 STEEL I BEAMS " B & H" HAVE HEAVY CORROSION & SECTION
LOSS
THE CONCRETE DECK GIRDERS HAVE FINE CRACKS & SPALLING TO
STEEL
THE SUBSTRUCTURE HAS FINE CRACKS & SPALLING

VEGETATION IS POOR

SCOUR IS GOOD @ THIS TIME



JASON ELLISON

INSPECTOR

CROSS SECTION: YES () NO (X)

BRM: YES (X) NO ()

Bridge No. _____ Skew 90 RT.

SPAN. NO. 1 **SEP 09 2019**DOR 



ELEMENT	RATING	COMMENT
TOP DECK	G F P C	Dispelled
CURBS	G F P C	See ①
RAIL & POST	G F P C	
DRAINS	G F P C	100% filled
JOINT	G F P C	
	G F P C	

SEP 09 2010

BRIDGE NO. 38 1 2.89

SPAN NO. 1

SKEW 45°




BR. NO. 38-521-2.89

DATE 2/14/12


SPAN NO. 1

S.I.B. (B)



BOTTOM OF BEAM

Note: Heavy scalling and section loss on RT. inside web,




⑤

RIGHT SIDE OF BEAM

⑤ section of Fly missing
15.0/L x up to 4"/W

⑥ section of Fly missing
1.2"/L x up to 4"/W



① section of Fly missing
8 1/2 L x 3 1/4 W.

LEFT SIDE OF BEAM

④ Hole in web
3.5 L x 6 H

⑤ Hole in Top of web
4 L x 6 H

⑥ Hole in top of web
8.5 L x up to 6 H

⑩ Hole in Bottom of
web
20 L x 3 H


⑬ 1/2" Section loss on
Bottom flange
length of Beam

BR. NO. 38-SR1-289



DATE 2/14/12

SPAN NO. 1

S.I.B. (F-1)



BOTTOM OF BEAM




1 Flg. Missing up to 4' W x

LEFT SIDE OF BEAM


8 Hole 3' L x 8' High

9 Heavy Section loss on Bottom Flange
90' 3.5' Long


10 Hole 2' L x 3' H



LOOKING AHEAD



Spalled to steel
6" W x 1" L x 1 1/2" D




LOOKING BACK

Spalled to steel
Areas on Lt side
1 1/4" x 4 1/2" W x 1 1/2" D

ELEMENT		RATING	COMMENT
BOTTOM DECK		G (F) P C	Harline Cracks with Eff Stanes
S.I.B.	A	G (F) P C	light Corr
	B	G F P (C)	See 1-11 on Detail sheet
GIRDER	C	G (F) P C	See ① & Harline Cracks with Eff Stanes
	D	(G) F P C	
	E	G (F) P C	Harline Cracks
	F	(G) F P C	
	G	G (F) P C	See ② & Harline Cracks with Eff Stanes
S.I.B.	H	G F P (C)	See 1-10 on Detail sheet
	I	G (F) P C	light corrosion
PAINT		G F (P) C	80% Missing
BACKWALLS		G (F) P C	Harline Cracks
		G F P C	

38 -- SR 1 -- 2.89 45R
 Bridge No. Co. Route Log Mile R/L Skew

SEP 09 2010
 ABUT. NO. 1




ELEMENT	RATING	COMMENT
BEARING	G F P C	
PAINT	G F P C	
BREASTWALL	G F P C	
WINGS	G (F) P C	Hair line Cracks
EMBANKMENT	(G) F P C	
RIP RAP	G F P C	
VEGETATION	G F (P) C	- Heavy Growth

SEP 09 2019

38 -- SR 1 -- 2.89 45R
 Bridge No. Co. Route Log Mile R/L Skew

ABUT. NO. 2



ELEMENT	RATING	COMMENT
BEARING	G F P C	<i>MV</i>
PAINT	G F P C	
BREASTWALL	G (F) P C	<i>Cracks</i>
WINGS	G (F) P C	<i>Cracks + see ①</i>
EMBANKMENT	(G) F P C	
RIP - RAP	G F P C	<i>MV</i>
VEGETATION	G F (P) C	<i>Heavy growth</i>

SEP 09 2014

38SR0010003 38 SR001 0289
BRIDGE NO.: CO. ROUTE L.M. L/R

SKEW: 45R

No. of Spans: 1

No. of Approach Spans:

Direction of Route



A1


A2

F = FIXED

E = EXPANSION

S = SIMPLE

C = CONTINUOUS



SEP 09 2019

Your Agency Name

Your Office Name

Your Department Name

Structure Inventory and Appraisal Sheet (English Units)

ELEMENT CONDITION STATE DATA

Str Unit	Elm/Env	Description	Unit	Total Qty	% in 1	Qty. St. 1	% in 2	Qty. St. 2	% in 3	Qty. St. 3	% in 4	Qty. St. 4
0	12/3	Re Concrete Deck	sq.ft	1,394.00	93%	1,302.00	1%	10.00	6%	82.00	0%	0.00
0	510/3	Wearing Surfaces	sq.ft	1,148.00	78%	898.00	0%	0.00	22%	250.00	0%	0.00
0	1120/3	Efflorescence/Rust Staining	sq.ft	10.00	0%	0.00	100%	10.00	0%	0.00	0%	0.00
0	107/3	Steel Opn Girder/Beam	ft	164.00	0%	0.00	50%	82.00	0%	0.00	50%	82.00
0	515/3	Steel Protective Coating	sq.ft	164.00	0%	0.00	50%	82.00	0%	0.00	50%	82.00
0	3420/3	Peel/Bub/Crack(Sil Protect Coat)	sq ft	164.00	0%	0.00	50%	82.00	0%	0.00	50%	82.00
0	1000/3	Corrosion	ft	164.00	0%	0.00	50%	82.00	0%	0.00	50%	82.00
0	110/3	Re Conc Opn Girder/Beam	ft	205.00	59%	120.00	42%	85.00	0%	0.00	0%	0.00
0	1080/3	Delamination/Spall/Patched Area	ft	2.00	100%	2.00	0%	0.00	0%	0.00	0%	0.00
0	1090/3	Exposed Rebar	ft	3.00	0%	0.00	100%	3.00	0%	0.00	0%	0.00
0	1120/3	Efflorescence/Rust Staining	ft	82.00	0%	0.00	100%	82.00	0%	0.00	0%	0.00
0	215/3	Re Conc Abutment	ft	96.00	88%	84.00	10%	10.00	2%	2.00	0%	0.00
0	1080/3	Delamination/Spall/Patched Area	ft	4.00	50%	2.00	0%	0.00	50%	2.00	0%	0.00
0	1130/3	Cracking (RC and Other)	ft	10.00	0%	0.00	100%	10.00	0%	0.00	0%	0.00
0	330/3	Metal Bridge Railing	ft	82.00	100%	82.00	0%	0.00	0%	0.00	0%	0.00