



Latitude:35.72240, Longitude:-86.32037

Region 03, 75 - Rutherford County


Team Leader: Carlos Goncalves

Inspectors: Maxwell Benefield, Daryl Ballard, Seth Mechling



County: 75 - Rutherford, Route: 01044, Log mile: 0.480

Team Lead: Carlos Goncalves, **Inspection Date:** 06/14/2024



EPPS MILL RD. Crossing I24 35.72240, -86.32037



Region: 03, County: 75 - Rutherford

Team Lead: Carlos Goncalves, Inspection Date: 06/14/2024

90 - LAS	T INSPECTI	06/14/202	2		
	V.C. OVER	99).99 FT.		
	I. V.C. OVEI DES SHOUL	99).99 FT.		
36 - TRAI	FFIC SAFE	TY FEATUR	ES		
Br. Rail	Trans.	Appr. Rail	Termir	nal SPI	EED LIM.
0	1	1	N		
41 - STR	C OPEN/CL	OSED/POST	ΓED	Р	
58 - DEC	K			6	
59 - SUPI	ERSTRUCT	URE		6	
60 - SUB	STRUCTUR	RE		7	
61 - CHA	NL/CHANL	PROTECTIO	ON	N	
62 - CUL	VERT AND	N			
71 - WAT	ERWAY AD	N			
72 - APP	ROACH RE	8			
521 - OVI	ERALL CON	2 - Fair			
16 - LATI	TUDE	JDE			
35.722400 -86.3203				867	

- N NOT APPLICABLE
- 9 EXCELLENT CONDITION
- 8 VERY GOOD CONDITION NO PROBLEMS NOTED.
- 7 GOOD CONDITION SOME MINOR PROBLEMS.
- 6 SATISFACTORY CONDITION MINOR DETERIORATION OF STRUCTURAL ELEMENTS.
- 5 FAIR CONDITION ALL PRIMARY STRUCTURAL ELEMENTS ARE SOUND BUT MAY HAVE MINOR SECTION LOSS, CRACKING, SPALLING OR SCOUR.
- 4 POOR CONDITION ADVANCED SECTION LOSS, DETERIORATION, SPALLING OR SCOUR.
- 3 SERIOUS CONDITION LOSS OF SECTION, DETERIORATION, SPALLING OR SCOUR HAVE SERIOUSLY AFFECTED PRIMARY STRUCTURAL COMPONENTS. LOCAL FAILURES ARE POSSIBLE. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT.
- 2 CRITICAL CONDITION ADVANCED
 DETERIORATION OF PRIMARY STRUCTURAL
 ELEMENTS. FATIGUE CRACKS IN STEEL OR
 SHEAR CRACKS IN CONCRETE MAY BE
 PRESENT OR SCOUR MAY HAVE REMOVED
 SUBSTRUCTURE SUPPORT. UNLESS
 CLOSELY MONITORED IT MAY BE
 NECESSARY TO CLOSE THE BRIDGE UNTIL
 CORRECTIVE ACTION IS TAKEN.
- 1 "IMMINENT" FAILURE CONDITION MAJOR DETERIORATION OR SECTION LOSS PRESENT IN CRITICAL STRUCTURAL COMPONENTS OR OBVIOUS VERTICAL OR HORIZONTAL MOVEMENT AFFECTING STRUCTURAL STABILITY. BRIDGE IS CLOSED TO TRAFFIC BUT CORRECTIVE ACTION MAY PUT IT BACK IN LIGHT SERVICE.
- 0 FAILED CONDITION OUT OF SERVICE AND BEYOND CORREC



IDENTIFIC	ATION
(1) State Names	47 - Tennessee
(8) Structure Number	75100240041
(5) Inventory Route	1
(2) Highway Agency District	Region 3
(3) County Code	75 - Rutherford
(4) Place Code	00000
(6) Features Intersected	10024
(7) Facility Carried	NFA 1044 (SA 7516)
(9) Location	5.2 MI NE JCT SR10&SR269
(11) Mile Point	0.480 mi
(12) Base Highway Network	No
(13) LRS Inventory Rte & Subrte	
(16) Latitude	35.722400
(17) Longitude	-86.320367
(98) Border Bridge State Code	
(99) Border Bridge Structure No.	ND MATERIAL
STRUCTURE TYPE A	
(43) Main Structure Type Material	42 4 - Steel continuous
Туре	2 - Stringer/Multi-beam or girder
(44) Approach Structure Type	2 - Stringer/Multi-beart or girder
Material	0 - Other / None
	0 - Other / None
Type (45) No. of Spans in Main Unit	0 - Other / None
(46) No. of Approach Spans	0
(107) Deck Structure Type	1 - Concrete Cast-in-Place
 	
(108) Wearing Surface/Protective System	6 - Bituminous
Type of Wearing Surface	-
Type of Membrane	0 - None 0 - None
Type of Deck Protection	
AGE AND SE	
(27) Year Built	1968
(106) Year Reconstructed	0
(42) Type of Service	11
On	1 - Highway
	Highway, with or without pedestrian
(28) Lane	
On	2
Under	4
(29) Average Daily Traffic	3334
(30) Year of ADT	2021
(109) Truck ADT	3 %
(19) Bypass, Detour Length	10 mi
GEOMETRIC	
(48) Length of Maximum Span	149.9 ft
(49) Structure Length	299.9 ft
(50) Curb or Sidewalk Width	1-#
	Left 0.0 ft
(54) D.: I. D. I. WEIR O. I. C.	Right 0.0 ft
(51) Bridge Roadway Width Curb to Curl	
(52) Deck Width Out to Out	32.5 ft
(32) Approach Roadway Width (W/Shou	
(33) Bridge Median	0 - No median
(34) Skew	80 Deg
(35) Structure Flared	0 - No flare
(10) Inventory Route Min Vert Clear	99.99 ft
(47) Inventory Route Total Horiz Clear	27.9 ft
(53) Min Vert Clear Over Bridge Rdwy	99.99 ft
(54) Min Vert Underclear	16.17 ft
Ref:	00.45
(55) Min Lat Underclear RT Ref:	36.1 ft
(56) Min Lat Underclear LT	52.2 ft
NAVIGATIO	
(38) Navigation Control	N - Not applicable, no waterwa
(111) Pier Protection	., ,
(39) Navigation Vertical Clearance	0.0 ft
(116) Vert-Lift Bridge Nav Min Vert Clear	
(40) Navigation Horizontal Clearance	0.0 ft
_ , ,	*****

CLASSIFI	CATION
(112) NBIS Bridge Length	Υ
(104) Highway System	0
(26) Functional Class	17 - Urban Collector
(100) Defense Highway	0 - The inventory route is not
(101) Parallel Structure	N - No parallel structure exis
(102) Direction of Traffic	2 - way traffic
(103) Temporary Structure	
(105) Federal Lands Highways	0 - N/A
(110) Designated National Network	0 - The inventory route is not
(20) Toll	3 - On free road. The structu
(21) Maintain	1 - State Highway Agency
(22) Owner	1 - State Highway Agency
(37) Historical Significance	5 - Bridge is not eligible for
CONDI	TION
(58) Deck	6
(59) Superstructure	6
(60) Substructure	7
(61) Channel & Channel Protection	N
(62) Culverts	N
LOAD RATING A	AND POSTING
(31) Design Load	4 - M 18 / H 20
(63) Operating Rating Method	8
(64) Operating Rating	
	d and Resistance Factor Rating (LRF
Rating	23.98
(65) Inventory Rating Method	8 - Load and Resistance Factor
(66) Inventory Rating	0 - Load and Nesistance i actor
· · ·	
Type Rating	18.47
	5 - Equal to or above legal loads
(70) Bridge Posting (41) Structure Open/Posted/Closed	P - Posted for load (may inclu
APPRA	
(67) Structural Evaluation	5
(68) Deck Geometry	4
(69) Clearances, Vertical/Horizontal	5
(71) Waterway Adequacy	N c
(72) Approach Roadway Alignment	O Increated feature does not meet
(36A) Bridge Railings	0 - Inspected feature does not meet
(36B) Transitions	1 - Inspected feature meets current
(36C) Approach Guardrail	1 - Inspected feature meets current
(36D) Approach Guardrail Ends	N - Not applicable or a safety feat
(113) Scour Critical Bridges	N - Bridge not over waterway.
PROPOSED IMP	PROVEMENTS
(75) Type of Work	36 - Bridge deck rehabilitation
(76) Length of Structure Improvement	299.9 f
(94) Bridge Improvement Cost	\$ 443
(95) Roadway Improvement Cost	\$ 45
(96) Total Project Cost	\$ 665
(97) Year of Improvement Cost Estima	te 2022
(114) Future ADT	5334
(115) Year of Future ADT	2042
INSPECT	CIONE *
(90) Inspection Date	06/14/2024
(91) Frequency	24
(92) Critical Feature Inspection	Done Freq. (Mon) Date
A: Fracture Critical Detail	No
B: Underwater Inspection	No
C: Other Special Inspection	No
* The inspection date and frequency the current NBI date and frequency i report header for the date this inspec	nformation. Please refer to the



PERFORMANCE EVALUATION					
Time of Day Inspecte	d 11:02 AM			Weather Conditions	SUNNY 88
Vehicles Observed	ALL TYPES				
_					
		LIV	E LOAD BE	EHAVIOR	
Sub Horiz./ Vert. De	fl (No)				
Sub Vibration	(No)				
Super Horiz./ Vert. D	Defl (Yes)				
Super Vibration	(No)				
			APPROA	ACH	
Alignment	(Coc4)				
Alignment	(Good)	AC DATCHES	AND DOTUG		
Pavement	(Fair)	AC PATCHES	AND POTHO	LES AT BOTH ENDS	5
Embankment	(Good)	MOD DEBRIS	יאי חוו ח וווום	' END DT	
Approach Drains	(Good)	MIOD DEBKIS	BUILD-UP A	END KI.	
		TRAFF	IC SAFETY	/ FEATURES	
Bridge Railing Rating	(Good)	SPAN #1 LT9	SPALL, LGT S	SURFACE SCALE	
Transitions Rating	(Good)				
Guardrail Rating	(Good)	A END RIGHT	- IMPACT DA	AMAGE	
		SIGN	S POSTED	ON ROUTE	
Paddleboards		No	V	Weight Limit Posted	Yes
Vertical Clearance (<14'-6")		No	(Gross	40 Tons
Posted Height			S	Single-unit Vehicle	Tons
Narrow Bridge Signs		No		· ·	
One Lane Bridge Sig	ns	No		Multi-unit Vehicle	Tons
Other Signs or Plaques			5	564 Assigned Bridge Name	



DECK

Wearing Surface Typ	e Asphalt	Wearing Surface Depth 10
Wearing Surface	(Fair)	SP 2AC PATCHES DOWN CENTERLINE
Deck - Structural Condition	(Fair)	NUMEROUS MAP CRACKS W/EFF, RANDOM SPALLS
Curbs	(Good)	
Expansion Joints	(Poor)	MOD DEBRIS BUILD-UP, ANGLED UP 90 DEGRES @ ENDS TRAPPING DEBRIS
		SUPERSTRUCTURE
Bearing Devices	(Fair)	MOD CORR ABUT #1 & #2. ALSO BEARINGS HAVE A TILT UPSTATION OF 2"-2-1/2" @ AB #1, BRG. 'A' @ BENT-LOOSE NUT
Girders	(Fair)	LGT CORR & PITT ON BTM FLANGES, IMPACT DAMAGE- BM 'D' SPAN #2 REPAIRED 2014
Diaphragms	(Good)	IMPACT DAMAGE @ BAY 'C' SPAN #2 REPAIRED 2014
Trusses - Bracing	(Good)	INTERMEDIATE SPANS #1 & #2
Superstructure Paint	(Fair)	FLAKING & AREAS OF ACTIVE CORROSION
Alignment of Members	(Good)	

TEXTURE COAT



		ABUTMENTS
Abutment Caps	(Good)	ABUT. #1 & #2-VERT., DIAG, HORIZ. CRACKS UP TO 1/16" OPEN, SPALLS; ABUT 1DELAM
Abutment Breastwall	(Good)	ABUT #1 & #2-VERT. CRACKS UP TO 1/16" OPEN WITH EFF.
Abutment Wings	(Good)	MAP CRACKS WITH EFF.
Abutment Backwall	(Good)	1/16" VERTICAL CRACKS, ABUTMENT #2 - MAP CRACKING W/EFF.
Abutment Plumb	(Good)	
Abutment Piles	(Not Visible)	
Abutment Embankment	(Good)	
Abutment Bearing Surface	(Good)	
Abutment Slope Paving	(Good)	

BENTS					
Bent Caps	(Good)				
Bent Columns	(Good)				
Bent Plumb	(Good)				
Bent Footing	(Not Visible)				
Bent Bearing Surface	(Good)				



Inspection Team's Summary

The 2 span WPG bridge on Epps Mill Road over I0024 was inspected and found to be in overall FAIR condition.

Bridge is posted for 40 tons. Approach traffic safety features are good and standard.

Approach alignment and embankment are good. Approach pavement is fair with a/c patches at both ends.

The asphalt-wearing surface is fair with a/c patches in span #2. The strip seal joints are poor with moderate-heavy debris, corrosion and light section loss. Joints are angled up 90 degrees at ends which is trapping debris in joint. The underside of the deck is fair with numerous map cracks with efflorescence. The bridge rails are good. The current Deck condition rating is Fair (6).

Girders are fair due to light corrosion and pitting on bottom flanges, and impact damage repairs on beam 'D' span #2. Bearings are fair at abutment #1 and #2 with moderate corrosion and 2" to 2.5" of tilt up station. The current Superstructure condition rating is Fair (6).

Abutments are good. The bent cap and columns are good. The current Substructure condition rating is Good (7).

The underpass safety features are good.

General Inspection Comment

HQ notes to TL



County: 75 - Rutherford, Route: 01044, Log mile: 0.480

Team Lead: Carlos Goncalves, Inspection Date: 06/14/2024

ELEMENTS	DESCRIPTION	UNITS	TOTAL	CS1	CS2	CS3	CS4
12	Re Concrete Deck	SF	9741	5795	3946	0	0
1080	Delamination/Spall/Patched Area	SF	50	0	50	0	0
1130	Cracking (RC and Other)	SF	3896	0	3896	0	0
510	Wearing Surfaces	SF	8340	7340	1000	0	0
3210	Delamination/Spall/Patched Area/Pothole (Wearing Surfaces)	SF	1000	0	1000	0	0
(12) Elemen	nt record added 2016-06-06.						
(1080-12) E	lement record added 7/14/2020						
(510-12) El∈	ement record added 2016-06-06.						
107	Steel Opn Girder/Beam	LF	1201	951	200	50	0
1000	Corrosion	LF	250	0	200	50	0
515	Steel Protective Coating	SF	15613	0	0	15313	300
3440	Effectiveness (Steel Protective Coatings)	LF	15613	0	0	15313	300
(107) Eleme	ent record added 2016-06-06.						
(1000-107)	Element record added 2016-06-29.						
(515-107) E	lement record added 2016-06-06.						
205	Re Conc Column	EA	2	2	0	0	0
(205) Eleme	ent record added 2016-06-06.						
215	Re Conc Abutment	LF	66	34	32	0	0
1080	Delamination/Spall/Patched Area	LF	2	0	2	0	0
1130	Cracking (RC and Other)	LF	30	0	30	0	0
(215) Eleme	ent record added 2016-06-06.						
(1080-215)	Element record added 2016-06-29.						
234	Re Conc Pier Cap	LF	30	26	4	0	0
1130	Cracking (RC and Other)	LF	4	0	4	0	0
(234) Eleme	ent record added 2016-06-06.						
303	Assem Jnt With Seal	LF	66	0	0	0	66
2350	Debris Impaction	LF	66	0	0	0	66
(303) Eleme	ent record added 2016-06-06.						
(2350-303)	Element record added 2016-06-29.						
311	Moveable Bearing	EA	8	0	8	0	0
1000	Corrosion	EA	7	0	7	0	0
1020	Connection	EA	1	0	1	0	0





ELEMENTS	DESCRIPTION	UNITS	TOTAL	CS1	CS2	CS3	CS4
515	Steel Protective Coating	SF	16	16	0	0	0
(311) Eleme	ent record added 2016-06-06.						
(1000-311)	Element record added 2016-06-29.						
(1020-311)	Element record added 2016-06-29.						
(515-311) El	lement record added 2016-06-06.						
313	Fixed Bearing	EA	4	4	0	0	0
515	Steel Protective Coating	SF	8	8	0	0	0
(313) Eleme	ent record added 2016-06-06.						
(515-313) El	lement record added 2016-06-06.						
331	Re Conc Bridge Railing	LF	600	599	0	1	0
1080	Delamination/Spall/Patched Area	LF	1	0	0	1	0
(331) Element record added 2016-06-06.							
(1080-331)	Element record added 2016-06-29.						



Equi	pment	List
------	-------	------

General Inspection	Tools For Measuring
Pocket knife	Masonry/Wood Ruler
Sounding/chipping hammer	6' Pocket Tape
Chain drag	<u>Yes</u> 25' and 100' Tape
Range pole	Calipers
Yes 25' rod - depth and clearance	Yes Thermometer
Visual Aid	Carpenter's Level String and Weighted line (plumb bob)
Binoculars	Special Purpose Equipment
Flashlight	
Magnifying glass	Reach All
Hand mirror	Bucket Truck
Cleaning	Traffic control
Wisk broom	Boat Sonar depth finder
Wire brush	Increment borer
Flat bladed screwdriver	Survey equipment
Hand shovel	Safety Harness
Penetrating oil (WD-40, etc.)	Climbing equipment
Tools For Access	Dye penetrant
Ladders	Drone
Rope	Air Meter
Waders	Special Purpose Equipment
Machete or bush axe	

Reach-All Approval and Comments

Comment





Bridge number abutment 1 Lt. side



Left side view





Right side view



B approach weight posted sign





A approach weight posted sign



Elevation Lt Side





Elevation Rt Side



A approach





B approach



A approach pavement A/C patches





A approach pavement pothole



B approach wearing surface left side pothole





B approach wearing surface area of map cracking full length



A approach Rt. side guardrail damage





View along deck




Span 2 near B approach area of small potholes over A/C patches





Span 1 near A approach 1/8" open longitudinal crack



A approach wearing surface A/C patches





Bottom of Deck Span 1



Spall in Bot Deck Bay 2 Span 1





Bottom of Deck Span 2



Bridge parapet right side near B approach joint area of delamination





Bridge parapet left side near A approach joint area of delamination



Bridge parapet right side near A approach joint spall with exposed steel





A approach joint filled with light debris



B approach joint filled with light debris





Abutment 1 moderate corrosion on bearings



Bent 1 Lt. side loose nut at bearing A





Abutment 2 bearings B - D moderate corrosion



Abutment 1 cap random hairline cracks w/EFF. throughout





Abutment 1 cap Lt. side area of delamination



Abutment 1 cap Lt. side spall





Abutment 2 cap Rt. Side spall



Abutment 2 cap random hairline cracks throughout





Abutment 2 cap map cracking



Abutment 2 cap 1/16" vertical cracks throughout





Abutment 1 breastwall Random hairline cracks w/EFF. Throughout




Abutment 1





Abutment 2




Abutment 1 Lt. wing map cracks w/EFF.





Abutment 1 Rt. Wing map cracks w/EFF.



Abutment 1 backwall Lt. side 1/16" vertical crack





Abutment 1 backwall Rt. Side 1/16" vertical crack



Abutment 2 Rt. Side backwall map cracking w/EFF





Abutment 2 backwall Lt. side 1/16" vertical crack



Bent 1 frontside






Bent 1 backside






Maintenance Recommendations							
525 - Repair List # N	523 - Repair List Add Date	524 - Repair List Revise Date 6/14/2022					

Date Added	Recommendation	Priority
06/22/2016	CLEAN EXPANSION JOINTS AT BOTH ENDS	
06/22/2016	REPAIR DETERIORATING DECK AREAS	
06/22/2016	CLEAN & PAINT ALL STRUCTURAL STEEL	
06/14/2022	REPAIR APPROACH PAVEMENT @ BOTH ENDS.	2
06/22/2016	EXTEND EXPANSION JOINTS OUT BEYOND BRIDGE RAIL	
06/09/2020	REPAIR JOINT ARMOR @ 'A' & 'B' ENDS	1



PAVEMENT	FAIR	AC PATCHES; POTHOLE
EMBANKS	GOOD	
DRAINS	FAIR	MOD. DEBRIS BLD-UP-RT SIDE
G-RAILS	GOOD	LIGHT DAMAGE
BR RAILS	GOOD	LIGHT SCALE, AREA OF DELAM., SPALL WITH EXPOSED STEEL




1.5' X 10"

PAVEMENT	FAIR	POTHOLE, HAIRLINE MAP CRACKING
EMBANKS	GOOD	
DRAINS	GOOD	
G-RAILS	GOOD	
BR RAILS	GOOD	LT SCALE


7" X 4" X 1/2"DP

MB



DECK	NV	A/C OVERLAY- GOOD
CURBS	GOOD	
RAILS	GOOD	LGH. SURFACE SCALE
JOINT	POOR	HVY. DEBRIS BUILD UP

MB




DECK	N/V	A/C OVERLAY-FAIR; AC PATCHES, POTHOLES
CURBS	GOOD	
RAILS	GOOD	LGH. SURFACE SCALE
JOINT	POOR	HVY. DEBRIS BUILD UP

Bottom of Slab Span No. 1

Date 6/14/2024 DB2

Bridge Location No. 75 1044 0.48
County Route Log Mile


HEAVY SPALL WITH EXPOSED STEEL 1' X 5" X 5"DP



DECK	FAIR	SPALL /EXP STL 1'DIA X 1"D,
		CONC. REPAIR @ ABUT. #1 AT ALL BAYS
BRACING	GOOD	INTERMEDIATE
DIAPH.	GOOD	
GIRDER A	GOOD	MOD CORR TOP FLANG 3' FROM ABUT #1
GIRDER B	FAIR	MOD CORR BTM FLANGE OVER ROAD
GIRDER C	FAIR	MOD CORR BOTTOM FLANGE- OVER ROAD
GIRDER D	FAIR	MOD. CORRO. TOP FLANGE 3' FROM ABUT. # 1, MOD CORR
		BOTT FLANGE-OVER ROAD
OVERHANGS	GOOD	RDM. H.C.'S W/EFF., RUST STAINS
PAINT	POOR	PEELING BM'S "B"-"D", FADING ALL BMS & DIAPHRAMS

Bottom of Slab Span No. 2


Date 6/14/2024 DB2



FAIR	H.L. MAP CRACKS W/EFF, CONC.
	REPAIRS AT ABUT #2 AT ALL BAYS
GOD	INTERMEDIATE
GOOD	
FAIR	LIGHT CORRBOT FLANGE, TOP FLANGE AT ABUT 2
GOOD	LIGHT CORROSION
GOOD	LIGHT CORROSION
FAIR	REPAIRED SECTION FROM IMPACT DAMAGE, LGT. CORR.
	OUTSIDE OF TOP & BTM. FLANGE 3'L, LGH CORR. BOTT
	FLANGE 25'L OVER RD, TOP FLANGE AT ABUT 2
FAIR	MAP CRACKS W/EFF, H.C.'S W/EFF
FAIR	FADING, PEELING ON ALL BEAMS
	GOOD FAIR GOOD FAIR FAIR




Date: 6/14/2024 SM



WALL	GOOD	OPEN CRACK UP TO 1/16" OPEN- 6'L W/ H.L. PATTERN CRACKS
CAP	GOOD	HORIZ/VERT H.C.'S W/EFFL
		LGT RUST STAINS; IMPACT DMG; AREA OF DELAM. 8"DIA
BEARING	FAIR	MOD. CORROSION ON ALL - PAINTED W/ MOD.RUST STAINS
LT. WING	GOOD	RDM MAP CRACK W/EFF
RT. WING	GOOD	RDM MAP CRACKS W/EFF
EMBANKMNT	GOOD	

Abutment No. 2

Date: 6/14/2024 SM




\\/\\	GOOD	DATTERN HICKS VERT CRACK LIR TO 1/16" OREN
WALL	GOOD	PATTERN H.C.'S, VERT CRACK UP TO 1/16" OPEN,
		FULL HEIGHT
CAP	GOOD	VERT CRACKS UP TO 1/16" OPEN-UP TO FULL HEIGHT,
		RANDOM DIAG/HORIZ H.C.'S, SPALL
BEARING	FAIR	MOD. CORROSION AT "B, C, & D"
LT. WING	GOOD	RANDOM H.L. PATTERN CRACKS
RT. WING	GOOD	

Clearances

Date: 6/14/2024

EPPS MILL RD



U.P. 75-10024-25.73