


LAUDERDALE COUNTY



**49-SR087-2076**

**Federal ID: 49S80460003**

**Road Name:**

**Crossing: DRAINAGE DITCH**

**OVR/UND PASS:**

**Road Name 2:**

# BRIDGE MAINTENANCE RECOMMENDATIONS



Tennessee Department  
of Transportation

COUNTY: LAUDERDALE  
LOCATION: 49-SR087-20.76-  
CO. SEQ.: 1 SPEC. CASE: 0

CROSSING: DRAINAGE DITCH  
FED. BRIDGE NO.: 49S80460003  
MAINT. DIST.: 49

REPAIR LIST NO.: N  
DATE ADDED:  
REVISED: 11/10/2021

FACILITY CARRIED:	FAU 87	NUMBER OF MAIN SPANS:	1
HIGHWAY SYSTEM:	05-STP RURAL, STATE	NUMBER OF APPROACH SPANS:	0
BRIDGE WIDTH (CURB TO CURB):	27 FT 10 IN	BRIDGE LENGTH (FT):	28
BRIDGE WIDTH (OUT TO OUT):	28 FT 10 IN	MAXIMUM SPAN LENGTH (FT):	28
APPROACH ROADWAY (W/SHOULDERS):	27 FT 10 IN	SKEW ANGLE (DEGREES):	90

MAINTAINED BY:	STATE HIGHWAY AGENCY
MAIN SPAN MATERIAL:	CONCRETE
MAIN SPAN DESIGN TYPE:	CHANNEL BEAM
APPROACH SPAN MATERIAL:	OTHER OR NOT APPLICABLE
APPROACH SPAN DESIGN TYPE:	OTHER OR NOT APPLICABLE

INSPECTION DATE:	11/10/2021	GENERAL CONDITION:	FAIR
EVALUATION DATE:	01/21/2020	STRUCTURALLY DEFICIENT:	NO
PPRM PIN NUMBER:			
H TRUCK RATING @ INV.:	15 TONS	SUFFICIENCY RATING:	86.2

## SUGGESTED ROUTINE MAINTENANCE AND COMMENTS

CLEAR DRAINS

APPROACH GUARDRAILS ARE SUBSTANDARD

BRIDGERAILS ARE SUBSTANDARD

## GENERAL COMMENTS:



STATE OF TENNESSEE  
DEPARTMENT OF TRANSPORTATION

# Bridge Condition Coding Form

Revised 11/12/2021

Bridge Number:   
(Includes Item 5A)

Feature Intersected:

Evaluation Status:

County:

Route:

Special Case:

County Sequence:

Log Mile:

## CODE ONLY THOSE VALUES WHICH HAVE CHANGED

ITEM #	DESCRIPTION	VALUE	CONDITION CODING GUIDELINES
90	LAST INSPECTION DATE	<input type="text" value="11/10/2021"/>	(Values for Coding Items 58, 59, 60 and 62)
	EARLIEST DATE OF NEXT REGULAR INSPECTION	<input type="text" value="09/11/2023"/>	
		<input type="text" value="/ /"/>	
10	MINIMUM V.C. OVER DECK (ROADWAY + SHOULDERS)	99 FT. <input type="text" value="99"/> IN.	N NOT APPLICABLE
520	MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS)	99 FT. <input type="text" value="99"/> IN.	9 EXCELLENT CONDITION
36	TRAFFIC SAFETY FEATURES		8 VERY GOOD CONDITION - NO PROBLEMS NOTED.
	Br. Rail Trans. Appr. Rail Terminal SPEED LIMIT	0 0 0 1 35	7 GOOD CONDITION - SOME MINOR PROBLEMS.
41	STRC OPEN/CLOSED/POSTED	P	6 SATISFACTORY CONDITION - MINOR DETERIORATION OF STRUCTURAL ELEMENTS.
	A K P		5 FAIR CONDITION - ALL PRIMARY STRUCTURAL ELEMENTS ARE SOUND BUT MAY HAVE MINOR SECTION LOSS, CRACKING, SPALLING OR SCOUR.
58	DECK	7	4 POOR CONDITION - ADVANCED SECTION LOSS, DETERIORATION, SPALLING OR SCOUR.
59	SUPERSTRUCTURE	7	3 SERIOUS CONDITION - LOSS OF SECTION, DETERIORATION, SPALLING OR SCOUR HAVE SERIOUSLY AFFECTED PRIMARY STRUCTURAL COMPONENTS. LOCAL FAILURES ARE POSSIBLE. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT.
60	SUBSTRUCTURE	6	2 CRITICAL CONDITION - ADVANCED DETERIORATION OF PRIMARY STRUCTURAL ELEMENTS. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT OR SCOUR MAY HAVE REMOVED SUBSTRUCTURE SUPPORT. UNLESS CLOSELY MONITORED IT MAY BE NECESSARY TO CLOSE THE BRIDGE UNTIL CORRECTIVE ACTION IS TAKEN.
61	CHANL/CHANL PROTECTION	6	1 "IMMINENT" FAILURE CONDITION - MAJOR DETERIORATION OR SECTION LOSS PRESENT IN CRITICAL STRUCTURAL COMPONENTS OR OBVIOUS VERTICAL OR HORIZONTAL MOVEMENT AFFECTING STRUCTURAL STABILITY. BRIDGE IS CLOSED TO TRAFFIC BUT CORRECTIVE ACTION MAY PUT IT BACK IN LIGHT SERVICE.
62	CULVERT AND RETAIN WALL	N	0 FAILED CONDITION - OUT OF SERVICE AND BEYOND CORRECTIVE ACTION.
71	WATERWAY ADEQUACY	6	
72	APPROACH RDWY ALIGNMENT	8	
521	OVERALL CONDITION	<input type="text" value="FAIR"/>	
16	LATITUDE	17 LONGITUDE	
	N 35° 40.3417'	W 89° 34.3617'	
	<input type="text" value=""/>	<input type="text" value=""/>	
TEAM LEADER SIGNATURE		REVIEW DATE	
<input type="text" value=""/>		<input type="text" value=""/>	

Bridge Loc. No: 49-SR087-20.76      Date: 11-10-21



BRIDGE NUMBER



DIRECTION OF ROUTE



**Bridge Loc. No: 49-SR087-20.76      Date: 11-10-21**



**APPROACH # 1 WEIGHT LIMIT SIGN**



**VIEW ACROSS TOP OF DECK**

**Bridge Loc. No: 49-SR087-20.76      Date: 11-10-21**



**OPPOSITE DIRECTION OF ROUTE**



**APPROACH # 2 WEIGHT LIMIT SIGN**



**Bridge Loc. No: 49-SR087-20.76      Date: 11-10-21**



**ABUTMENT # 2**



**ABUTMENT # 1**

**Bridge Loc. No: 49-SR087-20.76      Date: 11-10-21**



**BOTTOM DECK OF SPAN # 1**



**RIGHT ELEVATION**



**Bridge Loc. No: 49-SR087-20.76      Date: 11-10-21**



**LEFT ELEVATION**



**DIRFT CAUGHT ON PIPE IN MIDDLE OF CHANNEL**

NOV 10 2021

## BRIDGE INSPECTION REPORT

Form BIR 3.0  
(Rev. 9-22-98)  
DT-0069

Field Report No.: 26 Date: 11/10/21  
Previous Report No.: 25 Date: 12/30/19  
Co. Seq 01 Plans: YES ( ) NO ( )

Bridge No. 49S80460003 Bridge Location No. 49 - SR087 - 2076  
Eleven Digit No. Co. Route Log Mile OVER/UNDER PASS

DRAINAGE DITCH  
Road Name Feature Intersected CITY  
Year Constructed 1992 County Lauderdale Maint. Dist: 49 Maint. Resp: 02  
Year Widened Year Rehabilitated

Structure Name (If Named)

### FEATURES

Wearing Surface Concrete ( ) Timber ( ) Asphalt (☒) Depth 1" (in.)  
Flared Width Yes ( ) No (☒) Median Width Open ( ) None (☒) Closed ( )  
Navigational Control Yes ( ) No (☒) Bridge Skew 90 ° LT ( ) RT ( )  
Structure Type (Main Span) P. C. C. S.  
Structure Type (Appr. Spans)  
No. Main Spans 1 No. Approach Spans  
Maximum Span Length 28.0 (\*\*. ft.)  
Total Length 28.0 (\*\*. ft.)

### INSPECTORS

1. Kee (TL)  
2. S. Hayer  
3. A. Hayer  
4. Cox  
5.  
6.  
7.  
8.

### WIDTHS (\*. ft.)

Deck Out-to-Out 29.1  
Roadway Curb/Curb 27.9  
Roadway Rail/Rail  
Sidewalk Rt. Lt.  
\*Approach Roadway 20.0  
\*(Does Not Include Shoulders)  
Approach Shoulder Rt. 4.0  
Lt. 4.0

### CLEARANCES

Min. Vertical Clearance over Deck (ft.-in.)  
Min. Vertical Under Clearance (ft.-in.)  
Min. Lateral Under Clearance Rt. (\*. ft.)  
Min. Lateral Under Clearance Lt. (\*. ft.)

### FRACTURE CRITICAL:

(If Yes, Include BIR 3.9)

NBIS Bridge Length (<25 ft.) (ft.-in.)

### UNDERWATER INSPECTION

To Be Performed By: Date

DOT FIELD TEAM ( ) CONTRACT DIVERS ( ) NONE REQUIRED (☒)

Change in Structural Condition: Yes ( ) No (☒) Major Repairs Made: Yes ( ) No (☒)

### COMMENTS:

LATITUDE: N35 ° 40.3416

LONGITUDE: W89 ° 34.3616

G.P.S. Location

BRIDGE RATING: ( ) (☒) ( ) ( )

GOOD FAIR POOR CRITICAL

Supervising Bridge Inspector: Jack Lee

NOV 10 2021

Form BIR 3.1  
(Rev. 9-22-98)  
DT-0080

Bridge Location No. 49 - SR087 - 2076  
Co. Route Log Mile

Date \_\_\_\_\_

### PERFORMANCE EVALUATION

Time of Day Inspected 3:00 p.m. Weather Conditions 70° F ± Sunny  
Vehicles Observed All types

### LIVE LOAD BEHAVIOR

Substructure	YES	NO	Comments
Horiz./ Vert. Defl.	( )	(X)	
Vibration	( )	(X)	
Superstructure			
Horiz./ Vert. Defl.	( )	(X)	
Vibration	( )	(X)	

### APPROACH

	Rating	Comments
Alignment	(G) F P C	
Slab	G F P C	
Joints	G F P C	
Pavement	G (F) P C	
Embankment	(G) F P C	
Drains	G F P C	

### TRAFFIC SAFETY FEATURES

	Rating	STANDARD/ SUB-STANDARD	Comments
Bridgerailing	(G) F P C	( ) (X)	
Transitions	G F P C	( ) ( )	
Guardrail	G (F) P C	( ) (X)	
Guardrail Terminal	G (F) P C	(X) ( )	

### SIGNING

	YES	NO	NEEDED	Weight Limit Posted
Paddleboards	(X)	( )	( )	YES (X) NO ( )
Vertical Clearance (<14'-6")	( )	(X)	( )	Gross..... Tons
NARROW ( )	( )	(X)	( )	2 Axle..... <u>40</u> Tons
ONE LANE BRIDGE ( )	( )	(X)	( )	3 or more Axles.. <u>40</u> Tons

Other Signs or Plaques: None

Comments Regarding any Problems with Signing: 2 Paddleboards on App #2 only



NOV 10 2021

Form BIR 3.2  
(Rev. 9-22-98)  
DT-0081

Bridge Location No. 49 - SR087 - 2076  
Co. Route Log Mile

Date \_\_\_\_\_

**DECK**

	Rating				Comments
Wearing Surface	(G)	F	P	C	
Deck - Structural Condition	G	F	P	C	
Curbs	(G)	F	P	C	
Median	G	F	P	C	
Sidewalks	G	F	P	C	
Parapet	G	F	P	C	
Railing	(G)	F	P	C	
Paint	G	F	P	C	
Drains	G	F	(P)	C	All drains (043)
Lighting Standards	G	F	P	C	
Utilities	G	F	P	C	
Joint Leakage	G	F	P	C	
Expansion Joints	G	F	P	C	

**SUPERSTRUCTURE**

Bearing Devices	G	F	P	C	
Beams	G	F	P	C	
Girders	G	F	P	C	
P C C S	G	(F)	P	C	
BOLTS (PCCS)	(G)	F	P	C	
Floor Beams	G	F	P	C	
Stringers	G	F	P	C	
Diaphragms	G	F	P	C	
Bracing	G	F	P	C	
Trusses - General	G	F	P	C	
Portals	G	F	P	C	
Bracing	G	F	P	C	
Paint	G	F	P	C	
Alignment of Members	(G)	F	P	C	

**TEXTURE COAT**

Condition Rating	G	F	P	C	Fading	G	F	P	C
Overall Appearance	G	F	P	C	Needs Spot Painting	YES ( ) NO ( )			
Staining Rating	G	F	P	C	Needs Repainting	YES ( ) NO ( )			
Comments					Scaling Rating	G	F	P	C
RECOMMENDATIONS:					CLEAN SEAL JOINTS ( )				
					CLEAN DRAINS (X)				

NOV 10 2021

Form BIR 3.3  
(Rev. 9-22-98)  
DT-0082

Bridge Location No. 49 - SR087 - 2076  
Co. Route Log Mile

Date \_\_\_\_\_

**SUBSTRUCTURE**

**ABUTMENTS**

	Rating	Comments	PILE(S)	ABUTMENT
Caps	G <u>F</u> P C	_____	_____	_____
Breastwall	G <u>F</u> P C	_____	_____	_____
Wings	G <u>F</u> P C	_____	_____	_____
Backwall	G F P C	_____	_____	_____
Plumb	G <u>F</u> P C	_____	_____	_____
Footing	G F P C	_____	_____	_____
Piles	G <u>F</u> P C	_____	_____	_____
Embankment	G <u>F</u> P C	_____	_____	_____
Bearing Ret. wall	G <u>F</u> P C	_____	_____	_____
Slope Paving	G F P C	_____	_____	_____
Rip Rap	G F P C	_____	_____	_____
Earthquake Devices	G F P C	_____	_____	_____

**PIERS**

		PILE(S)	PIER
Caps	G F P C	_____	_____
Columns	G F P C	_____	_____
Plumb	G F P C	_____	_____
Footings	G F P C	_____	_____
Piles	G F P C	_____	_____
Bearing	G F P C	_____	_____
Web	G F P C	_____	_____
Earthquake Devices	G F P C	_____	_____

**BENTS**

		PILE(S)	BENT
Caps	G F P C	_____	_____
Columns	G F P C	_____	_____
Plumb	G F P C	_____	_____
Footings	G F P C	_____	_____
Piles	G F P C	_____	_____
Bearing	G F P C	_____	_____
Bracing	G F P C	_____	_____
Earthquake Devices	G F P C	_____	_____

Piles Need Replacement: NO (X) YES ( ) \_\_\_\_\_  
 CUT VEGETATION NO (X) YES ( ) \_\_\_\_\_  
 CLEAR DRIFT NO (X) YES ( ) \_\_\_\_\_

RECOMMENDATIONS: \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

NOV 10 2021

Form BIR 3.8

(Rev. 9-22-98)

DT-1508

Bridge Location No. 49 - SR087 - 2076

Co.      Route      Log Mile

Date \_\_\_\_\_

**STREAM CHANNEL DATA AND CONDITIONS**

Stream Crossing: DRAINAGE DITCH

- I. 1. Type of bed material? Sand & Silt
2. Has channel shifted? YES ( ) NO (X) NOT APPARENT ( )
3. Condition of rip-rap? G F P C Est. % failed \_\_\_\_\_ % N/A (X)
4. Overall condition of channel? G (F) P C
5. Item 61 - Code values 0 thru 9 according to the recording  
and coding guide currently in effect: 6
6. Underwater diver inspection recommended? YES ( ) NO (X)  
If yes, why? \_\_\_\_\_
- II. Channel and bank stability conditions: (check if applicable)
1. Steep bank conditions: - Failures upstream ( ) Failures downstream ( )
2. Moderate bank erosion (X)
3. Bank vegetation: a. low growth ( ) b. large timber ( ) c. clear banks ( )  
d. dead trees upstream (X) e. dead trees downstream (X)
4. Sediment or gravel accumulation: YES (X) NO ( ) UNKNOWN ( )
5. Channel altered or straightened: YES ( ) NO ( ) UNKNOWN ( )
6. Stable conditions: a. live growth (X) b. bedrock ( )  
c. boulders ( ) d. flat slopes ( $\leq 2:1$ ) ( )
- III. Waterway adequacy and debris characteristics: (check if applicable)
1. Bridge deck elevations:
- a. level with approach roadway. .... (X)
- b. higher than approach roadway. .... ( )
- c. roadway approach  $\geq 2$  ft. above natural ground line. . (X)
2. Abutment encroaches into channel. .... ( )
3. Large scour (blowhole) under bridge. .... ( )
4. Indications that flood waters overtop bridge:  
NO (X) YES ( ) OCCASIONALLY ( ) FREQUENTLY ( ) UNKNOWN ( )
5. Debris characteristics:
- a. debris/drift present YES (X) NO ( )
- b. debris/drift likely to accumulate YES (X) NO ( )
- c. dead trees upstream (X) dead trees downstream (X)

IV. Comments: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**SPECIAL INSPECTION DATA - FOR REASONS OTHER THAN FC OR SCOUR**

- I. Does this bridge need a special inspection? YES ( ) NO (X)
- II. Reason for special inspection: \_\_\_\_\_  
\_\_\_\_\_



Inspection Team's Summary

Bridge Location No. 49 - SR087 - 20.76

Inspection Date 11/10/21

Bridge Rating Fair

This is a 1 span p.c.c.s. & timber bridge with metal bridge rails,  
metal approach rails, 2 paddle boards on approach # 2 only &  
40 ton weight limit signs on both approaches.

Approach roadway has up to 1/16" cracks, light settlement &  
patched areas.

Drains are filled with debris.

The superstructure has up to 1/16" cracks & spalling.

The substructure has light to medium weathering & up to 1/4"  
checks.

Jaylan Cox

INSPECTOR


CROSS SECTION: YES ☐ NO ☒

BRM: YES ☒ NO ☐

NOV 10 2021

BR. NO. 49 87 20.76 SK. 90°

SPAN NO. 1




ELEMENT	RATING	COMMENT
TOP DECK	(G) F P C	
RAILS & POST	(G) F P C	
PAINT	G F P C	
DRAINS	G F (P) C	filled w/debris
JOINTS	G F P C	
CURBS	(G) F P C	

BRIDGE NO. 49 87 20.712

SKEW 90°

NOV 10 2021  
SPAN NO. 1

9 PRECAST CONCRETE SLABS



Element	Rating	Comment
SLAB	A <u>G</u> F P C	See ①
	B <u>G</u> F P C	
	C <u>G</u> <u>F</u> P C	See ②
	D <u>G</u> <u>F</u> P C	upto 1/8" cracks
	E <u>G</u> F P C	
	F <u>G</u> F P C	
	G <u>G</u> F P C	See ①
	H <u>G</u> F P C	
BOLTS	<u>G</u> F P C	
Btm Deck		

① Spalling 5" dia x 1/8" d  
② Spalling 1" w x 1/2" x 3/4" d



Date: \_\_\_\_\_

Pg. # \_\_\_\_\_ of \_\_\_\_\_

DATE 12/30/19


\_\_\_\_\_ TOP OF CAP TO TOP OF WATER: \_\_\_\_\_ RIP-RAP: YES: ( ) NO: ☒   
 \_\_\_\_\_ 100.00' UPSTREAM: \_\_\_\_\_ @ ABUTMENTS: \_\_\_\_\_   
 \_\_\_\_\_ THRU STRUCTURE: \_\_\_\_\_ @ BENTS/PIERS: \_\_\_\_\_   
 \_\_\_\_\_ 100.00' DOWNSTREAM: \_\_\_\_\_ UPSTREAM ☐ \_\_\_\_\_   
 DOWNSTREAM ☐ \_\_\_\_\_

COMMENTS: \_\_\_\_\_

NOV 10 2021

BR. NO. 49 87 20, 173

ABUT. NO. 1



LOOKING Back  $\odot$   $3\frac{1}{4}$ " shum


$\odot$   $3\frac{1}{2}$ "  $\odot$   $4\frac{1}{2}$ "  $\odot$   $14\frac{1}{2}$ "

ELEMENT	RATING	COMMENT
CAP	G F P C	Med. weathering
PILING	G F P C	Med. weathering
BREASTWALL	G F P C	Med. weathering
WINGS & PILE	G F P C	Med. weathering
EMB.	G F P C	Light growth
VEG.	G F P C	
	G F P C	
	G F P C	

NOV 10 2021

BR. NO. 49 87 2017

ABUT. NO. 2



LOOKING Ahead

① Splinter 1' w 3" tail

②  
13" 14 13 15

ELEMENT	RATING	COMMENT
CAP	G F P C	① Light to med event bearing
PILING	G F P C	med. weathering
BREASTWALL	G F P C	light weathering
WINGS & PILE	G F P C	E-17 piles up to 4' out under ②
FLUMES	G F P C	about in channel cap
VEG.	G F P C	light to med. event bearing
CH	G F P C	splinter 2.5 high 6' w 1/2" tail
C	G F P C	1/4" ch/c/2
F	F	



<u>49S80460003</u>	<u>49</u>	<u>SR087</u>	<u>2076</u>	<u>          </u>	SKEW: <u>90</u>
BRIDGE NO.:	CO.	ROUTE	L.M.	L/R	No. of Spans: 1
					No. of Approach Spans:


Direction of Route



A1

A2

F = FIXED  
E = EXPANSION  
S = SIMPLE  
C = CONTINUOUS



NOV 10 2021

Your Agency Name

Your Office Name

Your Department Name

## Structure Inventory and Appraisal Sheet (English Units)

### ELEMENT CONDITION STATE DATA

Str Unit	Elm/Env	Description	Unit	Total Qty	% In 1	Qty. St. 1	% In 2	Qty. St. 2	% In 3	Qty. St. 3	% In 4	Qty. St. 4
0	12/3	Re Concrete Deck	sq.ft	815.00	100%	815.00	0%	0.00	0%	0.00	0%	0.00
0	510/3	Wearing Surfaces	sq.ft	782.00	100%	782.00	0%	0.00	0%	0.00	0%	0.00
0	116/3	Re Conc Stringer	ft	224.00	98%	219.00	2%	5.00	0%	0.00	0%	0.00
0	1080/3	Delamination/Spall/Patched Area	ft	2.00	0%	0.00	100%	2.00	0%	0.00	0%	0.00
0	1130/3	Cracking (RC and Other)	ft	3.00	0%	0.00	100%	3.00	0%	0.00	0%	0.00
0	216/3	Timber Abutment	ft	62.00	100%	62.00	0%	0.00	0%	0.00	0%	0.00
0	330/3	Metal Bridge Railing	ft	56.00	100%	56.00	0%	0.00	0%	0.00	0%	0.00