




Latitude:35.80540, Longitude:-86.85062

Region 03, 94 - Williamson County

Team Leader: Korbin Hinson

Inspectors: Sean Bonner, Layton Breithaupt, Michael Cresap



I-65 Crossing I65 / SR106 & HARPETH RV

35.80540, -86.85062

90 - LAST INSPECTION DATE 02/14/2025

10 - MIN. V.C. OVER DECK 99.99 FT.
(ROADWAY + SHOULDERS)

520 - MIN. V.C. OVER DECK 99.990 FT.
(EXCLUDES SHOULDERS)

36 - TRAFFIC SAFETY FEATURES

Br. Rail	Trans.	Appr. Rail	Terminal	SPEED LIM.
0	0	0	0	70

41 - STRC OPEN/CLOSED/POSTED A

58 - DECK 5

59 - SUPERSTRUCTURE 6

60 - SUBSTRUCTURE 4

61 - CHANL/CHANL PROTECTION 6


62 - CULVERT AND RETAIN WALL N

71 - WATERWAY ADEQUACY 6

72 - APPROACH RDWY ALIGNMENT 8

521 - OVERALL CONDITION 3 - Poor

16 - LATITUDE 35.805400
17 - LONGITUDE -86.850617



TEAM LEADER SIGNATURE

N NOT APPLICABLE

9 EXCELLENT CONDITION

8 VERY GOOD CONDITION - NO PROBLEMS NOTED.

7 GOOD CONDITION - SOME MINOR PROBLEMS.

6 SATISFACTORY CONDITION - MINOR DETERIORATION OF STRUCTURAL ELEMENTS.

5 FAIR CONDITION - ALL PRIMARY STRUCTURAL ELEMENTS ARE SOUND BUT MAY HAVE MINOR SECTION LOSS, CRACKING, SPALLING OR SCOUR.

4 POOR CONDITION - ADVANCED SECTION LOSS, DETERIORATION, SPALLING OR SCOUR.

3 SERIOUS CONDITION - LOSS OF SECTION, DETERIORATION, SPALLING OR SCOUR HAVE SERIOUSLY AFFECTED PRIMARY STRUCTURAL COMPONENTS. LOCAL FAILURES ARE POSSIBLE. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT.

2 CRITICAL CONDITION - ADVANCED DETERIORATION OF PRIMARY STRUCTURAL ELEMENTS. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT OR SCOUR MAY HAVE REMOVED SUBSTRUCTURE SUPPORT. UNLESS CLOSELY MONITORED IT MAY BE NECESSARY TO CLOSE THE BRIDGE UNTIL CORRECTIVE ACTION IS TAKEN.

1 "IMMINENT" FAILURE CONDITION - MAJOR DETERIORATION OR SECTION LOSS PRESENT IN CRITICAL STRUCTURAL COMPONENTS OR OBVIOUS VERTICAL OR HORIZONTAL MOVEMENT AFFECTING STRUCTURAL STABILITY. BRIDGE IS CLOSED TO TRAFFIC BUT CORRECTIVE ACTION MAY PUT IT BACK IN LIGHT SERVICE.

0 FAILED CONDITION - OUT OF SERVICE AND BEYOND CORREC

IDENTIFICATION	
(1) State Names	47 - Tennessee
(8) Structure Number	94I00650006
(5) Inventory Route	1
(2) Highway Agency District	Region 3
(3) County Code	94 - Williamson
(4) Place Code	00000
(6) Features Intersected	I65 / SR106 & HARPETH RV
(7) Facility Carried	I65
(9) Location	3.8 M S JCT SR248&SR106
(11) Mile Point	4.790 mi
(12) Base Highway Network	Yes
(13) LRS Inventory Rte & Subrte	94I0065001
(16) Latitude	35.805400
(17) Longitude	-86.850617
(98) Border Bridge State Code	
(99) Border Bridge Structure No.	
STRUCTURE TYPE AND MATERIAL	
(43) Main Structure Type	52
Material	5 - Prestressed concrete *
Type	2 - Stringer/Multi-beam or girder
(44) Approach Structure Type	00
Material	0 - Other / None
Type	0 - Other / None
(45) No. of Spans in Main Unit	4
(46) No. of Approach Spans	0
(107) Deck Structure Type	1 - Concrete Cast-in-Place
(108) Wearing Surface/Protective System	
Type of Wearing Surface	6 - Bituminous
Type of Membrane	0 - None
Type of Deck Protection	0 - None
AGE AND SERVICE	
(27) Year Built	1963
(106) Year Reconstructed	1979
(42) Type of Service	16
On	1 - Highway
Under	6 - Highway-waterway
(28) Lane	
On	2
Under	2
(29) Average Daily Traffic	94031
(30) Year of ADT	2021
(109) Truck ADT	7 %
(19) Bypass, Detour Length	1 mi
GEOMETRIC DATA	
(48) Length of Maximum Span	52.8 ft
(49) Structure Length	193.9 ft
(50) Curb or Sidewalk Width	
Left	0.0 ft
Right	0.0 ft
(51) Bridge Roadway Width Curb to Curb	40.4 ft
(52) Deck Width Out to Out	44.0 ft
(32) Approach Roadway Width (W/Shoulders)	40.4 ft
(33) Bridge Median	1 - Open median
(34) Skew	70 Deg
(35) Structure Flared	0 - No flare
(10) Inventory Route Min Vert Clear	99.99 ft
(47) Inventory Route Total Horiz Clear	40.4 ft
(53) Min Vert Clear Over Bridge Rdwy	99.99 ft
(54) Min Vert Underclear	19.58 ft
Ref:	
(55) Min Lat Underclear RT	8.0 ft
Ref:	
(56) Min Lat Underclear LT	0.0 ft
NAVIGATION DATA	
(38) Navigation Control	0 - No navigation control on w
(111) Pier Protection	
(39) Navigation Vertical Clearance	0.0 ft
(116) Vert-Lift Bridge Nav Min Vert Clear	ft
(40) Navigation Horizontal Clearance	0.0 ft

CLASSIFICATION	
(112) NBIS Bridge Length	Y
(104) Highway System	1
(26) Functional Class	11 - Urban Principal Arterial
(100) Defense Highway	1 - The inventory route is on
(101) Parallel Structure	L - The left structure of para
(102) Direction of Traffic	1 - way traffic
(103) Temporary Structure	
(105) Federal Lands Highways	0 - N/A
(110) Designated National Network	1 - The inventory route is par
(20) Toll	3 - On free road. The structu
(21) Maintain	1 - State Highway Agency
(22) Owner	1 - State Highway Agency
(37) Historical Significance	4 - Historical significance is
CONDITION	
(58) Deck	5
(59) Superstructure	6
(60) Substructure	4
(61) Channel & Channel Protection	6
(62) Culverts	N
LOAD RATING AND POSTING	
(31) Design Load	6 - MS 18+Mod / HS 20+Mod
(63) Operating Rating Method	8
(64) Operating Rating	
Type	8 - Load and Resistance Factor Rating (LRF
Rating	31.75
(65) Inventory Rating Method	8 - Load and Resistance Factor
(66) Inventory Rating	
Type	
Rating	18.14
(70) Bridge Posting	5 - Equal to or above legal loads
(41) Structure Open/Posted/Closed	A - Open, no restriction
APPRAISAL	
(67) Structural Evaluation	4
(68) Deck Geometry	8
(69) Clearances, Vertical/Horizontal	5
(71) Waterway Adequacy	6
(72) Approach Roadway Alignment	8
(36A) Bridge Railings	0 - Inspected feature does not meet
(36B) Transitions	0 - Inspected feature does not meet
(36C) Approach Guardrail	0 - Inspected feature does not meet
(36D) Approach Guardrail Ends	0 - Inspected feature does not meet
(113) Scour Critical Bridges	8 - Bridge foundations determined t
PROPOSED IMPROVEMENTS	
(75) Type of Work	35 - Bridge rehabilitation bec
(76) Length of Structure Improvement	194.9 ft
(94) Bridge Improvement Cost	\$ 1269
(95) Roadway Improvement Cost	\$ 127
(96) Total Project Cost	\$ 1904
(97) Year of Improvement Cost Estimate	2021
(114) Future ADT	134918
(115) Year of Future ADT	2041

INSPECTIONS *			
(90) Inspection Date	02/14/2025		
(91) Frequency	24		
(92) Critical Feature Inspection	Done	Freq. (Mon)	Date
A: Fracture Critical Detail	No		
B: Underwater Inspection	No		
C: Other Special Inspection	No		
* The inspection date and frequency information in this box contains the current NBI date and frequency information. Please refer to the report header for the date this inspection was conducted.			

PERFORMANCE EVALUATION

Time of Day Inspected 1:30 PM

Weather Conditions Sunny and 38 Degrees

Vehicles Observed All Types

LIVE LOAD BEHAVIOR

Sub Horiz./ Vert. Defl (No)

Sub Vibration (No)

Super Horiz./ Vert. Defl (No)

Super Vibration (No)

APPROACH

Alignment (Good)

Pavement (Fair)

 Approach 1 asphalt exhibits isolated wide cracks and an isolated patched pothole.
 Approach 2 asphalt exhibits isolated wide cracks and an isolated moderate pothole.

Embankment (Good)

Approach Drains (Poor)

Approach 2 left concrete embankment drain is cracked and heavily undermined.

TRAFFIC SAFETY FEATURES

Bridge Railing Rating (Fair)

The parapet height is substandard. Both parapets in all spans exhibit widespread vertical hairline cracks spaced at 1'-6" on average. There is a spall with exposed rebar in the left parapet over Abutment 1. The parapet over the left wingwall of Abutment 2 exhibits a wide vertical crack. The right parapet in Span 4 near Bent 3 exhibits wide vertical cracking.

Transitions Rating (Good)

Both Approach 1 and 2 transitions are substandard with metal blockouts.

Guardrail Rating (Good)

Both Approach 1 and 2 guardrail is substandard with metal blockouts.

Guardrail Terminal Rating (Good)

SIGNS POSTED ON ROUTE

Paddleboards Yes

Vertical Clearance (<14'-6") No

Posted Height

Narrow Bridge Signs No

One Lane Bridge Signs No

Other Signs or Plaques NONE

Weight Limit Posted Not Needed

Gross Tons

Single-unit Vehicle Tons

Multi-unit Vehicle Tons

564 Assigned Bridge Name

ATTACHED SIGNS

Sign No	Location	Text on Sign	Noted Defects
---------	----------	--------------	---------------

DECK

Wearing Surface Type		Asphalt	Wearing Surface Depth	3
Wearing Surface	(Good)	An asphalt overlay is present over the bridge deck. The right shoulder in all spans has widespread vegetation growth. Span 2 has a moderate pothole and a gouge in the wearing surface near Bent 2. Span 4 has a full-length patch that is sound condition.		
Deck - Structural Condition	(Fair)	Span 1 exhibits isolated moderate spalls with exposed rebar and isolated moderate cracking in Bay C. Span 2 exhibits isolated moderate spalls with exposed rebar, delaminations, and insignificant cracking in Bays C and E. Span 3 exhibits some delaminations, isolated moderate spalls with exposed rebar, and isolated sound patches in Bay E. There are also some insignificant cracks in the right overhang of Span 3. There is an area of water leakage in the left overhang of Span 3. There are no defects noted in Span 4.		
Parapet	(Fair)	The parapet height is substandard. Both parapets in all spans exhibit widespread vertical hairline cracks spaced at 1'-6" on average. There is a spall with exposed rebar in the left parapet over Abutment 1. The parapet over the left wingwall of Abutment 2 exhibits a wide vertical crack. The right parapet in Span 4 near Bent 3 exhibits wide vertical cracking.		

SUPERSTRUCTURE

Bearing Devices	(Good)	Elastomeric bearing pads.
Girders	(Good)	Span 1 Beam B exhibits isolated moderate spalling on the top flange. Span 3 Beam B exhibits isolated moderate spalling on the top flange. Span 3 Beam F has a small area of delamination on the top flange.
Diaphragms	(Fair)	Intermediate diaphragms are all in Good condition. The diaphragm over Bent 1 has isolated areas of delamination. the diaphragm over Bent 2 has spalls with exposed rebar, areas of delamination, and moderate cracks. The diaphragm over Bent 3 has spalls with exposed rebar and areas of delamination.
Alignment of Members	(Good)	

TEXTURE COAT

ABUTMENTS

Abutment Caps	(Poor)	Abutment 1 cap exhibits widespread large delaminations and isolated large spalls with exposed rebar. Abutment 2 cap has a wide crack that runs the entire length of the cap and widespread moderate spalls with exposed rebar. There are also areas of delamination, honeycombing, and heavy water staining in the Abutment 2 cap.
Abutment Wings	(Fair)	The left wingwall at Abutment 2 has isolated spalling and is covered with vegetation. The right wingwall at Abutment 2 has isolated wide cracks.
Abutment Plumb	(Good)	
Abutment Piles	(Fair)	Abutment 1 exhibits 1 exposed pile with surface corrosion due to undermining. No section loss is present in the pile.
Abutment Embankment	(Poor)	Abutment 1 is exhibiting widespread undermining up to 2'-6"D underneath the cap with 1 exposed pile. There is no slope protection at Abutment 1.
Abutment Slope Paving	(Good)	There is concrete slope paving present at Abutment 1 only.

PIERS

BENTS

Bent Caps	(Poor)	Bent 1 cap exhibits isolated wide cracking and widespread moderate spall with exposed rebar. Bent 2 cap exhibits some moderate spalls with exposed rebar and widespread delamination. Bent 3 cap exhibits isolated wide cracking, isolated areas of honeycombing, and widespread areas of delamination.
Bent Columns	(Fair)	Bent 1 Column A has delaminated areas. Bent 1 Column B exhibits widespread moderate spalls. Bent 1 Column C has vegetation growth covering it. Bent 2 Column A has a large patch with hairline cracks in it along with hairline map cracking. Bent 2 Column B exhibits widespread delamination, isolated moderate spalls, and insignificant cracks. Bent 3 Column A exhibits widespread moderate cracking. Bent 3 Column B has isolated wide cracking. Bent 3 Column C has isolated moderate spalls.
Bent Plumb	(Good)	
Bent Footing	(Not Visible)	

Inspection Team's Summary

Bridge 94I00650006 is a 4-span bridge on a 70 degree skew composed of a cast-in-place concrete deck supported by prestressed AASHTO Type II beams. The bridge has a total length of 193'-10.25", an out-to-out width of 44'-0", a roadway width of 40'-5", and carries 2 lanes of traffic. The maximum span length is 52'-10.125". On February 14, 2025, a Michael Baker inspection team performed a 1-day Routine Inspection on the bridge. Korbin Hinson and Sean Bonner inspected the top of deck, superstructure, and substructure from the ground. The weather conditions were sunny and 38 degrees.

The approach roadway was in overall Fair condition. The alignment at both Approach 1 and 2 was Good. The approach asphalt was fair. Approach 1 asphalt exhibits an isolated wide crack and a patched pothole. Approach 2 asphalt exhibits an isolated wide crack and an isolated moderate pothole. The approach embankment is in Good condition. The approach drains are in Poor condition. The drain on the left at Approach 2 is cracked and heavily undermined. The transitions, guardrails, and terminals are in Good condition, but the metal blockouts do not meet the current standards.

The deck is in overall Fair condition. An asphalt overlay is present over the bridge deck. The right shoulder in all spans has widespread vegetation growth. Span 2 has a moderate pothole and a gouge in the wearing surface near Bent 2. Span 4 has a full-length patch that is sound condition. The bottom of the deck was rated Fair. Span 1 exhibits isolated moderate spalls with exposed rebar and isolated moderate cracking in Bay C. Span 2 exhibits isolated moderate spalls with exposed rebar, delaminations, and insignificant cracking in Bays C and E. Span 3 exhibits some delaminations, isolated moderate spalls with exposed rebar, and isolated sound patches in Bay E. There are also some insignificant cracks in the right overhang of Span 3. There is an area of water leakage in the left overhang of Span 3. There are no defects noted in Span 4. The parapet was rated Fair. The parapet height is substandard. Both parapets in all spans exhibit widespread vertical hairline cracks spaced at 1'-6" on average. There is a spall with exposed rebar in the left parapet over Abutment 1. The parapet over the left wingwall of Abutment 2 exhibits a wide vertical crack. The right parapet in Span 4 near Bent 3 exhibits wide vertical cracking.

The superstructure is in overall Fair condition. The superstructure consists of pre-stressed concrete beams, which are in Good condition. Span 1 Beam B exhibits isolated moderate spalling on the top flange. Span 3 Beam B exhibits isolated moderate spalling on the top flange. Span 3 Beam F has a small area of delamination on the top flange. The concrete diaphragms are in Fair condition. Intermediate diaphragms are all in Good condition. The diaphragm over Bent 1 has isolated areas of delamination. the diaphragm over Bent 2 has spalls with exposed rebar, areas of delamination, and moderate cracks. The diaphragm over Bent 3 has spalls with exposed rebar and areas of delamination. The elastomeric bearing pads are in Good condition.

The substructure is in overall Poor condition. The abutment caps are in Poor condition. Abutment 1 cap exhibits widespread large delaminations and isolated large spalls with exposed rebar. Abutment 2 cap has a wide crack that runs the entire length of the cap and widespread moderate spalls with exposed rebar. There are also areas of delamination, honeycombing, and

heavy water staining in the Abutment 2 cap. The wingwalls are in Fair condition. The left wingwall at Abutment 2 has isolated spalling and is covered with vegetation. The right wingwall at Abutment 2 has isolated wide cracks. The abutment piles are in Fair condition. Abutment 1 exhibits 1 exposed pile with surface corrosion due to undermining. No section loss is present in the pile. The abutment embankment is in Poor condition. Abutment 1 is exhibiting widespread undermining up to 2'-6"D underneath the cap with 1 exposed pile. There is no slope protection at Abutment 1. The abutment slope paving is in Good condition. There is concrete slope paving present at Abutment 1 only. The bent caps are Poor and the bent columns are Fair. Bent 1 cap exhibits isolated wide cracking and widespread moderate spall with exposed rebar. Bent 2 cap exhibits some moderate spalls with exposed rebar and widespread delamination. Bent 3 cap exhibits isolated wide cracking, isolated areas of honeycombing, and widespread areas of delamination. Bent 1 Column A has delaminated areas. Bent 1 Column B exhibits widespread moderate spalls. Bent 1 Column C has vegetation growth covering it. Bent 2 Column A has a large patch with hairline cracks in it along with hairline map cracking. Bent 2 Column B exhibits widespread delamination, isolated moderate spalls, and insignificant cracks. Bent 3 Column A exhibits widespread moderate cracking. Bent 3 Column B has isolated wide cracking. Bent 3 Column C has isolated moderate spalls.

The overall condition of the Channel is Fair. At the time of inspection, the channel opening was mostly clear of debris; however, large amounts of timber have been cut on the Abutment 1 slope, and timber debris now aligns the bank on the upstream side of the bridge.

The bridge was not posted during the 02/14/2025 inspection. An evaluation is requested for potential posting due to the Substructure's updated condition at the Bent 1 cap and Abutment 2 cap.

General Inspection Comment

The bridge was not posted during the 02/14/2025 inspection. An evaluation is requested for potential posting due to the Substructure's updated condition at the Bent 1 cap and Abutment 2 cap.

HQ notes to TL

ELEMENTS	DESCRIPTION	UNITS	TOTAL	CS1	CS2	CS3	CS4
12	Re Concrete Deck	SF	8575	8435	115	25	0
1080	Delamination/Spall/Patched Area	SF	59	0	34	25	0
1120	Efflorescence/Rust Staining	SF	65	0	65	0	0
1130	Cracking (RC and Other)	SF	16	0	16	0	0
510	Wearing Surfaces	SF	8185	8145	39	1	0
3220	Crack (Wearing Surface)	SF	40	0	39	1	0
(12) Element record added 2/6/2017							
109	Pre Opn Conc Girder/Beam	LF	1170	1163	2	5	0
1080	Delamination/Spall/Patched Area	LF	7	0	2	5	0
(109) Element record added 2/6/2017							
205	Re Conc Column	EA	9	2	5	2	0
1080	Delamination/Spall/Patched Area	EA	7	0	5	2	0
(205) Element record added 2/7/2019							
215	Re Conc Abutment	LF	95	5	32	58	0
1080	Delamination/Spall/Patched Area	LF	58	0	32	26	0
1130	Cracking (RC and Other)	LF	32	0	0	32	0
(215) Element record added 2/6/2017							
234	Re Conc Pier Cap	LF	111	31	34	46	0
1080	Delamination/Spall/Patched Area	LF	72	0	34	38	0
1130	Cracking (RC and Other)	LF	8	0	0	8	0
(234) Element record added 2/6/2017							
310	Elastomeric Bearing	EA	46	46	0	0	0
(310) Element record added 2/6/2017							
331	Re Conc Bridge Railing	LF	390	351	0	39	0
1130	Cracking (RC and Other)	LF	39	0	0	39	0
(331) Element record added 2/6/2017							

STREAM CHANNEL DATA AND CONDITIONS

Stream Crossing	SR 106 & West Harpeth River		
Type of bed material	Bedrock		
Has channel shifted?	No		
Condition of rip-rap	N/A	Est. % failed	%
Overall condition of channel	Fair		
Underwater Inspection Req?	No		
Why UW required?			

Channel and bank stability conditions

Steep bank cond - Failure US	No	Moderate Bank Erosion	Yes
Steep bank cond - Failure DS	No	Sediment or Gravel Accumulation	No
Bank Vegetation:		Channel Altered or Straightened	No
Low Growth	Yes	Stable Conditions:	
Large Timber	Yes	Live Growth	Yes
Clear Banks	No	Bedrock	Yes
Dead Trees - US	Yes	Boulders	No
Dead Trees - DS	Yes	FlatSlopes (<=2:1)	No

Waterway adequacy and debris characteristics


Bridge deck elevations:		Large Scour Under Bridge	No
Level with Approach Roadway	Yes	Indications Flood Overtop Bridge	No
Higher than Approach Roadway	No	Debris / Drift - Present	Yes
Road Appr >2' Above Natural Ground	No	Debris / Drift - Likely to Accumulate	Yes
Abutment Encroaches into Channel	No		

Channel Profile Upstream

Benchmark height _____ Benchmark location _____ Measure to bottom of deck _____

Comment _____

Station	Distance	HI	Upstream
248+29	0		5.1
248+56	27		15.1
248+82	53		27.6
249+08	79		35
249+34	105		23.9
249+60	131		22.8
249+86	157		22.1
250+05	176		11.2
250+23	194		5.2




Channel Profile Downstream

Benchmark height _____ Benchmark location _____ Measured to bottom of deck _____

Comment _____

Station	Distance	HI	Downstream
248+29	0		5.3
248+56	27		17.3
248+82	53		30.1
249+08	79		35
249+34	105		24.1
249+60	131		22.5
249+86	157		21.4
250+05	176		11.2
250+23	194		5



Substructure Exposure

Last Exposure	Abut/Bent/Pier Number	Total height	Footing Thickness	Exposure
	Abutment 1			2.1
	Bent 1			26.9
	Bent 2			20.9
	Bent 3			18.9
	Abutment 2			2

Last Exposure Upstream

Last Exposure
Downstream

Top of cap to top of water

Upstream Distance

Upstream Depth

Thru structure

Downstream Distance

Downstream Depth

Rip-Rap

@ Abutment

@ Bents

@ Piers

Upstream

Downstream

Thru Structure

N

No

No

N

N

N

Equipment List

General Inspection

- ☒ Yes Pocket knife
☒ Yes Sounding/chipping hammer
☐ Chain drag
☒ Yes Range pole
☒ Yes 25' rod - depth and clearance

Visual Aid

- ☒ Yes Binoculars
☒ Yes Flashlight
☐ Magnifying glass
☐ Hand mirror

Cleaning

- ☐ Wisk broom
☐ Wire brush
☐ Flat bladed screwdriver
☐ Hand shovel
☐ Penetrating oil (WD-40, etc.)

Tools For Access

- ☒ Yes Ladders
☐ Rope
☒ Yes Waders
☐ Machete or bush axe

Comment

Tools For Measuring

- ☒ Yes Masonry/Wood Ruler
☒ Yes 6' Pocket Tape
☒ Yes 25' and 100' Tape
☐ Calipers
☒ Yes Thermometer
☒ Yes Carpenter's Level
☒ Yes String and Weighted line (plumb bob)

Special Purpose Equipment

- ☐ Reach All
☐ Bucket Truck
☐ Traffic control
☐ Boat
☐ Sonar depth finder
☐ Increment borer
☐ Survey equipment
☐ Safety Harness
☐ Climbing equipment
☐ Dye penetrant
☐ Drone
☐ Air Meter

Special Purpose Equipment

Reach-All Approval and Comments



Bridge number



Upstream right side elevation



Downstream left side elevation



Looking upstream from beneath bridge



Looking downstream from beneath bridge



US-431 looking forward on route



US-431 looking back on route



Approach 1 looking forward



Approach 1 looking back



Approach 2 looking forward



Approach 2 looking back



Approach 1 distortion in left side guardrail



Wide crack and patch at beginning of bridge



Wide crack in wearing surface at end of bridge



Top of deck looking forward



Top of deck looking back



Typical HL crack in both parapets all spans



Span 1 crack w/ eff in right overhang



Span 1 HL cracks w/ eff in Bay C



Span 1 delam in forward diaphragm



Span 1 spall w/ exposed rebar on left parapet over Abutment 1



Span 1 spall on left side top flg of Beam B



Span 1 spall w/ exposed rebar in Bay C over Abutment 1



Span 1 spall w/ exposed rebar in Bay C



Span 1 delam in Bay E over Abutment 1



Span 2 pothole in wearing surface



Span 2 gouge in wearing surface



Span 2 spalling w/ exposed rebar in forward diaphragms



Span 2 delams in Bay E



Span 2 delam and spall w/ exposed rebar in Bay E



Span 2 delam in Bay C



Span 2 spalling w/ exposed rebar and delams in back diaphragms



Spans 2 and 3 HL cracks w/ eff in right overhang over Bent 2



Span 3 mod cracks and delam in forward diaphragms



Span 3 delam in top flg left side of Beam F



Span 3 spall in top flg left side of Beam B



Span 3 delam and spall w/ exposed rebar in Bay E



Span 4 moderate cracks in right parapet



Span 4 spall w/ exposed rebar in back diaphragms



Span 4 delam and spalls in back diaphragms



Vegetation growth along right parapet entire bridge length



Span 2



Span 3



Span 4



Abutment 1



Bent 1 front



Bent 1 back



Bent 2 front



Bent 2 back



Bent 3 front



Bent 3 back



Abutment 2



Abutment 1 crack and spalls along construct. joint under Bay A



Abutment 1 delam on cap under Bay B



Abutment 1 whole face delam on cap under Beam B and delam and spall on cap under Bay A



Abutment 1 undermining of cap under Beam C



Abutment 1 HL cracks w/ eff on backwall under Bay C



Abutment 1 delam on cap under Bay C



Abutment 1 spall on backwall under Bay D



Abutment 1 delam on cap under Bay D



Abutment 1 undermining of cap w/ exposed pile w/ laminar corrosion under Bay E



Abutment 1 spall on backwall under Bay E



Abutment 1 delam on cap under Bay E



Abutment 1 delam on cap under right overhang



Abutment 1 spalls on backwall under right overhang



Abutment 1 cracks w/ hvly eff on backwall under right overhang



Bent 1 spall w/ exposed rebar on front of cap under Beam B



Bent 1 delam on front of cap under Beam C



Bent 1 spall w/ exposed rebar on underside of cap to the right of Column C



Bent 1 delam on front face of cap under Beam E



Bent 1 delam on front face of Column C



Bent 1 delam in cap front to the right of Column C



Bent 1 1/16" crack in back of cap



Bent 1 vegetation growth on Column A



Bent 1 delam in Column C



Bent 1 HL crack in Column C



Bent 1 moderate cracks at right end and bottom of cap



Bent 1 spalls w/ exposed rebar on right face of Column B



Bent 1 spalls w/ exp. rebar on back and bottom faces of cap



Bent 1 spall w/ exp. rebar on Column B



Bent 2 HL map cracking in right face of Column C



Bent 2 1/32" cracks in right face of Column C



Bent 2 spalls w/ exposed rebar in front face of cap



Bent 2 delam in front and left faces of Column B



Bent 2 delam in back face of Column B



Bent 2 1/32" crack and failed patch on right face of Column B



Bent 2 patch with HL cracks on back face of Column C



Bent 2 delam in front face of cap



Bent 2 delam in right face of Column B



Bent 2 delam in bottom of cap



Bent 2 delam in cap above column C



Bent 3 delams along top of cap between Beams C and E of Span 4



Bent 3 delam and HL crack in back of cap under Beam B



Bent 3 delam and honeycombing on back of cap between Columns B and C



Bent 3 HL map cracking in back of cap to the right of Column C



Bent 3 HL map cracking w/ iso 1/32" cracks in right face of Column C



Bent 3 delam in patch on underside of cap between Columns B and C



Bent 3 delam on underside of cap to the right of Column C



Bent 3 delam and moderate cracks on underside of cap between Columns A and B



Bent 3 delam on front of cap over Column A



Bent 3 mod crack through patch on front of cap



Abutment 2 1/16" crack w/ water leakage and staining in right wingwall



Abutment 2 heavy eff on backwall under right overhang



Abutment 2 spall on backwall under right overhang



Abutment 2 water leakage and staining of backwall and cap under right overhang



Abutment 2 spalling on top of cap under right overhang



Abutment 2 spalling w/ exposed rebar on cap under Beam E



Abutment 2 spalling w/ exposed rebar and delam of top of cap under Bay D



Abutment 2 delam on cap under Bay C



Abutment 2 spalling w/ exposed rebar and wide crack on cap under Bay C



Abutment 2 spalling and wide crack on cap under Bay B



Abutment 2 deep honeycombing and 1/16" crack on cap under Bay A



Abutment 2 spalls w/ exposed rebar in backwall of Bay A



Abutment 2 vegetation growth on left wingwall and backwall



Abutment 2 1/16" crack in parapet over left wingwall



Abutment 2 spall on corner of left wingwall and backwall



Abutment 2 undermining of left embankment drain



Abutment #2 failed left embankment drain



Abutment 1 bearing typical



Abutment 2 bearing typ

Maintenance Recommendations


525 - Repair List # 2

523 - Repair List Add Date 10/3/2019

524 - Repair List Revise Date 2/3/2021 1

Date Added	Recommendation	Priority
04/02/2002	REPAIR DIAPHRAGMS IN SPANS 1, 2 & 3	3
02/04/2021	REPAIR CAPBEAM AT ABUTMENT NO. 1 AND 2	2
02/04/2021	REPAIR COLUMNS "B" & "C" AT BENT NO. 1	3
02/04/2021	REPAIR CAPBEAM AT BENTS NO. 1 AND 2	2
02/21/2023	REPAIR APPROACH DRAIN AT APPROACH NO. 2, LEFT SIDE	3
02/21/2023	REPAIR EMBANKMENT SETTLEMENT AT ABUTMENT NO. 1	3
02/14/2025	Repair Cap and Columns A & B in Bent 3	3
02/14/2025	Repair Columns A & B in Bent 2	3
02/14/2025	Repair the backwalls at Abutments 1 and 2.	3


Br. No. 94-165-4.79 LT. LANE DATE: 02/14/2025
Underpass Clearance



Top Span No. 1

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile




W. SURFACE	GOOD	LIGHT VEGETATION GROWTH AT CURB
PARAPETS	FAIR	WIDESPREAD HAIRLINE CRACKS
DRAINS	POOR	PAVED OVER

Top Span No. 2

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile




W. SURFACE	FAIR	ISOLATED POTHOLE AND GOUGE
PARAPETS	FAIR	WIDESPREAD HAIRLINE CRACKS
DRAINS	POOR	PAVED OVER

Top Span No. 3

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile




W. SURFACE	GOOD	LIGHT VEGETATION GROWTH AT CURB
PARAPETS	FAIR	WIDESPREAD HAIRLINE CRACKS
DRAINS	POOR	PAVED OVER

Top Span No. 4

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile




W. SURFACE	FAIR	LARGE PATCH IN SOUND CONDITION
PARAPETS	FAIR	SOME WIDE CRACKS
DRAINS	POOR	PAVED OVER

Bottom Span No. 1

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile




DECK	FAIR	ISOLATED SPALLS WITH EXPOSED REBAR
		ISOLATED MODERATE CRACKING
BEAM	A	GOOD
	B	FAIR
	C	GOOD
	D	GOOD
	E	GOOD
	F	GOOD
DIAPHRAGMS		
BACK	N/A	ABUTMENT BACKWALL
INT.	GOOD	
AHEAD	GOOD	ISOLATED DELAMINATIONS

Bottom Span No. 2

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile




DECK	FAIR	ISOLATED MODERATE SPALLS
		SOME DELAMINATIONS
		SOME INSIGNIFICANT CRACKING
BEAM	A	GOOD
	B	GOOD
	C	GOOD
	D	GOOD
	E	GOOD
	F	GOOD
DIAPHRAGMS		
BACK	FAIR	SPALLING WITH EXPOSED REBAR
INT.	GOOD	
AHEAD	FAIR	SPALLING WITH EXPOSED REBAR AND DELAMS

Bottom Span No. 3

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile



DECK	FAIR	ISOLATED MODERATE SPALLS
		ISOLATED DELAMS & ISIGNIFICANT CRACKS
		ISOLATED SOUND PATCHES
BEAM	A	GOOD
	B	FAIR
	C	GOOD
	D	GOOD
	E	GOOD
	F	GOOD
		ISOLATED DELAMINATIONS
DIAPHRAGMS		
BACK	FAIR	MODERATE CRACKS AND DELAMS
INT.	GOOD	
AHEAD	GOOD	

Bottom Span No. 4

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile




DECK	GOOD	
BEAM	A	GOOD
	B	GOOD
	C	GOOD
	D	GOOD
	E	GOOD
DIAPHRAGMS		
BACK	FAIR	SPALLS WITH EXPOSED REBAR AND DELAMS
INT.	GOOD	
AHEAD	N/A	ABUTMENT BACKWALL

Abutment No. 1

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile




BEARINGS	GOOD	ELASTOMERIC
CAP	FAIR	WIDESPREAD LARGE DELAMINATIONS
		ISOLATED LARGE SPALL
LT WING	GOOD	
RT WING	GOOD	
SLOPE	POOR	UNPROTECTED SOIL GRADE W/ WIDESPREAD UNDERMINING
PILE	FAIR	1 EXPOSED PILE W/ SURFACE CORROSION
BACKWALL	FAIR	SOME DELAMS AND ISOLATED MODERATE SPALLS
		SOME INSIGNIFICANT CRACKING

BENT NO. 1

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile




CAP	POOR	ISOLATED WIDE CRACKING
		WIDESPREAD MODERATE SPALLS
COLUMN A	FAIR	DELAMINATIONS
B	POOR	WIDESPREAD MODERATE SPALLS
C	GOOD	VEGETATION GROWTH
BEARINGS	GOOD	ELASTOMERIC
FOOTINGS	N/V	

BENT NO. 2

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile




CAP	FAIR	SOME MODERATE SPALLS
		WIDESPREAD DELAMINATIONS
COLUMN A	FAIR	LARGE PATCH WITH HAIRLINE CRACKS
		HAIRLINE MAP CRACKING
B	FAIR	WIDESPREAD DELAMINATIONS
		ISOLATED MODERATE SPALLS AND INSIG CRACKS
C	GOOD	
BEARINGS	GOOD	ELASTOMERIC
FOOTINGS	N/V	

BENT NO. 3

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile




CAP	FAIR	ISOLATED WIDE CRACKING
		WIDESPREAD DELAMINATIONS
COLUMN A	FAIR	SOME MODERATE CRACKING
B	FAIR	ISOLATED WIDE CRACKING
C	FAIR	ISOLATED MODERATE SPALL
BEARINGS	GOOD	ELASTOMERIC
FOOTINGS	N/V	

Abutment No. 2

Date: 02/14/2025

Bridge Location No. 94 I-65 4.79 RT
County Route Log Mile



BEARINGS	GOOD	ELASTOMERIC
CAP	POOR	WIDE CRACK
		WIDESPREAD MODERATE SPALLS
LT WING	FAIR	ISOLATED SPALLING
		COVERED WITH VEGETATION
RT WING	FAIR	ISOLATED WIDE CRACK
SLOPE	GOOD	CONCRETE SLOPE PAVING
PILE	N/V	
BACKWALL	FAIR	SOME MODERATE SPALLS
		SOME MODERATE CRACKING