


Date: 08/20/03

Williamson County



Page 1 of 1

Co.	Route	Log Mile
-----	-------	----------

Facility Carried By: I65

-0- REPAIR BENT CAP NO. 1

-0- REPAIR COLUMN "B" AND "C" AT BENT NO. 1

REPAIR ABUTMENT CAP NO. 1

REPAIR DIAPHRAGMS IN SPANS NO. 1, 2, AND 3

Bridge Maintenance Recommendations

Page No. _____

Page 1 of 1

Bridge Location No.: 94 - I0065 - 4.79 L

Co. Route Log Mile

Bridge Number: 94I00650006

County: WILLIAMSON

Crossing: SR 106&HARPETH RIVER

Region: 03

Bridge Rating: FAIR

District: 31

Inspection Cycle: 15

Maint.Resp.: 01

Inspection Date: 8/16/01

Spec.Case: 0

Co.Seq: 01

Comments: -0-

Level of Service: 1

Number Main Spans: 004

Owner: 01

Number Appr Spans: 0000

Appr Rdwy (xxx ft): 038

Bridge Length (xxxxxx ft) 000194

Skew: 70

Curb-to-Curb (xxx.x ft): 0405

Type of Service: 16

Out-to-Out (xxx.x ft): 0440

Main Structure Type: 502

Item 500: 01

Appr Structure Type: 000

Facility Carried By: 165

Maintenance Recommendations:

Maintenance Completed

By / Date

-0- REPAIR BENT CAP NO. 1

-0- REPAIR COLUMN "B" AND "C" AT BENT NO. 1

REPAIR ABUTMENT CAP NO. 1

REPAIR DIAPHRAGMS IN SPANS NO. 1, 2, AND 3

BRIDGE MAINTENANCE RECOMMENDATIONS

BRIDGE SEQ. NO. : 94I00650006

BRIDGE NO. : 94 - I0065 - 0479 - L
OVER : I65/SR 106&HARPETH RIVER*

DATE : 09/02/99 BRIDGE RATING : FAIR COUNTY : Williamson
CO. SEQ. : 01 INSPECTION CYCLE : 14 MAINT DIST : 31
SPEC. CASE : 0 INSPECTION DATE : 08/23/99 REGION : 03

007 - FACILITY CARRIED BY STRUCT : I65
021 - MAINTENANCE RESPONSIBILITY : 01
022 - OWNER : 01
042 - TYPE OF SERVICE : 16
043 - STRUCTURE TYPE, MAIN : 502
044 - STRUCTURE TYPE, APPROACH : 000
045 - SPANS, MAIN UNIT : 004
046 - SPANS, APPROACH : 0000
049 - STRUCTURE LENGTH : 000194
032 - APPROACH ROADWAY WIDTH : 038
034 - SKEW : 70
051 - BRDG RDWY WID, CRB-TO-CRB : 0405
052 - DECK WIDTH, OUT-TO-OUT : 0440
500 - HWY OF THE INVENTORY ROUTE : 01

: MAINTENANCE & REPAIR RECOMMENDATIONS :

: MAINTENANCE COMPLETED :

1	REPAIR ABUT. CAP NO. 1	1BY__ DATE ____
2	REPAIR BENT CAP NO. 1,2, AND 3	2BY__ DATE ____
3	REPAIR COLUMN "B" AND "C" AT BENT NO. 1	3BY__ DATE ____
4	REPAIR COLUMN "B" AND "C" AT BENT NO. 2	4BY__ DATE ____
5	REPAIR COLUMN "B" AND "C" AT BENT NO. 3	5BY__ DATE ____
6	REPAIR DIAPHRAGMS IN SPANS NO. 1,2, AND 3	6BY__ DATE ____

: COMMENTS FOR BRIDGE SEQ. NO. : 94I00650006 :

COMPLETION NOTIFICATION : RETURN WITHIN 6 MONTHS OF INSPECTION DATE

MAINTENANCE ACTIVITIES ARE

--- COMPLETED (DATE) -----
--- PARTIALLY COMPLETE (DATE) -----
--- INCOMPLETE SCHEDULED FOR (DATE) -----

EXPLANATIONS AND COMMENTS:

TENNESSEE BRIDGE INSPECTION PROGRAM

SUMMARY OF EVALUATION

REV. 03-05-2003

BRIDGE ID NO: 94I00650006

LOCATION NO: 94 - I0065 - 4.79 L

(6A) CROSSING: I65 / SR106 & HARPETH RV

(505) METHOD OF ANALYSIS: LOAD FACTOR
METHOD

(548) RATING BASED ON: VIRTIS ANALYSIS - 9"
ASPHALT

LOAD RATINGS IN TONS

INVENTORY (503) H 18	(518B) HS 28
OPERATING (504) H 30	(519) HS 46

(549) EVALUATOR: MRJ

(522) EVAL. DATE: 4/18/2017

LAST UPDATED BY: JOHNSON

(29) ADT: 74,700 (30) ADT YR: 2018

(100) STRAHNET ROUTE: YES

(19) DETOUR LENGTH: 2 KM

(520) VC OVER RDWY: 99.99 METERS

CONDITION RATINGS

(58) DECK RATING: 5

(59) SUPERSTRUCTURE RATING: 6

(60) SUBSTRUCTURE RATING: 5

(61) CHANNEL PROTECTION: 7

(62) CULVERT RATING: N

(113A) NBIS SCOUR CODE: 8

(113B) TDOT SCOUR CODE: R

OTHER RATING ITEMS

(521) OVERALL CONDITION: F

(513) TEXTURE COAT RATING: G 06

(514) PAINT CONDITION RATING: N

(41) WEIGHT POSTING CODE: A

APPRAISAL RATINGS

(67) STRUCTURAL EVALUATION: 5

(68) DECK GEOMETRY: 8

(69) UNDER CLEARANCE: 5

(70) BRIDGE POSTING: 5

(71) WATERWAY ADEQUACY: 6

(72) APPROACH RDWY ALIGNMENT: 8

(36) TRAFFIC SAFETY

FEATURES: 0 0 0 0

(525) REPAIR LIST NO: 3

CODE VALUES

N - NOT APPLICABLE

9 - EXCELLENT CONDITION

8 - VERY GOOD CONDITION

7 - GOOD CONDITION

6 - SATISFACTORY

5 - FAIR CONDITION

4 - POOR CONDITION

3 - SERIOUS CONDITION

2 - CRITICAL CONDITION

1 - FAILURE IS IMMINENT

0 - FAILED CONDITION

COMMENTS

NO COMMENTS AT THIS TIME.

(502) SUFF. RATING:	66.7
(528) STR. DEFICIENT:	NO
(529) FUNC. OBSOLETE:	NO



STATE OF TENNESSEE
DEPARTMENT OF TRANSPORTATION

Bridge Condition Coding Form

Revised 07/31/2003

Bridge Number: 94I006500061

(Includes Item 5A)

Feature Intersected: I65/SR 106&HARPETH RIVER

Evaluation Status:

County: 94

Route: 10065

Special Case: 0

County Sequence: 1

Log Mile: 4.79

CODE ONLY THOSE VALUES WHICH HAVE CHANGED

ITEM #	DESCRIPTION	VALUE	CONDITION CODING GUIDELINES (Values for Coding Items 58, 59, 60 and 62)
90	INSPECTION DATE	<u>08/16/2001</u> <u>08 / 20 / 03</u>	N NOT APPLICABLE
10	MINIMUM V.C. OVER DECK (ROADWAY + SHOULDERS)	99 FT. 99 IN. ____ FT. ____ IN.	9 EXCELLENT CONDITION
520	MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS)	99 FT. 99 IN. ____ FT. ____ IN.	8 VERY GOOD CONDITION - NO PROBLEMS NOTED.
36	TRAFFIC SAFETY FEATURES Br. Rail Trans. Appr. Rail Terminal SPEED LIMIT 1 1 1 1 70		7 GOOD CONDITION - SOME MINOR PROBLEMS.
41	STRC OPEN/CLOSED/POSTED A K P	A	6 SATISFACTORY CONDITION - MINOR DETERIORATION OF STRUCTURAL ELEMENTS.
58	DECK	6	5 FAIR CONDITION - ALL PRIMARY STRUCTURAL ELEMENTS ARE SOUND BUT MAY HAVE MINOR SECTION LOSS, CRACKING, SPALLING OR SCOUR.
59	SUPERSTRUCTURE	7	4 POOR CONDITION - ADVANCED SECTION LOSS, DETERIORATION, SPALLING OR SCOUR.
60	SUBSTRUCTURE	6	3 SERIOUS CONDITION - LOSS OF SECTION, DETERIORATION, SPALLING OR SCOUR HAVE SERIOUSLY AFFECTED PRIMARY STRUCTURAL COMPONENTS. LOCAL FAILURES ARE POSSIBLE. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT.
61	CHANL/CHANL PROTECTION	7	2 CRITICAL CONDITION - ADVANCED DETERIORATION OF PRIMARY STRUCTURAL ELEMENTS. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT OR SCOUR MAY HAVE REMOVED SUBSTRUCTURE SUPPORT. UNLESS CLOSELY MONITORED IT MAY BE NECESSARY TO CLOSE THE BRIDGE UNTIL CORRECTIVE ACTION IS TAKEN.
62	CULVERT AND RETAIN WALL	N	1 "IMMINENT" FAILURE CONDITION - MAJOR DETERIORATION OR SECTION LOSS PRESENT IN CRITICAL STRUCTURAL COMPONENTS OR OBVIOUS VERTICAL OR HORIZONTAL MOVEMENT AFFECTING STRUCTURAL STABILITY. BRIDGE IS CLOSED TO TRAFFIC BUT CORRECTIVE ACTION MAY PUT IT BACK IN LIGHT SERVICE.
71	WATERWAY ADEQUACY	6	0 FAILED CONDITION - OUT OF SERVICE AND BEYOND CORRECTIVE ACTION.
72	APPROACH RDWY ALIGNMENT	6	
521	OVERALL CONDITION	FAIR	

TEAM LEADER SIGNATURE

08/20/03
REVIEW DATE



STATE OF TENNESSEE
DEPARTMENT OF TRANSPORTATION

Underpass Condition Coding Form

Revised 08/01/2003

Bridge Number: 941006500062
(Includes Item 5A)

Feature Intersected: I65 / SR 106

County: 94

Route: SR106

Special Case: 0

County Sequence: 1

Log Mile: 5.89

CODE ONLY THOSE VALUES WHICH HAVE CHANGED

ITEM #	DESCRIPTION	VALUE	UNDERPASS SAFETY FEATURES
90	INSPECTION DATE	<u>08/16/2001</u> <u>08/20/03</u>	515 (A) TYPE UNDERPASS BARRIER METAL BARRIER OR RAIL
10	MINIMUM V.C. OVER DECK (ROADWAY + SHOULDERS)	<u>19</u> FT. <u>8</u> IN. <u>19</u> FT. <u>9</u> IN.	Revised Barrier Type
520	MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS)	<u>19</u> FT. <u>8</u> IN. <u>19</u> FT. <u>9</u> IN.	(B) ADEQUACY OF BARRIER OR RAIL <u>1</u>
47	TOTAL HORIZONTAL UNDERCLEARANCE	<u>45</u> FT. <u>7</u> IN. <u>45</u> FT. <u>10</u> IN.	(C) ADEQUACY OF TRANSITIONS <u>1</u>
54	MINIMUM VERTICAL UNDERCLEARANCE (EXCLUDES SHOULDERS)	Circle One: <u>H</u> R <u> </u> FT. <u> </u> IN.	(D) ADEQUACY OF TERMINALS <u>1</u>
55	MINIMUM LATERAL UNDERCLEARANCE ON RIGHT SIDE	Circle One: <u>H</u> R <u>19</u> FT. <u>9</u> IN.	554 VERTICAL CLEARANCE LISTED ON HEIGHT POSTING <u> </u> FT. <u> </u> IN. <u> </u> FT. <u> </u> IN.
56	MINIMUM LATERAL UNDERCLEARANCE ON LEFT SIDE	<u>00</u> FT. <u>00</u> IN.	
521	OVERALL CONDITION	<u>FAIR</u>	HEIGHT POSTED AT BOTH APPROACHES? YES ☐ NO ☒ N/A ☐
555	COMMENTS		

TEAM LEADER SIGNATURE

08/20/03

REVIEW DATE



STATE OF TENNESSEE
DEPARTMENT OF TRANSPORTATION

Bridge Condition Coding Form

Revised 06/15/2000

Bridge Number: 941006500061
(Includes Item 5A)

Feature Intersected: 165/SR 106&HARPETH RIVER

County: 94
Route: 10065
Special Case: 0
County Sequence: 01
Log Mile: 4.79

CODE ONLY THOSE VALUES WHICH HAVE CHANGED

ITEM #	DESCRIPTION	VALUE
90	INSPECTION DATE	<u>08/23/1999</u>
		<u>08/16/2001</u>
10	MINIMUM V.C. OVER DECK (ROADWAY + SHOULDERS)	99 FT. 99 IN.
		FT. IN.
520	MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS)	99 FT. 99 IN.
		FT. IN.
36	TRAFFIC SAFETY FEATURES	
	Br. Rail Trans. Appr. Rail Appr. Rail Ends	
	1 1 1 1	
41	STRC OPEN/CLOSED/POSTED	A
	A K P	
58	DECK	6
59	SUPERSTRUCTURE	7
60	SUBSTRUCTURE	6
61	CHANL/CHANL PROTECTION	7
62	CULVERT AND RETAIN WALL	N
71	WATERWAY ADEQUACY	6
72	APPROACH RDWY ALIGNMENT (USE VALUES OF 3, 6, OR 8)	6
521	OVERALL CONDITION (Circle One)	

CONDITION CODING GUIDELINES
(Values for Coding Items 58, 59, 60 and 62)

- N NOT APPLICABLE
- 9 EXCELLENT CONDITION
- 8 VERY GOOD CONDITION - NO PROBLEMS NOTED.
- 7 GOOD CONDITION - SOME MINOR PROBLEMS.
- 6 SATISFACTORY CONDITION - MINOR DETERIORATION OF STRUCTURAL ELEMENTS.
- 5 FAIR CONDITION - ALL PRIMARY STRUCTURAL ELEMENTS ARE SOUND BUT MAY HAVE MINOR SECTION LOSS, CRACKING, SPALLING OR SCOUR.
- 4 POOR CONDITION - ADVANCED SECTION LOSS, DETERIORATION, SPALLING OR SCOUR.
- 3 SERIOUS CONDITION - LOSS OF SECTION, DETERIORATION, SPALLING OR SCOUR HAVE SERIOUSLY AFFECTED PRIMARY STRUCTURAL COMPONENTS. LOCAL FAILURES ARE POSSIBLE. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT.
- 2 CRITICAL CONDITION - ADVANCED DETERIORATION OF PRIMARY STRUCTURAL ELEMENTS. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT OR SCOUR MAY HAVE REMOVED SUBSTRUCTURE SUPPORT. UNLESS CLOSELY MONITORED IT MAY BE NECESSARY TO CLOSE THE BRIDGE UNTIL CORRECTIVE ACTION IS TAKEN.
- 1 "IMMINENT" FAILURE CONDITION - MAJOR DETERIORATION OR SECTION LOSS PRESENT IN CRITICAL STRUCTURAL COMPONENTS OR OBVIOUS VERTICAL OR HORIZONTAL MOVEMENT AFFECTING STRUCTURAL STABILITY. BRIDGE IS CLOSED TO TRAFFIC BUT CORRECTIVE ACTION MAY PUT BACK IN LIGHT SERVICE.
- 0 FAILED CONDITION - OUT OF SERVICE AND BEYOND CORRECTIVE ACTION.

GOOD FAIR POOR CRITICAL

TEAM LEADER SIGNATURE

08/16/2001
REVIEW DATE



STATE OF TENNESSEE
DEPARTMENT OF TRANSPORTATION

Underpass Condition Coding Form

Revised 06/15/2000

Bridge Number: 941006500062
(Includes Item 5A)
Feature Intersected: 165 / SR 106

County: 94
Route: SR106
Special Case: 0
County Sequence: 01
Log Mile: 5.89

CODE ONLY THOSE VALUES WHICH HAVE CHANGED

ITEM #	DESCRIPTION	VALUE	UNDERPASS SAFETY FEATURES
90	INSPECTION DATE	<u>08/23/1999</u> <u>08/14/2001</u>	515 (A) TYPE UNDERPASS BARRIER Metal Barrier or Rail
10	MINIMUM V.C. OVER DECK (ROADWAY + SHOULDERS)	19 FT. 7 IN. <u>19 FT. 9 IN.</u>	Revised Barrier Type
520	MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS)	19 FT. 7 IN. <u>19 FT. 9 IN.</u>	(B) ADEQUACY OF BARRIER OR RAIL 1
47	TOTAL HORIZONTAL UNDERCLEARANCE	45 FT. 7 IN. <u>45 FT. 10 IN.</u>	(C) ADEQUACY OF TRANSITIONS 1
54	MINIMUM VERTICAL UNDERCLEARANCE (EXCLUDES SHOULDERS) Circle One: <u>H</u> R <u>19 FT. 9 IN.</u>		(D) ADEQUACY OF TERMINALS 1
55	MINIMUM LATERAL UNDERCLEARANCE ON RIGHT SIDE Circle One: <u>H</u> R <u>11 FT. 9 IN.</u>		554 VERTICAL CLEARANCE LISTED ON HEIGHT POSTING 99 FT. 99 IN. ____ FT. ____ IN.
56	MINIMUM LATERAL UNDERCLEARANCE ON LEFT SIDE	<u>00 FT. 00 IN.</u>	
521	OVERALL CONDITION (Circle One) GOOD <u>FAIR</u> POOR CRITICAL		HEIGHT POSTED AT BOTH APPROACHES? YES [] NO [☒] N/A []

555 COMMENTS

TEAM LEADER SIGNATURE

REVIEW DATE

08/14/2001



STATE OF TENNESSEE
DEPARTMENT OF TRANSPORTATION

Bridge Condition Coding Form

County: 94

Route: 10065

Special Case: 0

County Sequence: 1

Log Mile: 4.79

Bridge Number:
(Includes Item 5A) 941006500061

Feature Intersected: 165/SR 106&HARPETH RIVER

CODE ONLY THOSE NUMBERS WHICH HAVE CHANGED

ITEM #	DESCRIPTION	VALUE	COMMENTS
90	INSPECTION DATE	9/1/97	RATINGS FOR CODING ITEMS 58, 59, 60 AND 62
		68 / 05 / 07	N NOT APPLICABLE
10	MINIMUM V.C. OVER DECK (ROADWAY + SHOULDERS)	99 FT. 99 IN.	9 EXCELLENT CONDITION
		FT. IN.	8 VERY GOOD CONDITION - NO PROBLEMS NOTED.
520	MINIMUM V.C. OVER DECK (EXCLUDES SHOULDERS)	99 FT. 99 IN.	7 GOOD CONDITION - SOME MINOR PROBLEMS.
		FT. IN.	6 SATISFACTORY CONDITION - MINOR DETERIORATION OF STRUCTURAL ELEMENTS.
54	MINIMUM VERTICAL UNDERCLEARANCE (EXCLUDES SHOULDERS)	19 FT. 7 IN.	5 FAIR CONDITION - ALL PRIMARY STRUCTURAL ELEMENTS ARE SOUND BUT MAY HAVE MINOR SECTION LOSS, CRACKING, SPALLING OR SCOUR.
	Circle One: ☒ H ☐ R ☐ N	19 FT. 8 IN.	4 POOR CONDITION - ADVANCED SECTION LOSS, DETERIORATION, SPALLING OR SCOUR.
36	TRAFFIC SAFETY FEATURES		3 SERIOUS CONDITION - LOSS OF SECTION, DETERIORATION, SPALLING OR SCOUR HAVE SERIOUSLY AFFECTED PRIMARY STRUCTURAL COMPONENTS. LOCAL FAILURES ARE POSSIBLE. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT.
	Br. Rail Trans. Appr. Rail Appr. Rail Ends		2 CRITICAL CONDITION - ADVANCED DETERIORATION OF PRIMARY STRUCTURAL ELEMENTS. FATIGUE CRACKS IN STEEL OR SHEAR CRACKS IN CONCRETE MAY BE PRESENT OR SCOUR MAY HAVE REMOVED SUBSTRUCTURE SUPPORT. UNLESS CLOSELY MONITORED IT MAY BE NECESSARY TO CLOSE THE BRIDGE UNTIL CORRECTIVE ACTION IS TAKEN.
	1 1 1 1		1 "IMMINENT" FAILURE CONDITION - MAJOR DETERIORATION OR SECTION LOSS PRESENT IN CRITICAL STRUCTURAL COMPONENTS OR OBVIOUS VERTICAL OR HORIZONTAL MOVEMENT AFFECTING STRUCTURAL STABILITY. BRIDGE IS CLOSED TO TRAFFIC BUT CORRECTIVE ACTION MAY PUT BACK IN LIGHT SERVICE.
41	STRC OPEN/CLOSED/POSTED	A	0 FAILED CONDITION - OUT OF SERVICE AND BEYOND CORRECTIVE ACTION.
	A K P		
58	DECK	6	
59	SUPERSTRUCTURE	7	
60	SUBSTRUCTURE	6	
61	CHANL/CHANL PROTECTION	7	
62	CULVERT AND RETAIN WALL	N	
72	APPROACH RDWY ALIGNMENT (USE VALUES OF 3, 6, OR 8)	6	
	OVERALL CONDITION (Circle One)		
	GOOD FAIR POOR CRITICAL		
	SIGNATURE	DATE	



STATE OF TENNESSEE
DEPARTMENT OF TRANSPORTATION

Underpass Condition Coding Form

County: 94

Route: SR106

Special Case: 0

County Sequence: 1

Bridge Number: 94I006500062
(Includes Item 5A)

Feature Intersected: I65 / SR 106

Log Mile: 5.88

CODE ONLY THOSE NUMBERS WHICH HAVE CHANGED

ITEM # DESCRIPTION

VALUE

UNDERPASS SAFETY FEATURES

90 INSPECTION DATE

9/1/97

(A) TYPE UNDERPASS BARRIER

Metal Barrier or Rail

10 MINIMUM V.C. OVER DECK
(ROADWAY + SHOULDERS)

19 FT. 7 IN.

520 MINIMUM V.C. OVER DECK
(EXCLUDES SHOULDERS)

19 FT. 7 IN.

47 TOTAL HORIZONTAL
UNDERCLEARANCE

45 FT. 7 IN.

55 MINIMUM LATERAL
UNDERCLEARANCE ON RIGHT SIDE

H

11 FT. 9 IN.

Circle One: (H) R N

56 MINIMUM LATERAL
UNDERCLEARANCE ON LEFT SIDE

0 FT. 0 IN.

Revised Barrier Type

(B) ADEQUACY OF BARRIER OR RAIL 1

(C) ADEQUACY OF TRANSITIONS 1

(D) ADEQUACY OF TERMINALS 1

VERTICAL CLEARANCE
LISTED ON HEIGHT
POSTING SIGNS

99 FT. 99 IN.

FT. IN.

OVERALL CONDITION (Circle One)

GOOD FAIR POOR CRITICAL

HEIGHT POSTED AT
BOTH APPROACHES?

YES [] NO [X] N/A []

NOTE: DESCRIBE ANY PROBLEMS ON BRIDGES THAT THE STATE DOES NOT INSPECT (SUCH AS RAILROAD OR PRIVATE BRIDGES) THAT WOULD AFFECT THE ROADWAY SUCH AS LOOSE MEMBERS, SEVERELY SPALLED OR CRACKED CONCRETE, EXCESSIVE SECTION LOSS ON STEEL, EXCESSIVE TIMBER DECAY, ETC. ALSO, DESCRIBE ANY UNSAFE ITEMS.

COMMENTS

SIGNATURE

DATE

DT-1449

REV. 06-28-90

Bridge No.: 479
 Evaluator: 11/1/77
 Date: 6-3-98
 ADT: 30470 1925 Defense Rte.
 Detour length: 1 Yes ☒ No ☐
 V.C. Over Deck ft. in. [☒] NA

APPRAISAL RATING (Relation to System)

	Calverts
67 Structural Evaluation	6
68 Deck Geometry	7
69 Under Clearance	N 6
70 Bridge Posting	5
71 Waterway Adequacy	6
72 Approach Rdy Alignment	6

(36) gr. Rail, Trans., Appr. rails, Terminals

Traffic Safety features: 1/1/1/1

Rail Under Bridge (515): 211

CONCUR 9-5-06 AK17

CONCUR 4-2-02 ARM

COMMENTARY (Condition)

COMMENTARY (Appraisal)

N	Not applicable
9	Superior to present desirable criteria
8	Equal to present desirable criteria
7	Better than present minimum criteria
6	Equal to present minimum criteria
5	Somewhat better than minimum adequacy to tolerate being left in place as is
4	Meets minimum tolerable limits to be left in place as is
3	Basically intolerable requiring high priority of corrective action
2	Basically intolerable requiring high priority of replacement
1	This value of rating code not used
0	Bridge closed

GOOD-----7, 8 & 9
FAIR-----5 & 6
POOR-----3 & 4
CRITICAL 0, 1 & 2

Sufficiency Rating
Dated: 9-5-01

Bridge Name: I 65 / SR106 & Harpeth River

NBI Structure ID: 94I00650006

Bridge ID: 94I00650006

Analyzed By: bridgeware

Analyze Date: Thursday, August 30, 2018 09:59:21

Analysis Engine: AASHTO LFR Engine Version 6.8.1.3001

Analysis Preference Setting: None

Report By: bridgeware

Report Date: Thursday, August 30, 2018 10:01:34

Structure Definition Name: SPAN 4

Member Name: G5

Member Alternative Name: G5

Load Factor Rating Summary

		Girder Summary							
		Rating		Capacity	Location				
Live Load		Factor	Controls	(Ton)	Span	(ft)	Percent	Impact	Lane
H 15-44	Inventory	1.215	Design Flexure - Concrete	18.22	1	17.26	50.0	As Requested	As Requested
H 15-44	Operating	2.029	Design Flexure - Concrete	30.43	1	17.26	50.0	As Requested	As Requested
HS 20-44	Inventory	0.772	Design Flexure - Concrete	27.79	1	17.26	50.0	As Requested	As Requested
HS 20-44	Operating	1.289	Design Flexure - Concrete	46.41	1	17.26	50.0	As Requested	As Requested
Type 3S2	Inventory	0.984	Design Flexure - Concrete	35.42	1	17.26	50.0	As Requested	As Requested
Type 3S2	Operating	1.643	Design Flexure - Concrete	59.15	1	17.26	50.0	As Requested	As Requested
Annual Permit 1	Inventory	0.609	Design Flexure - Concrete	50.24	1	17.26	50.0	As Requested	As Requested
Annual Permit 1	Operating	1.017	Design Flexure - Concrete	83.90	1	17.26	50.0	As Requested	As Requested
Annual Permit 2	Inventory	0.609	Design Flexure - Concrete	50.24	1	17.26	50.0	As Requested	As Requested
Annual Permit 2	Operating	1.017	Design Flexure - Concrete	83.90	1	17.26	50.0	As Requested	As Requested
Gravel Truck	Inventory	0.632	Design Flexure - Concrete	23.37	1	17.26	50.0	As Requested	As Requested
Gravel Truck	Operating	1.055	Design Flexure - Concrete	39.03	1	17.26	50.0	As Requested	As Requested
Overweight Permit	Inventory	0.569	Design Flexure - Concrete	72.57	1	17.26	50.0	As Requested	As Requested
Overweight Permit	Operating	0.950	Design Flexure - Concrete	121.19	1	17.26	50.0	As Requested	As Requested
EV2	Operating	1.380	Design Flexure - Concrete	39.68	1	13.81	40.0	As Requested	As Requested
EV3	Operating	0.840	Design Flexure - Concrete	36.10	1	17.26	50.0	As Requested	As Requested
SU6 LFR	Operating	1.138	Design Flexure - Concrete	39.56	1	17.26	50.0	As Requested	As Requested
SU7 LFR	Operating	1.080	Design Flexure - Concrete	41.84	1	17.26	50.0	As Requested	As Requested

Bridge Name: I 65 / SR106 & Harpeth River
NBI Structure ID: 94I00650006
Bridge ID: 94I00650006

Analyzed By: bridgeware
Analyze Date: Wednesday, July 16, 2014 08:48:39
Analysis Engine: AASHTO LFR Engine Version 6.4.0.3001
Analysis Preference Setting: None

Report By: bridgeware
Report Date: Wednesday, July 16, 2014 08:52:47

Structure Definition Name: SPANS 1,2,3
Member Name: G1
Member Alternative Name: G1

Load Factor Rating Summary

		Rating			Capacity			Location		
Live Load		Factor	Controls	(Ton)	Span	(ft)	Percent	Impact	Lane	
H 15-44	Inventory	2.707	Design Shear - Concrete	40.60	3	10.27	20.0	As Requested	As Requested	
	Operating	4.521	Design Shear - Concrete	67.81	3	10.27	20.0	As Requested	As Requested	
HS 20-44	Inventory	1.477	Design Shear - Concrete	53.19	3	10.27	20.0	As Requested	As Requested	
	Operating	2.467	Design Shear - Concrete	88.83	3	10.27	20.0	As Requested	As Requested	
Gravel - Concrete Truck	Inventory	1.380	Design Shear - Concrete	51.05	3	10.27	20.0	As Requested	As Requested	
	Operating	2.304	Design Shear - Concrete	85.25	3	10.27	20.0	As Requested	As Requested	
Overweight Permit	Inventory	0.974	Design Shear - Concrete	124.19	3	10.27	20.0	As Requested	As Requested	
	Operating	1.627	Design Shear - Concrete	207.41	3	10.27	20.0	As Requested	As Requested	
SU4 LFR	Inventory	1.818	Design Shear - Concrete	49.08	3	10.27	20.0	As Requested	As Requested	
	Operating	3.035	Design Shear - Concrete	81.96	3	10.27	20.0	As Requested	As Requested	
SU5 LFR	Inventory	1.646	Design Shear - Concrete	51.03	3	10.27	20.0	As Requested	As Requested	
	Operating	2.749	Design Shear - Concrete	85.23	3	10.27	20.0	As Requested	As Requested	
SU6 LFR	Inventory	1.570	Design Shear - Concrete	54.55	3	10.27	20.0	As Requested	As Requested	
	Operating	2.622	Design Shear - Concrete	91.10	3	10.27	20.0	As Requested	As Requested	
SU7 LFR	Inventory	1.519	Design Shear - Concrete	58.84	3	10.27	20.0	As Requested	As Requested	
	Operating	2.536	Design Shear - Concrete	98.27	3	10.27	20.0	As Requested	As Requested	

Note:
"N/A" indicates not applicable
"***" indicates not available

Bridge Name: I 65 / SR106 & Harpeth River
NBI Structure ID: 94I00650006
Bridge ID: 94I00650006

Analyzed By: bridgeware
Analyze Date: Wednesday, July 16, 2014 08:48:39
Analysis Engine: AASHTO LFR Engine Version 6.4.0.3001
Analysis Preference Setting: None

Report By: bridgeware
Report Date: Wednesday, July 16, 2014 08:52:47

Structure Definition Name: SPANS 1,2,3
Member Name: G2
Member Alternative Name: G2

Load Factor Rating Summary

		Rating			Capacity	Location			
Live Load		Factor	Controls	(Ton)	Span	(ft)	Percent	Impact	Lane
H 15-44	Inventory	2.263	Design Shear - Concrete	33.94	3	10.27	20.0	As Requested	As Requested
	Operating	3.779	Design Shear - Concrete	56.68	3	10.27	20.0	As Requested	As Requested
HS 20-44	Inventory	1.235	Design Shear - Concrete	44.46	3	10.27	20.0	As Requested	As Requested
	Operating	2.062	Design Shear - Concrete	74.25	3	10.27	20.0	As Requested	As Requested
Gravel - Concrete Truck	Inventory	1.153	Design Shear - Concrete	42.67	3	10.27	20.0	As Requested	As Requested
	Operating	1.926	Design Shear - Concrete	71.26	3	10.27	20.0	As Requested	As Requested
Overweight Permit	Inventory	0.814	Design Shear - Concrete	103.81	3	10.27	20.0	As Requested	As Requested
	Operating	1.360	Design Shear - Concrete	173.36	3	10.27	20.0	As Requested	As Requested
SU4 LFR	Inventory	1.519	Design Shear - Concrete	41.02	3	10.27	20.0	As Requested	As Requested
	Operating	2.537	Design Shear - Concrete	68.50	3	10.27	20.0	As Requested	As Requested
SU5 LFR	Inventory	1.376	Design Shear - Concrete	42.66	3	10.27	20.0	As Requested	As Requested
	Operating	2.298	Design Shear - Concrete	71.24	3	10.27	20.0	As Requested	As Requested
SU6 LFR	Inventory	1.312	Design Shear - Concrete	45.60	3	10.27	20.0	As Requested	As Requested
	Operating	2.191	Design Shear - Concrete	76.15	3	10.27	20.0	As Requested	As Requested
SU7 LFR	Inventory	1.269	Design Shear - Concrete	49.19	3	10.27	20.0	As Requested	As Requested
	Operating	2.120	Design Shear - Concrete	82.14	3	10.27	20.0	As Requested	As Requested

Note:
"N/A" indicates not applicable
"***" indicates not available

Bridge Name: I 65 / SR106 & Harpeth River
NBI Structure ID: 94I00650006
Bridge ID: 94I00650006

Analyzed By: bridgeware
Analyze Date: Wednesday, July 16, 2014 08:48:39
Analysis Engine: AASHTO LFR Engine Version 6.4.0.3001
Analysis Preference Setting: None

Report By: bridgeware
Report Date: Wednesday, July 16, 2014 08:52:47

Structure Definition Name: SPANS 1,2,3
Member Name: G3
Member Alternative Name: G3

Load Factor Rating Summary

		Rating			Capacity	Location			
Live Load		Factor	Controls	(Ton)	Span	(ft)	Percent	Impact	Lane
H 15-44	Inventory	2.561	Design Shear - Concrete	38.42	3	10.27	20.0	As Requested	As Requested
	Operating	4.277	Design Shear - Concrete	64.16	3	10.27	20.0	As Requested	As Requested
HS 20-44	Inventory	1.398	Design Shear - Concrete	50.33	3	10.27	20.0	As Requested	As Requested
	Operating	2.335	Design Shear - Concrete	84.04	3	10.27	20.0	As Requested	As Requested
Gravel - Concrete Truck	Inventory	1.305	Design Shear - Concrete	48.30	3	10.27	20.0	As Requested	As Requested
	Operating	2.180	Design Shear - Concrete	80.66	3	10.27	20.0	As Requested	As Requested
Overweight Permit	Inventory	0.922	Design Shear - Concrete	117.51	3	10.27	20.0	As Requested	As Requested
	Operating	1.539	Design Shear - Concrete	196.24	3	10.27	20.0	As Requested	As Requested
SU4 LFR	Inventory	1.720	Design Shear - Concrete	46.43	3	10.27	20.0	As Requested	As Requested
	Operating	2.872	Design Shear - Concrete	77.54	3	10.27	20.0	As Requested	As Requested
SU5 LFR	Inventory	1.558	Design Shear - Concrete	48.29	3	10.27	20.0	As Requested	As Requested
	Operating	2.601	Design Shear - Concrete	80.64	3	10.27	20.0	As Requested	As Requested
SU6 LFR	Inventory	1.485	Design Shear - Concrete	51.61	3	10.27	20.0	As Requested	As Requested
	Operating	2.480	Design Shear - Concrete	86.20	3	10.27	20.0	As Requested	As Requested
SU7 LFR	Inventory	1.437	Design Shear - Concrete	55.68	3	10.27	20.0	As Requested	As Requested
	Operating	2.399	Design Shear - Concrete	92.98	3	10.27	20.0	As Requested	As Requested

Note:
"N/A" indicates not applicable
"***" indicates not available

Bridge Name: I 65 / SR106 & Harpeth River
NBI Structure ID: 94I00650006
Bridge ID: 94I00650006

Analyzed By: bridgeware
Analyze Date: Wednesday, July 16, 2014 08:48:39
Analysis Engine: AASHTO LFR Engine Version 6.4.0.3001
Analysis Preference Setting: None

Report By: bridgeware
Report Date: Wednesday, July 16, 2014 08:52:47

Structure Definition Name: SPANS 1,2,3
Member Name: G6
Member Alternative Name: G6

Load Factor Rating Summary

		Rating			Capacity	Location			
Live Load		Factor	Controls	(Ton)	Span	(ft)	Percent	Impact	Lane
H 15-44	Inventory	2.081	Design Shear - Concrete	31.22	3	10.27	20.0	As Requested	As Requested
	Operating	3.475	Design Shear - Concrete	52.13	3	10.27	20.0	As Requested	As Requested
HS 20-44	Inventory	1.136	Design Shear - Concrete	40.89	3	10.27	20.0	As Requested	As Requested
	Operating	1.897	Design Shear - Concrete	68.29	3	10.27	20.0	As Requested	As Requested
Gravel - Concrete Truck	Inventory	1.057	PS Tensile Stress - Concrete	39.09	3	25.67	50.0	As Requested	As Requested
	Operating	1.771	Design Shear - Concrete	65.54	3	10.27	20.0	As Requested	As Requested
Overweight Permit	Inventory	0.749	Design Shear - Concrete	95.48	3	10.27	20.0	As Requested	As Requested
	Operating	1.251	Design Shear - Concrete	159.45	3	10.27	20.0	As Requested	As Requested
SU4 LFR	Inventory	1.372	PS Tensile Stress - Concrete	37.03	3	25.67	50.0	As Requested	As Requested
	Operating	2.334	Design Shear - Concrete	63.00	3	10.27	20.0	As Requested	As Requested
SU5 LFR	Inventory	1.266	Design Shear - Concrete	39.23	3	10.27	20.0	As Requested	As Requested
	Operating	2.114	Design Shear - Concrete	65.52	3	10.27	20.0	As Requested	As Requested
SU6 LFR	Inventory	1.147	PS Tensile Stress - Concrete	39.86	3	25.67	50.0	As Requested	As Requested
	Operating	2.015	Design Shear - Concrete	70.04	3	10.27	20.0	As Requested	As Requested
SU7 LFR	Inventory	1.071	PS Tensile Stress - Concrete	41.49	3	25.67	50.0	As Requested	As Requested
	Operating	1.950	Design Shear - Concrete	75.55	3	10.27	20.0	As Requested	As Requested

Note:
"N/A" indicates not applicable
"***" indicates not available

Bridge Name: I 65 / SR106 & Harpeth River
NBI Structure ID: 94I00650006
Bridge ID: 94I00650006

Analyzed By: bridgeware
Analyze Date: Wednesday, July 16, 2014 08:48:39
Analysis Engine: AASHTO LFR Engine Version 6.4.0.3001
Analysis Preference Setting: None

Report By: bridgeware
Report Date: Wednesday, July 16, 2014 08:52:47

Structure Definition Name: SPAN 4
Member Name: G1
Member Alternative Name: G1

Load Factor Rating Summary

		Rating			Capacity			Location		
Live Load		Factor	Controls	(Ton)	Span	(ft)	Percent	Impact	Lane	
H 15-44	Inventory	2.275	Design Flexure - Concrete	34.12	1	17.26	50.0	As Requested	As Requested	
	Operating	3.799	Design Flexure - Concrete	56.98	1	17.26	50.0	As Requested	As Requested	
HS 20-44	Inventory	1.445	Design Flexure - Concrete	52.03	1	17.26	50.0	As Requested	As Requested	
	Operating	2.414	Design Flexure - Concrete	86.89	1	17.26	50.0	As Requested	As Requested	
Gravel - Concrete Truck	Inventory	1.183	Design Flexure - Concrete	43.76	1	17.26	50.0	As Requested	As Requested	
	Operating	1.975	Design Flexure - Concrete	73.07	1	17.26	50.0	As Requested	As Requested	
Overweight Permit	Inventory	1.066	Design Flexure - Concrete	135.87	1	17.26	50.0	As Requested	As Requested	
	Operating	1.780	Design Flexure - Concrete	226.90	1	17.26	50.0	As Requested	As Requested	
SU4 LFR	Inventory	1.486	Design Flexure - Concrete	40.12	1	17.26	50.0	As Requested	As Requested	
	Operating	2.482	Design Flexure - Concrete	67.01	1	17.26	50.0	As Requested	As Requested	
SU5 LFR	Inventory	1.412	Design Flexure - Concrete	43.76	1	17.26	50.0	As Requested	As Requested	
	Operating	2.357	Design Flexure - Concrete	73.08	1	17.26	50.0	As Requested	As Requested	
SU6 LFR	Inventory	1.276	Design Flexure - Concrete	44.36	1	17.26	50.0	As Requested	As Requested	
	Operating	2.132	Design Flexure - Concrete	74.07	1	17.26	50.0	As Requested	As Requested	
SU7 LFR	Inventory	1.211	Design Flexure - Concrete	46.91	1	17.26	50.0	As Requested	As Requested	
	Operating	2.022	Design Flexure - Concrete	78.34	1	17.26	50.0	As Requested	As Requested	

Note:
"N/A" indicates not applicable
"***" indicates not available

Bridge Name: I 65 / SR106 & Harpeth River
NBI Structure ID: 94I00650006
Bridge ID: 94I00650006

Analyzed By: bridgeware
Analyze Date: Wednesday, July 16, 2014 08:48:39
Analysis Engine: AASHTO LFR Engine Version 6.4.0.3001
Analysis Preference Setting: None

Report By: bridgeware
Report Date: Wednesday, July 16, 2014 08:52:47

Structure Definition Name: SPAN 4
Member Name: G2
Member Alternative Name: G2

Load Factor Rating Summary

		Rating			Capacity	Location			
Live Load		Factor	Controls	(Ton)	Span	(ft)	Percent	Impact	Lane
H 15-44	Inventory	1.696	Design Flexure - Concrete	25.45	1	17.26	50.0	As Requested	As Requested
	Operating	2.833	Design Flexure - Concrete	42.50	1	17.26	50.0	As Requested	As Requested
HS 20-44	Inventory	1.072	Design Flexure - Concrete	38.59	1	13.81	40.0	As Requested	As Requested
	Operating	1.790	Design Flexure - Concrete	64.44	1	13.81	40.0	As Requested	As Requested
Gravel - Concrete Truck	Inventory	0.882	Design Flexure - Concrete	32.63	1	17.26	50.0	As Requested	As Requested
	Operating	1.473	Design Flexure - Concrete	54.50	1	17.26	50.0	As Requested	As Requested
Overweight Permit	Inventory	0.795	Design Flexure - Concrete	101.33	1	17.26	50.0	As Requested	As Requested
	Operating	1.327	Design Flexure - Concrete	169.21	1	17.26	50.0	As Requested	As Requested
SU4 LFR	Inventory	1.108	Design Flexure - Concrete	29.92	1	17.26	50.0	As Requested	As Requested
	Operating	1.851	Design Flexure - Concrete	49.97	1	17.26	50.0	As Requested	As Requested
SU5 LFR	Inventory	1.053	Design Flexure - Concrete	32.64	1	17.26	50.0	As Requested	As Requested
	Operating	1.758	Design Flexure - Concrete	54.50	1	17.26	50.0	As Requested	As Requested
SU6 LFR	Inventory	0.952	Design Flexure - Concrete	33.08	1	17.26	50.0	As Requested	As Requested
	Operating	1.590	Design Flexure - Concrete	55.24	1	17.26	50.0	As Requested	As Requested
SU7 LFR	Inventory	0.903	Design Flexure - Concrete	34.98	1	17.26	50.0	As Requested	As Requested
	Operating	1.508	Design Flexure - Concrete	58.42	1	17.26	50.0	As Requested	As Requested

Note:
"N/A" indicates not applicable
"***" indicates not available

Bridge Name: I 65 / SR106 & Harpeth River
NBI Structure ID: 94I00650006
Bridge ID: 94I00650006

Analyzed By: bridgeware
Analyze Date: Wednesday, July 16, 2014 08:48:39
Analysis Engine: AASHTO LFR Engine Version 6.4.0.3001
Analysis Preference Setting: None

Report By: bridgeware
Report Date: Wednesday, July 16, 2014 08:52:47

Structure Definition Name: SPAN 4
Member Name: G3
Member Alternative Name: G3

Load Factor Rating Summary

		Rating			Capacity	Location			
Live Load		Factor	Controls	(Ton)	Span	(ft)	Percent	Impact	Lane
H 15-44	Inventory	1.634	Design Flexure - Concrete	24.50	1	17.26	50.0	As Requested	As Requested
	Operating	2.728	Design Flexure - Concrete	40.92	1	17.26	50.0	As Requested	As Requested
HS 20-44	Inventory	1.033	Design Flexure - Concrete	37.17	1	13.81	40.0	As Requested	As Requested
	Operating	1.724	Design Flexure - Concrete	62.08	1	13.81	40.0	As Requested	As Requested
Gravel - Concrete Truck	Inventory	0.849	Design Flexure - Concrete	31.42	1	17.26	50.0	As Requested	As Requested
	Operating	1.418	Design Flexure - Concrete	52.48	1	17.26	50.0	As Requested	As Requested
Overweight Permit	Inventory	0.765	Design Flexure - Concrete	97.57	1	17.26	50.0	As Requested	As Requested
	Operating	1.278	Design Flexure - Concrete	162.94	1	17.26	50.0	As Requested	As Requested
SU4 LFR	Inventory	1.067	Design Flexure - Concrete	28.81	1	17.26	50.0	As Requested	As Requested
	Operating	1.782	Design Flexure - Concrete	48.12	1	17.26	50.0	As Requested	As Requested
SU5 LFR	Inventory	1.014	Design Flexure - Concrete	31.43	1	17.26	50.0	As Requested	As Requested
	Operating	1.693	Design Flexure - Concrete	52.48	1	17.26	50.0	As Requested	As Requested
SU6 LFR	Inventory	0.917	Design Flexure - Concrete	31.85	1	17.26	50.0	As Requested	As Requested
	Operating	1.531	Design Flexure - Concrete	53.20	1	17.26	50.0	As Requested	As Requested
SU7 LFR	Inventory	0.869	Design Flexure - Concrete	33.69	1	17.26	50.0	As Requested	As Requested
	Operating	1.452	Design Flexure - Concrete	56.26	1	17.26	50.0	As Requested	As Requested

Note:
"N/A" indicates not applicable
"***" indicates not available

Bridge No.: 94 — I65 — 4.79 Lt. Ln
Crossing: I65 / SR 106 & - Harpeth River
Federal No.: 94100650006

Date: August 20, 2003

PIC1



Br. No. Abutment No. 1

Bridge No.: 94 — I65 — 4.79 Lt. Ln
Crossing:: I65 / SR 106 & - Harpeth River
Federal No.: 94100650006

Date: August 20, 2003

PIC 2



Across Top of Deck

PIC 3



Spall @ Lt. Side of Abutment No. 1

Bridge No.: 94 — I65 — 4.79 Lt. Ln
Crossing: I65 / SR 106 & - Harpeth River
Federal No.: 94100650006

Date: August 20, 2003

PIC 4



Spall & Rebar, Bottom of Bent Cap No. 1

PIC 5



Cracks in Column "B" Bent No. 1

Bridge No.: 94 — I65 — 4.79 Lt. Ln
Crossing: I65 / SR 106 & - Harpeth River
Federal No.: 94100650006

Date: August 20, 2003

PIC 6



Cracks in Column "C" Bent No. 1

PIC 7



Elev. View, Rt. Side

Bridge No.: 94 — I65 — 4.79 Lt. Ln
Crossing: I65 / SR 106 & - Harpeth River
Federal No.: 94100650006

Date: August 20, 2003

PIC 8



Spall & Rebar in Diaphragm @ Bent No.2

PIC 9



Looking Ahead on Route (94-106-5.88)

Bridge No.: 94 — I65 — 4.79 Lt. Ln
Crossing: I65 / SR 106 & - Harpeth River
Federal No.: 94100650006


Date: August 20, 2003

PIC 8



Looking Back on Route (94-106-5.88)

PIC 9



Spall & Rebar in Diaphragm @ Bent No.3

Bridge No.: 00094 — 10065 — 479
Crossing: 165' SR 106 HARPETH RIVER
Federal No.: 94100650006

Date:

LEFT LANE

August 20, 2001

PIC1



BR. NO. ABUTMENT NO. 1

Bridge No.: 94 — 10065 — 479
Crossing:: I65/SR 106 & HARPETH RIVER
Federal No 94100650006

Date:

August 20, 2001

0

PIC2



ACROSS TOP OF DECK

PIC3



SPALL @ LT. SIDE OF ABUTMENT NO. 1

Bridge No.: 94 — I0065 — 479
Crossing:: I65/SR 106 & HARPETH RIVER
Federal No.: 94I00650006

Date:

August 20, 2001

PIC4



SPALL & REBAR, BOTTOM OF BENT CAP NO. 1

PIC5



CRACKS IN COLUMN "B", BENT NO. 1

Bridge No.: 94 — 10065 — 479
Crossing:: I65/SR 106 & HARPETH RIVER
Federal No.: 94I00650006

Date: August 20, 2001

PIC6



CRACKS IN COLUMN "C", BENT NO. 1

PIC7



ELEV. VIEW, RT. SIDE.

Bridge No.: 94 — 10065 — 479
Crossing:: I65/SR 106 & HARPETH RIVER
Federal No.: 94I00650006

Date: August 20, 2001

PIC8



SPALL & REBAR IN DIAPHRAGM @ BENT NO. 2

PIC9



CRACKS, SPALL, & REBAR IN COLUMN "C", BENT NO. 2-REPAIRED

Bridge No.: 94 — I0065 — 479
Crossing:: I65/SR 106 & HARPETH RIVER
Federal No.: 94I00650006

Date: August 20, 2001

PIC10



CRACKS, SPALL, & REBAR IN COLUMN "C", BENT NO. 3-REPAIRED

Bridge No.: 00094 — 10065 — 479
Crossing: 165' SR 106 HARPETH RIVER
Federal No.: 94100650006

Date:

LEFT LANE

August 20, 2001

PIC 1



CRACKS & SPALL ON COLUMN "C", BENT NO. 3 @ BOTTOM (REPAIRED)

PIC 2



LOOKING BACK ON ROUTE- 94-106-5.88-UP

Bridge No.: 94 — I0065 — 479
Crossing:: I65/SR 106 & HARPETH RIVER
Federal No 94I00650006

Date:

August 20, 2001

PIC 3



SPALL & REBAR IN DIAPHRAGM, BACK OF BENT NO. 3

PIC 4



LOOKING AHEAD ON ROUTE (94-106-5.88 UP)

ROUTINE BRIDGE INSPECTION REPORT

Page No. _____

Form BIR 3.0C
(Rev. 9-22-98)
DT-1537

Field Report No. 16 Date 8/20/2003
Previous Report No. 15 Date 8/16/2001
Plans: YES

Bridge No. 94100650006
Eleven Digit No.

Bridge Location No. 94 - 10065 - 4.79 L
Co. Route Log Mile

INTERSTATE 65 over SR 106&HARPETH RIVER
Road Name Crossing

Indepth Insp. Req'd: NO
(If yes itemize limits under comment)

Structure Type PPCIB

FRACTURE CRITICAL: NO

FEATURE CHANGES: NO

Wearing Surface NO Type ASPHALT Depth +4 (in.)

Bridge Rail NO Describe changes:

Approach Rail NO

CLEARANCE CHANGES: NO (If yes make changes below)

Vertical Clearance over deck _____ (ft.-in.)

Vertical Under Clearance 19'-9" (ft.-in.)

Horizontal Under Clearance 45'-10" (*. ft.)

Deck Width Curb/Curb 40.5 (*. ft.)

Deck Width Rail/Rail _____ (*. ft.)

Sidewalk Width Rt. _____ Lt. _____

INSPECTORS

HOWELL

CHOATE

FINCH

WILLIAMS

Condition: FAIR (If change describe in comments)

Comments

Approaches

GOOD

Deck Condition (Item 58)

F

NUMEROUS RANDOM CRACKS IN BOTTOM SPANS

Superstructure (Item 59)

a. Beams

GOOD

b. Bearings

GOOD

NEOPRENE

c. Diaphragms

F-P

SEVERAL WITH HEAVY SPALLS AND EXPOSED REBARS

Substructure (Item 60)

a. Caps/Bridge Seats

F-P

ABUTMENT NO. 1 AND BENT NO. 1 HAS SPALLS, OPEN CRACKS AND DELA

b. Columns/Piles

POOR

BENT NO. 1, CRACKS, POPOUTS, AND DELAMINATION.

c. Footings

NV

d. Wing W./Breast W.

GOOD

Scour/Erosion

GOOD

Channel (Item 61)

G

UNDERWATER INSPECTION

To Be Performed By: T.D.O.T.

Date Underwater Insp. 08/20/03

BRIDGE is: OPEN


Weight Limit Posted NO

Gross..... Tons

2 Axle..... Tons

3 or more Axles.. Tons

COMMENTS:

Supervising Bridge Inspector: 

BRIDGE RATING: FAIR

INSPECTION TEAM'S SUMMARY
BRIDGE NUMBER 94-I65-4.79 (LEFT LANE)
I-65 OVER SR-106 & HARPETH RIVER

AUGUST 20, 2003

The subject bridge was inspected, on the above date, and found to be in fair condition.

This structure is a 4 span precast, prestressed, concrete I-beam bridge on a 70° skew to the left. The bridge has a cross-section of 6 I-beams and a 7" thick concrete deck. All substructure members are cast-in-place concrete. The bridge has a roadway width of 40 and a total length of 194.

The approach alignment, pavement and embankment are rated good.

The approach guardrailing and bridge railing are present and standard.

The parapets are fair due to some light cracks. The beams are rated good. The diaphragms are fair to poor with open cracks, spalls, rebar exposure, and section loss.

The abutment No. 1 cap is fair to poor with open cracks, heavy spalls, and exposed rebars. The bent cap No. 1 is poor with rebar exposure, popouts open cracks, and delamination. Bent columns in bent No. 1 are poor with delamination, heavy spalls, rebar exposure, and section loss.

The channel opening is clean and appears to be adequate.

Form BIR 3.0A
(Rev. 9-22-98)
DT-1443

Field Report No. 16 Date 8/20/2003
Previous Report No. 15 Date 8/16/2001

Bridge No. 94100650006
Eleven Digit No.

Underpass Location No.	94	-	SR106	-	5.88
	Co.		Route		Log Mile

<u> </u>	or	94 - 10065 - 0479 L	over	94 - SR106 - 5.88
Railroad/Walkway		Co. Route Log Mile		Co. Route Log Mile

County WILLIAMSON

Structure Name (If Named) _____

Year Constructed 1963 ACTUAL

Year Widened Year Rehabilitated

GEOMETRIC FEATURES UNDER BRIDGE (*. * ft. unless otherwise noted)

Divided Highway N.A. Type of Wearing Surface ASPHALT

Width of Approach Traveled Roadway 21'-4" ft. (Does Not Include Shoulders)

Width of Median if Divided Highway — ft.

Approach Shoulder Width 8 ft. Right ft. Left

*Horizontal Clearance Under Bridge 45'-10" ft.

*Distance Between Pier Protection Guardrail and Substructure	2.75	ft.	Right	3.25	ft.	Left
---	------	-----	-------	------	-----	------

*Width of Sidewalk Under Bridge — ft. Right — ft. Left

*Minimum Vertical Clearance: 19 ft. 9 in. (ft.-in.)

***Show on Sketch**

TRAFFIC SAFETY FEATURES

Pier Protection Railing or Parapet

Approach Guardrail Terminals

Approach Guardrail

Approach Guardrail Terminal

Rating	Standard/ SubStandard Non Exist
GOOD	STANDARD
GOOD	STANDARD
GOOD	STANDARD
GOOD	STANDARD

SIGNING

Yes/ No/ Needed

Paddleboards	YES
Vertical Clearance (<14'-6")	NO
Narrow Passage	NO
One Lane Passage	NO

INSPECTORS

- | | |
|----|----------|
| 1. | HOWELL |
| 2. | CHOATE |
| 3. | FINCH |
| 4. | WILLIAMS |
| 5. | |
| 6. | |

Other Underpass Signs Needed

Form BIR 3.0A (Continued)

Date 8/20/2003

(Rev. 9-22-98)

DT-1443

Underpass Location No. 94 - SR106 - 5.88

Co. Route Log Mile

Other Signs or Plaques: NONE

Comments Regarding any

Problems with Signing: NONE**BRIDGE FEATURES** (*.* ft.)Bridge Skew 70°Number of Lanes/Tracks on Bridge 2Structure Type (Main Span) PPCIBNo. Main Spans 4Structure Type (Appr.Spans) N/ANo. Appr. Spans 0Maximum Span Length 52 (ft.) Total Length 194 (ft.)Width of Bridge Out-to-Out 44 (ft.) Right Angle to Centerline of Bridge)Width of Bridge Along Skew (ft.) (If Unable to Measure at Right
Angle to Centerline of Bridge)**BRIDGE CONDITION:** FAIRDoes Potential Exist for Elements from Bridge Falling on Roadway Beneath? NODoes Potential Exist Because of Deteriorated Condition or Failure of Major Members? NO

Comment on any Conditions of Bridge that would Effect Roadway Beneath:

NONE

Note: If Underpass Route Is Divided Highway, Use Two of These Forms, One for Each Roadway.

MINIMUM PICTURES REQUIRED

1. Elevation View of Bridge on Both Sides Showing Underpass
2. View Showing Both Approaches to Bridge
3. View Showing Safety Features
4. View Showing Any Problems

BRIDGE INSPECTION REPORT

Page No. _____

Form BIR 3.0
(Rev. 9-22-98)
DT-0069

Field Report No. 15 Date 8/16/01
Previous Report No. 14 Date 8/23/99
Plans: YES

Bridge No. 94I00650006
Eleven Digit No.

Bridge Location No. 94 - I0065 - 4.79 L
Co. Route Log Mile

INTERSTATE 65 over SR 106&HARPETH RIVER
Road Name Crossing

Structure Name (If Named) _____

Year Constructed 1963 ACTUAL County WILLIAMSON Maintenance District 31

Year Widened _____ Year Rehabilitated _____

FEATURES

Wearing Surface ASPHALT Depth +4 (in.)
Flared Width NO Median Width NONE
Navigational Control NO Bridge Skew 70°
Structure Type (Main Span) PPCIB
Structure Type (Appr.Spans) N/A
No. Main Spans 4 No. Approach Spans 0
Maximum Span Length 52 (**.ft.)
Total Length 194 (**.ft.)

INSPECTORS

1. HOWELL
2. CHOATE
3. FINCH
4. WILLIAMS
5. _____
6. _____
7. _____
8. _____

WIDTHS (**.ft.)

Deck Out-to-Out 44
Roadway Curb/Curb 40.5
Roadway Rail/Rail _____
Sidewalk Rt. _____ Lt. _____
*Approach Roadway 23.58
*(Does Not Include Shoulders)
Approach Shoulder Rt. 4
Lt. 10

CLEARANCES

Min. Vertical Clearance over Deck _____ (ft.-in.)
Min. Vertical Under Clearance 19'-9" (ft.-in.)
Min. Lateral Under Clearance Rt. 11'-10" (**.ft.)
Min. Lateral Under Clearance Lt. 000 (**.ft.)

FRACTURE CRITICAL: NO
(If Yes, Include BIR 3.9)

NBIS Bridge Length (<25 ft.) _____ >25' _____ (ft.-in.)

UNDERWATER INSPECTION

To Be Performed By: NONE REQUIRED Date _____

Change in Structural Condition: NO Major Repairs Made: NO BRIDGE is: OPEN

COMMENTS:

Supervising Bridge Inspector: [Signature]

BRIDGE RATING: FAIR

PERFORMANCE EVALUATION

Time of Day Inspected 11:30 Weather Conditions Clear (65°)
Vehicles Observed 17 Trucks, 1 Bus, 10 Cars, 1 Motorcycle

LIVE LOAD BEHAVIOR

Substructure	Yes/No	Comments
Horiz./ Vert. Defl.	<u>No</u>	
Vibration	<u>No</u>	
Superstructure		
Horiz./ Vert. Defl.	<u>No</u>	
Vibration	<u>No</u>	

APPROACH

	Rating	Comments
Alignment	<u>Good</u>	
Slab	<u>-</u>	
Joints	<u>-</u>	
Pavement	<u>Good</u>	
Embankment	<u>Fair</u>	<u>Light erosion</u>
Drains	<u>Good</u>	

TRAFFIC SAFETY FEATURES

	Rating	Standard/ SubStandard	Comments
Bridgerailing	<u>Fair</u>	<u>Standard</u>	<u>Light cracks</u>
Transitions	<u>Good</u>	<u>1</u>	
Guardrail	<u>Good</u>	<u>1</u>	
Guardrail Terminal	<u>Good</u>	<u>1</u>	

SIGNING

	Yes/ No/ Needed
Paddleboards	<u>✓</u>
Vertical Clearance (<14'-6")	<u>✓</u>
Narrow Bridge Signs	<u>✓</u>
One Lane Bridge Signs	<u>✓</u>

Other Signs or Plaques: NONE

Comments Regarding any
Problems with Signing: NONE

Weight Limit Posted No
Gross..... Tons
2 Axle..... Tons
3 or more Axles.. Tons

DECK

Wearing Surface

Rating

Comments

Deck - Structural Condition

Curbs

Median

Sidewalks

Parapet

Railing

Paint

Drains

Lighting Standards

Utilities

Joint Leakage

Expansion Joints

SUPERSTRUCTURE

Bearing Devices

Girders or Beams

Floor Beams

Stringers

Diaphragms

Bracing

Trusses - General

Portals

Bracing

Paint

Alignment of Members

TEXTURE COAT

Condition Rating

Overall Appearance

Staining Rating

Fading Rating

Scaling Rating

Needs Spot Painting

Needs Repainting

Comments

SUBSTRUCTURE

ABUTMENTS

	Rating	Comments
Caps	F-P	Heavy Spalls & Mort Cracks in Abut 1
Breastwall	—	
Wings	Good	
Backwall	—	
Plumb	Good	
Footings	—	
Piles	N/V	
Embankment	Good	
Bearing Surface	Good	
Slope Paving	Good	
Rip Rap	—	

PIERS

Caps		
Columns		
Plumb		
Footings		
Piles		
Bearing Surface		

BENTS

Caps	Poor	Bent Cap No. 1 has delamination, cracks and rebar pop-outs.
Columns	Poor	Columns B & C have cracks, pop-outs & delamination.
Plumb	Good	
Footings	N/V	
Piles	—	
Bearing Surface	Good	

Piles Need Replacement: No

Piles To Be Replaced:

STREAM CHANNEL DATA AND CONDITIONS

Stream Crossing: I65/SR 106&HARPETH RIVER

- I. 1. Type of bed material? Bedrock
2. Has channel shifted? No (Yes/ No/ Not Apparent)
3. Condition of rip-rap? N/A Est. % failed _____ %
4. Overall condition of channel? Good
5. Item 61 - Code values 0 thru 9 according to the recording and coding guide currently in effect: 8
6. Underwater diver inspection recommended? No
If yes, why? _____
- II. Channel and bank stability conditions: (yes if applicable)
1. Steep bank conditions: Failures upstream _____ Failures downstream _____
2. Moderate bank erosion _____
3. Bank vegetation: a. low growth ✓ b. large timber _____ c. clear banks _____
d. dead trees upstream _____ e. dead trees downstream _____
4. Sediment or gravel accumulation: No (Yes/ No/ Unknown)
5. Channel altered or straightened: No (Yes/ No/ Unknown)
6. Stable conditions: a. live growth ✓ b. bedrock ✓
c. boulders _____ d. flat slopes ($\leq 2:1$) _____
- III. Waterway adequacy and debris characteristics: (yes if applicable)
1. Bridge deck elevations:
a. level with approach roadway. ✓
b. higher than approach roadway. _____
c. roadway approach ≥ 2 ft. above natural ground line. _____
2. Abutment encroaches into channel. _____
3. Large scour (blowhole) under bridge. _____
4. Indications that flood waters overtop bridge: No (Yes/No)
If YES, Answer: Occasionally, Frequently, or Unknown _____
5. Debris characteristics:
a. debris/drift present No
b. debris/drift likely to accumulate No
c. dead trees upstream _____ dead trees downstream _____

IV. Comments:

SPECIAL INSPECTION DATA - FOR REASONS OTHER THAN FC OR SCOUR

- I. Does this bridge need a special inspection? No
II. Reason for special inspection:

INSPECTION REPORT FOR UNDERPASS ROUTE

Form BIR 3.0A

(Rev. 9-22-98)

DT-1443

Field Report No. 15Date 8/16/01Previous Report No. 14Date 8/23/99Bridge No. 94100650006

Eleven Digit No.

Underpass Location No. 94 - SR106 - 5.88

Co. Route Log Mile

or 94 - 10065 - 0479 L over 94 - SR106 - 5.88

Railroad/Walkway

Co. Route Log Mile

Co. Route Log Mile

County WILLIAMSON

Structure Name (If Named) _____

Year Constructed 1963 ACTUAL

Year Widened _____

Year Rehabilitated _____

GEOMETRIC FEATURES UNDER BRIDGE (*. * ft. unless otherwise noted)Divided Highway N.A. Type of Wearing Surface ASPHALTWidth of Approach Traveled Roadway 21 ft. (Does Not Include Shoulders)

Width of Median if Divided Highway _____ ft.

Approach Shoulder Width 8 ft. Right _____ ft. Left*Horizontal Clearance Under Bridge 45'-10" ft.*Distance Between Pier Protection
Guardrail and Substructure2.75 ft. Right 3.25 ft. Left

*Width of Sidewalk Under Bridge

_____ ft. Right _____ ft. Left

*Minimum Vertical Clearance:

19 ft. 9 in. (ft.-in.)

*Show on Sketch

TRAFFIC SAFETY FEATURES

Pier Protection Railing or Parapet

Approach Guardrail Terminals

Approach Guardrail

Approach Guardrail Terminal

Rating Standard/ SubStandard
Non Exist

GOOD	STANDARD
GOOD	STANDARD
GOOD	STANDARD
GOOD	STANDARD

INSPECTORS

1. HOWELL
2. CHOATE
3. FINCH
4. WILLIAMS
5. _____
6. _____

SIGNING

Yes/ No/ Needed

Paddleboards

YES

Vertical Clearance (<14'-6")

NO

Narrow Passage

NO

One Lane Passage

NO

Other Underpass Signs Needed

Form BIR 3.0A (Continued)
(Rev. 9-22-98)
DT-1443

Date 8/16/01

Underpass Location No. 94 - SR106 - 5.88
Co. Route Log Mile

Other Signs or Plaques: NONE

Comments Regarding any
Problems with Signing: NONE

BRIDGE FEATURES (* * ft.)

Bridge Skew	<u>70°</u>	Number of Lanes/Tracks on Bridge	<u>2</u>
Structure Type (Main Span)	<u>PPCIB</u>	No. Main Spans	<u>4</u>
Structure Type (Appr. Spans)	<u>N/A</u>	No. Appr. Spans	<u>0</u>
Maximum Span Length	<u>52</u> (ft.)	Total Length	<u>194</u> (ft.)
Width of Bridge Out-to-Out	<u>44</u> (ft.)	Right Angle to Centerline of Bridge)	
Width of Bridge Along Skew	<u>—</u> (ft.)	(If Unable to Measure at Right Angle to Centerline of Bridge)	

BRIDGE CONDITION: FAIR

Does Potential Exist for Elements from Bridge Falling on Roadway Beneath? NO
Does Potential Exist Because of Deteriorated Condition or Failure of Major Members? NO

Comment on any Conditions of Bridge that would Effect Roadway Beneath:
NONE

Note: If Underpass Route is Divided Highway, Use Two of These Forms, One for Each Roadway.

MINIMUM PICTURES REQUIRED

1. Elevation View of Bridge on Both Sides Showing Underpass
2. View Showing Both Approaches to Bridge
3. View Showing Safety Features
4. View Showing Any Problems

INSPECTION TEAM'S SUMMARY
BRIDGE NUMBER 94-I65-4.79 (LEFT LANE)
I-65 OVER SR-106 & HARPETH RIVER

AUGUST 16, 2001

The subject bridge was inspected, on the above date, and found to be in fair condition.

This structure is a 4 span precast, prestressed, concrete I-beam bridge on a 70° skew to the left. The bridge has a cross-section of 6 I-beams and a 7" thick concrete deck. All substructure members are cast-in-place concrete. The bridge has a roadway width of 40 and a total length of 194.

The approach alignment, pavement and embankment are rated good.

The approach guardrailing and bridge railing are present and standard.


The parapets are fair due to some light cracks. The beams are rated good. The diaphragms are fair to poor with open cracks, spalls, rebar exposure, and section loss.

The abutment caps are fair to poor with open cracks, heavy spalls, and exposed rebars. The bent caps are poor with rebar exposure, popouts open cracks, and delamination. The bent columns are poor with delamination, heavy spalls, rebar exposure, and section loss.

The channel opening is clean and appears to be adequate.


Br. No. 94-I65-4.79 LT. LANE DATE: 08/20/03
Underpass Clearance

1/9.




Proj. No. 94-165-4.79 LT. LANE DATE: 8/16/01
Underpass Clearance

15.



Br. No. 94-165-4.79 LT. LANE DATE: 02/23/99
Underpass Clearance


19.



BR # 94-I65-479 Lt Lane

Date: 08/16/01

Top Span 1




DECK	Good	
DRAINS	N/A	
HANDRAILS	N/A	
JOINTS	N/A	
PARAPET	Good	Light Cracks

BR # 94-I65-479 Lt. Lane

Date:

Top span 2




DECK	Good	
DRAINS	N/A	
HANDRAILS	N/A	
JOINTS	N/A	
PARAPET	Good	Light RAIL

BR # 94-I65-479 Lt. Lane

Date:

Top span 3




DECK	Good	
DRAINS	N/A	
HANDRAILS	N/A	
JOINTS	N/A	
PARAPET	Good	Light Cracks

BR # 94-I65-4.79 Lt. Lane

Date:

Top Span 4




DECK	Good	
DRAINS	N/A	
HANDRAILS	N/A	
JOINTS	N/A	
PARAPET	Good	Left Lane

BR # 94-I65-479

DATE: 8/10/01

Lt Lane
Bottom Span #




DECK	Good	
BEAM A	"	
B	"	
C	"	
D	"	
E	"	
F	"	
DRAINS		
DIAPH-BACK	Fair	Cracks w/old
INT	Good	
AHEAD	Fair	Light Cracks

BR # 94-I65-479

DATE: 8/12/01

Lt Lane
Bottom Span
#2




DECK	Fair	New and Lt Lane Span
BEAM A	Good	
B	"	
C	"	
D	"	
E	"	
F	"	
DECKS		
DIAPH-BACK	Fair	Light Cracks
INT	Good	
AHEAD	Good	Spalls & Exposed Rebar

BR # 94-I65-479

DATE: 8/14/01

Lt Lane
Bottom Span #:




DECK	Fair	Light Crack - Conc. Patch
BEAM A	Good	
B	"	
C	"	
D	"	
E	"	
F	"	
DRAINS		
DIAPH-BACK	F-P	Heavy open cracks
INT	Good	
AHEAD	Fair	Light Crack.

94-165-4.79

Date: 8/16/01

Lt. Lane

Bottom Span #4




DECK	Good	
BEAM A	"	
B	"	
C	"	
D	"	
E	"	
DRAWING		
DIAPH.-BACK	Poor	Spalls & Exposed Rebar
AHEAD	Fair	Cracks w/ Exposed Rebar
INT.	Good	

BR. No. 94-I65-4.77

LT. LANE

DATE: 8/20/03

RT.



LT.

BEARINGS	GOOD	
BR. SEAL		
CAO	F-P	Heavy spall, open cracks
LT. WING	Good	
RT. WING	"	
Slope Paving	N/A	

Abutment No. 1


BR. No. 94-IG5-4.79

LT. LANE

DATE: 8/20/03

Lt.

Rt.




~~BACK~~

FRONT VIEW BENT No. 1

Rt. End View

Rt.



FRONT
~~BACK~~ VIEW BENT No. 1

Lt. End View

BR # 94-I65-4.79

LT. LANE

BENT # 1

DATE: 8/20/03

BEARINGS Good

CAP F-P Cracks, pop-outs, spalls, rebar

COLUMN 'A' Good


COL. 'B' Poor large area of delam

COL. 'C' " SAME

FOOTINGS N/V

BR. No. 94-165-4.77
 LT. LANE
 DATE: 8/16/81

RT.



Abutment No. 1

LT.

PIERINGS	
BR. 5-1	
CAO	
LT. WING	
RT. WING	
Slope Paving	


BS. No. 94-IG5-4.79

Lt. LANE

DATE: 8/16/01

Lt.

Rt.




BACK

~~FRONT~~ VIEW BENT No. 1

Rt. End View

Rt.

Lt.



FRONT

~~BACK~~ VIEW BENT No. 1

Lt. End View

BR # 94-I65-4.79

LT. LANE

BENT # 1

DATE: 5/14/01

BEARINGS *Good*CAP *Reps* *Delam, cracks, rebar pop-out*COLUMN 'A' *Good*COL. 'B' *Reps* *Reps, cracks, delam*COL. 'C' " *SAME*FOOTINGS *N/V*


BA. No. 94-IG5-4.79

Lt. LANE

DATE: 6/16/01

Lt.

Rt.




BACK
VIEW BENT No. 2

Rt. End View

Rt.

Lt.



FRONT
VIEW BENT No. 2

Lt. End View

BR # 94-I65-4.79

LT. LANE

BENT # 2

DATE: 8/10/01

BEARINGS

CAP

COLUMN 'A'

COL. 'B'

COL. 'C'

FOOTINGS


BA. No. 94-IG5-4.78

Lt LANE

DATE: 7/14/01

Lt.

Rt.




FRONT VIEW BENT No. 3

Rt. End VIEW

Rt.

Lt.



BACK VIEW BENT No. 3

Lt. End VIEW

BR # 94-I65-4.79

LT. LANE

BENT # 3

DATE: 8/14/01

BEARINGS Goo

CAP

COLUMN 'A' "


COL. 'B' "

COL. 'C' "

FOOTINGS N/V

BR. No. 94-165-4.77
 Lt. LANE
 DATE: 8/16/01

7.



Abutment No. 2

REMARKS	GOOD
REMARKS	
U/A	GOOD
Lt. Wing	"
Rt. Wing	"
Slope Paying	"

7.

BRIDGE PIANS ARE IN REPORT

94I00650005