HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 06022760001

BRIDGE OWNER: BRADLEY COUNTY

ROAD NAME: UPPER RIVER RD

CROSSING: CHATATA CREEK

LATITUDE:: N 35.26087 DEGREES
ONGITUDE: W 84.74458 DEGREES

COUNTY: BRADLEY
ROUTE: 02276
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.94
VEAR BUILT: 1963

LON	IGITUDE: W 84.74458 DEGREES	;	YEAR BUILT: 1963
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	PRESTRESSED CONCRETE - STRIN OR GIRDER	NGER/MULTI-BEAM APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON S	STEEL PILE FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE HAMMERHEAD PIER O	N STEEL PILE FOUNDATION	
		SCOUR EVALUATION	
			Iculated scour conditions. Rip-rap protection ment of the protection system is needed.
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection		[] BridgeWatch Alert	
	·		al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
1. C 2. C [] - Chec [] - Chec [] - Chec	movement - horizontally as we check displacement / deflection check for plumb of piers or being the for embankment erosion k for drift build-up on piers or k pier exposure, if possible, and the latest bridge inspection	n along curb line, both bridg nts. bents nd compare to previous insp	
lf Closure is	recommended:		
Coun temp	ity or City Maintenance Persor	nnel. Use Barricade Tape, tra rists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	e maintained)
	(2) City or County Highwa	y Maintenance Official (if b	ridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	dge should remain closed until the water recedes and a daylight visual inspection is made OT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	work with State District maintenance or local highway maintenance r route. Any bridge on the selected detour route shall be checked		
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 728-7141		
HWY. CHIEF ADMINISTRATOR'S OFFIC	E (423) 728-7006		
COUNTY SHERIFF'S OFFICE	(423) 728-7301		
The report shall include the date as appropriate, photographs of t	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to condu	uct the Inspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Che	cklist		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
	e Barricade Tape printed with the following message:		
SAFETY H	IAZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24