## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 09SR0770025

BRIDGE OWNER: STATE OF TENNESSEE ROAD NAME: GORDON BROWNING HWY

CROSSING: BRANCH

LATITUDE:: N 36.08175 DEGREES

COUNTY: CARROLL ROUTE: SR077 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 21.41

LON	NGITUDE: W 88.36103 DEGREES	YEAR BUILT: 1990	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU		
BENTS:	TIMBER PILE BENT ON PILE FOUNI	DATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION ————————————————————————————————————	
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
		[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
[ ] - Span 1. 0 2. 0 [ ] - Chec [ ] - Chec	Check for plumb of piers or being the control of th	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.	
<u>If Closure is</u>	recommended:		
Cour temp	nty or City Maintenance Person	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )	
	( ) (	y Maintenance Official ( if bridge is not State maintained )	
	` '	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	•	
	] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance ridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(731) 234-9561		
DISTRICT MAINTENANCE SUPERVISOR	(731) 571-8883		
TENNESSEE HIGHWAY PATROL	(731) 423-6635		
<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.         The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.     </li> </ul>			
COMMENTS:			
Suggested List of Equipment to conduct the Inspect  Latest Bridge Inspection Report	tion:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole	one printed with the following massage:		
A 1000 Foot Roll of yellow Polyethylene Barricade To			
SAFETY HAZARD KEEP	' AVVA I		

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)