HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 230A4170001 BRIDGE OWNER: DYER COUNTY ROAD NAME: MILLER LOOP CROSSING: ELIZA CREEK

> LATITUDE:: **N** 35.97101 **DEGREES**

ROUTE: 0A417 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 1.29

COUNTY: DYER

LON	NGITUDE: W 89.25130 DEGREES	YEAR BUILT: 1980			
		TYPE OF SUPERSTRUCTURE			
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE			
		TYPE OF SUBSTRUCTURE			
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION			
BENTS:	TIMBER PILE BENT ON PILE FOUND	DATION			
PIERS:	NOT APPLICABLE				
		SCOUR EVALUATION			
	our critical; bridge foundations de ling scour countermeasures.	termined to be unstable for calculated scour conditions. Monitor bridge in			
		INSPECTION PROCEDURES			
What Initiated the Call-out Inspection?		[] BridgeWatch Alert			
		[] TDOT District or Local Maintenance Personnel			
		[] THP or Local Law Enforcement Personnel			
		[] Other:			
1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, an	n along curb line, both bridge rails and outer edge of bridge deck. nts.			
If Closure is	recommended:				
Coun temp	nty or City Maintenance Person	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may			
[] - Conta	upervisor (if bridge is State maintained)				
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)			
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate			
	(4) TDOT Regional Bridge	Engineer			
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 				

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	a detour route. Any bridge o	trict maintenance or local highway maintenance on the selected detour route shall be checked		
[] - The bridge can be re-ope units and they are determ	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 			
CONTACT PERSONNEL:		TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE		(731) 286-7800		
HWY. CHIEF ADMINISTRATOR	N'S OFFICE	(731) 286-7838		
COUNTY SHERIFF'S OFFICE		(731) 285-2802		
The report shall include t as appropriate, photogra	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:				
Suggested List of Equipment to Latest Bridge Inspection Repo	-			
Scour POA Report with the abo	ove Checklist			
Bridge Design Plans, if availab	le			
Tape measure with weight				
Plumb bob				
Range Pole				
•	• •	rinted with the following message:		
9.0	VEELA HVAVABU KEED VMV	V		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24