## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 27SR1040011
BRIDGE OWNER: GIBSON COUNTY
ROAD NAME: OLD SR104

CROSSING: BRANCH

LATITUDE:: N 35.98606 DEGREES

ROUTE: 02488
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.00
YEAR BUILT: 1978

COUNTY: GIBSON

LON	NGITUDE: W 89.02269 DEGREES	YEAR BUILT: 1978	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES -	
What Initiat	ted the Call-out Inspection?	[ ] BridgeWatch Alert	
		[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
[ ] - Span 1. 0 2. 0 [ ] - Chec [ ] - Chec	Check for plumb of piers or being the control of th	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.	
<u>If Closure is</u>	recommended:		
Cour temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )	
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )	
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in		State District maintenance or local highway maintenance y bridge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PE	RSONNEL:	TELEPHONE NUMBER:	
COUNTY MAY	OR'S OFFICE	(731) 855-7611	
HWY. CHIEF	ADMINISTRATOR'S OFFICE	(731) 855-7684	
COUNTY SHE	RIFF'S OFFICE	(731) 855-1121	
The report s	] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of	f Equipment to conduct the Insp	pection:	
Latest Bridge Ins	pection Report		
Scour POA Repor	rt with the above Checklist		
Bridge Design Pla	ans, if available		
Tape measure wi	th weight		
Plumb bob			
Range Pole			
A 1000 Foot Roll	•	e Tape printed with the following message:	
	SAFETY HAZARD KE	EEP AWAY	

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24