## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 360A2370003
BRIDGE OWNER: HARDIN COUNTY
ROAD NAME: CHERRY CHAPEL LP
CROSSING: LEFT FORK WHITES CREEK
LATITUDE:: N 35.08861 DEGREES

LONGITUDE: W 88.04492 DEGREES

COUNTY: HARDIN
ROUTE: 01742
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 6.63
YEAR BUILT: 1977

		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	OR GIRDER APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	ENT ON ROCK FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE SOLID SHAFT PIER ON	I ROCK FOUNDATION	
		SCOUR EVALUATION	
Bridge has u	inknown foundations. Risk of sco	our cannot be determined. The bridge shall be monitored for distress	
		e in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiat	ad the Call and Increasion?		
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
		[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
Things to c	heck on a bridge during flood	<u>s:</u>	
[ ] - Snan	movement - horizontally as w	vell as vertically	
	-	on along curb line, both bridge rails and outer edge of bridge deck.	
	Check for plumb of piers or be		
	k for embankment erosion		
[ ] - Check for drift build-up on piers or bents			
[ ] - Check pier exposure, if possible, and compare to previous inspection			
[ ] - Review the latest bridge inspection report versus current field conditions			
[ ] Novio	in the latest bridge mapeonen	Troport Volcus current field conditions	
If Closure is	recommended:		
[ ] - Stav a	at bridge with vehicle pulled a	cross road until bridge is secured and properly closed by District,	
	•	nnel. Use Barricade Tape, traffic cones and/or traffic flares as	
		rists to stay off of the bridge until such time as the bridge may	
•	operly closed and barricaded.		
[ ] - Conta	` '	Supervisor ( if bridge is State maintained )	
		y Maintenance Official ( if bridge is not State maintained )	
	` '	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	_	
	Bridge should remain closed u FDOT bridge inspection team.	Intil the water recedes and a daylight visual inspection is made	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance y bridge on the selected detour route shall be checked		
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 925-9078		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 925-4993		
COUNTY SHERIFF'S OFFICE	(731) 925-3377		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Insp  Latest Bridge Inspection Report	pection:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricad			
SAFFTY HAZARD KE	-EP AWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24