## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 360A2450001
BRIDGE OWNER: HARDIN COUNTY
ROAD NAME: BEULAH GEAN RD
CROSSING: LEFT FORK WHITES CREEK

CROSSING: LEFT FORK WHITES CREEK
LATITUDE:: N 35.08614 DEGREES
LONGITUDE: W 87.99072 DEGREES

COUNTY: HARDIN
ROUTE: 0A245
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.34
VEAP BUILT: 1993

LON	GITUDE: W 87.99072 DEGREES	3	YEAR BUILT: 1992
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	WOOD OR TIMBER - STRINGER/MU GIRDER	ILTI-BEAM OR APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOL	INDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
	nknown foundations. Risk of scant flood events. Monitor bridg	our cannot be determined. The	bridge shall be monitored for distress ntermeasures.
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
		[ ] TDOT District or Loc	al Maintenance Personnel
		[ ] THP or Local Law En	forcement Personnel
		[ ] Other:	
1. C 2. C [ ] - Chec [ ] - Chec [ ] - Chec	movement - horizontally as we heck displacement / deflection when the heck for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, as the latest bridge inspection	n along curb line, both bridg nts. bents nd compare to previous insp	
f Closure is	recommended:		
Coun temp	ty or City Maintenance Persoi	nnel. Use Barricade Tape, tra rists to stay off of the bridge	cured and properly closed by District, iffic cones and/or traffic flares as until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	Supervisor ( if bridge is State	e maintained )
	(2) City or County Highwa	y Maintenance Official ( if b	ridge is not State maintained )
	(3) Tennessee Highway P	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed u FDOT bridge inspection team.		daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in		State District maintenance or local highway maintenance bridge on the selected detour route shall be checked	
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PE	RSONNEL:	TELEPHONE NUMBER:	
COUNTY MAY	OR'S OFFICE	(731) 925-9078	
HWY. CHIEF A	ADMINISTRATOR'S OFFICE	(731) 925-4993	
COUNTY SHE	RIFF'S OFFICE	(731) 925-3377	
The report s	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
Suggested List of	Equipment to conduct the Insp	ection:	
Latest Bridge Ins	pection Report		
Scour POA Repor	t with the above Checklist		
Bridge Design Pla	ıns, if available		
Tape measure wit	h weight		
Plumb bob			
Range Pole			
A 1000 Foot Roll of	•	e Tape printed with the following message:	
	SAFETY HAZARD KE	EP AWAY	

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24