HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 390A0010001

BRIDGE OWNER: HENDERSON COUNTY

ROAD NAME: ROCK MILAM

CROSSING: M. FK. FORKED DEER RIVER
LATITUDE:: N 35.74481 DEGREES
LONGITUDE: W 88.55483 DEGREES

COUNTY: HENDERSON
ROUTE: 0A001
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 4.90
YEAR BUILT: 1950

LON	NGH ODE. W 66.33463 DEGREES	I LAN BOILT. 1930
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL - GIRDER AND FLOORBEAM	SYSTEM APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE -
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		ur cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES -
What Initiate	ed the Call-out Inspection?	[] BridgeWatch Alert
	·	[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
[] - Span 1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or l k pier exposure, if possible, an	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. hts.
f Closure is	recommended:	
Coun temp	ity or City Maintenance Person	eross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)
	(2) City or County Highwa	Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed ui TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ith State District maintenance or local highway maintenance Any bridge on the selected detour route shall be checked	
] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(731) 968-0122	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 968-9201	
COUNTY SHERIFF'S OFFICE	(731) 968-7777	
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:		
Suggested List of Equipment to conduct the I	Inspection:	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barrio	cade Tape printed with the following message:	
SAFETY HAZARD	KEEP AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24