HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 390A0490001

BRIDGE OWNER: HENDERSON COUNTY ROAD NAME: **NEW STANFORD RD**

CROSSING: OVERFLOW

COUNTY: HENDERSON ROUTE: 0A049 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	TITUDE:: N 35.72642 DEGREES NGITUDE: W 88.19064 DEGREES		
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	WOOD OR TIMBER - STRINGER/MU GIRDER		
		TYPE OF SUBSTRUCTURE	
	TIMBER CAP ON TIMBER PILE FOU	NDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
Things to c	heck on a bridge during floods	<u>s:</u>	
	movement - horizontally as w	•	
	-	n along curb line, both bridge rails and outer edge of bridge deck.	
	Check for plumb of piers or be	nts.	
	k for embankment erosion		
] - Check for drift build-up on piers or bents		
] - Check pier exposure, if possible, and compare to previous inspection			
[] - Revie	ew the latest bridge inspection	report versus current field conditions	
lf Closure is	recommended:		
Coun temp	ity or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
[] - Conta	ct: (1) District Maintenance Supervisor (if bridge is State maintained)		
_	• •	y Maintenance Official (if bridge is not State maintained)	
	` ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge		
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	tate District maintenance or local highway maintenance bridge on the selected detour route shall be checked	
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructuunits and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(731) 968-0122	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 968-9201	
COUNTY SHERIFF'S OFFICE	(731) 968-7777	
as appropriate, photographs of the bridge ar	the inspection, a brief summary of findings and, and stream channel measurements. If significant be copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to conduct the Inspe	ection:	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade	Tape printed with the following message:	
SAFETY HAZARD KEI	EP AWAY	
A Barricade Tape Dispenser with serrated cutter		

PUBLICATION DATE
17-Apr-19

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

BRIDGE ID 390A0490001