HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 43018060005

BRIDGE OWNER: HUMPHREYS COUNTY
ROAD NAME: BROWN HILL RD
CROSSING: RICHLAND CREEK

LATITUDE:: N 36.14668 DEGREES
LONGITUDE: W 87.70602 DEGREES

COUNTY: HUMPHREYS

ROUTE: 01806

SPECIAL CASE: 0

COUNTY SEQUENCE: 1

LOG MILE: 3.11

	GITUDE: W 87.70602 DE	GREES	YEAR BUILT: 1974
MAIN SPAN:	PRESTRESSED CONCRETE GIRDERS - MULTIPLE	- BOX BEAM OR AP	PR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUC	TURE
ABUTMENTS: BENTS:	CONCRETE FULL HEIGHT A	BUTMENT ON CONCRETE SPR	EAD FOOTING FOUNDATION
PIERS:	CONCRETE SOLID SHAFT F	IER ON UNKNOWN FOUNDATION)N
		SCOUR EVALUAT	ION
		of scour cannot be determ r bridge in lieu of installing s	ined. The bridge shall be monitored for distress cour countermeasures.
		INSPECTION PROCE	DURES
What Initiated the Call-out Inspection?		on? [] BridgeWatc	h Alert
		[] TDOT Distri	ct or Local Maintenance Personnel
		[] THP or Loca	l Law Enforcement Personnel
		[] Other:	
[] - Span 1. C 2. C [] - Check [] - Check	heck for plumb of piers of for embankment erosi of for drift build-up on pi of pier exposure, if possi	y as well as vertically flection along curb line, b or bents. on	-
lf Clasura is	recommended:		
[] - Stay a Coun- tempo be pro	ty or City Maintenance I orary measures to warn operly closed and barrio act: (1) District Maintena (2) City or County H	Personnel. Use Barricade motorists to stay off of the aded. ance Supervisor (if bridgighway Maintenance Office way Patrol and/or local law	dge is secured and properly closed by District, Tape, traffic cones and/or traffic flares as ie bridge until such time as the bridge may e is State maintained) cial (if bridge is not State maintained) w enforcement Officers as appropriate

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	- The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.		
] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 296-7795		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 296-2121		
COUNTY SHERIFF'S OFFICE	(931) 296-2301		
The report shall include the date and time of the as appropriate, photographs of the bridge and s	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	on:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Tap			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

17-Apr-19