## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: JACKSON

BRIDGE ID NUMBER: 44SR0850007

BRIDGE OWNER: STATE OF TENNESSEE
ROAD NAME: OLD SR85 HWY
CROSSING: JENNINGS CREEK

LATITUDE:: N 36.41967 DEGREES
LONGITUDE: W 85.67327 DEGREES

ROUTE: SR085
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 15.07

LON	NGITUDE: W 85.67327 DEGREES	YEAR BUILT: 1981	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	PRESTRESSED CONCRETE CONTIL STRINGER/MULTI-BEAM OR GIRDE		
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON S	TEEL PILE FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE HAMMERHEAD PIER O	STEEL PILE FOUNDATION	
		SCOUR EVALUATION	
•	our critical; bridge foundations de ling scour countermeasures.	termined to be unstable for calculated scour conditions. Monitor bridge in	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
	·	[ ] TDOT District or Local Maintenance Personnel	
		THP or Local Law Enforcement Personnel	
		[ ] Other:	
1. C 2. C [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	n along curb line, both bridge rails and outer edge of bridge deck. nts.	
If Closure is	recommended:		
Coun temp	ity or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )	
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	ne Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ate District maintenance or local highway maintenance oridge on the selected detour route shall be checked		
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(423) 290-7467		
DISTRICT MAINTENANCE SUPERVISOR	(931) 267-6324		
TENNESSEE HIGHWAY PATROL	(931) 528-8496		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspectatest Bridge Inspection Report Scour POA Report with the above Checklist	ction:		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade			
SAFETY HAZARD KEE	ΡΑΜΑΥ		

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

**TDOT radio directory (State Personnel only)** 

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape