## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 45S24130001

BRIDGE OWNER: JEFFERSON COUNTY ROAD NAME: DUMPLIN VALLEY RD CROSSING: PIEDMONT BRANCH LATITUDE:: N 36.02180 DEGREES LONGITUDE: W 83 53210 DEGREES

COUNTY: **JEFFERSON** ROUTE: 0A137 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.33

VEAR BILLT: 10/0

LON	NGHODE. W 63.33210 DEGREES	•	TEAN BOILT. 1940
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
Bridge bas I	unknown foundations. Pick of soc		bridge shall be monitored for distress
•	icant flood events. Monitor bridge		•
		INSPECTION PROCEDURES =	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
	·	•	al Maintenance Personnel
		[ ] THP or Local Law En	forcement Personnel
		[ ] Other:	
1. 0 2. 0 [ ] - Chec [ ] - Chec [ ] - Chec	movement - horizontally as we heck displacement / deflection the heck for plumb of piers or be known for embankment erosion known for drift build-up on piers or known exposure, if possible, and the latest bridge inspection	n along curb line, both bridg nts. bents nd compare to previous insp	
[ ] - Stay a	nty or City Maintenance Persor	nnel. Use Barricade Tape, tra	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
-	operly closed and barricaded.		
[ ] - Conta	act: (1) District Maintenance S	• •	•
	`, ,	•	ridge is not State maintained )
	• •		ement Officers as appropriate
<b></b>	(4) TDOT Regional Bridge	· ·	
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a	daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	a detour route. Any bridge o	rict maintenance or local highway maintenance in the selected detour route shall be checked		
[ ] - The bridge can be re-ope units and they are determ	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL:		TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE		(865) 397-3800		
HWY. CHIEF ADMINISTRATOR	R'S OFFICE	(865) 397-2155		
COUNTY SHERIFF'S OFFICE		(865) 397-9411		
The report shall include t as appropriate, photogra	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:				
Suggested List of Equipment t	-			
Latest Bridge Inspection Repo				
Scour POA Report with the abo Bridge Design Plans, if availab				
Tape measure with weight	ie			
Plumb bob				
Range Pole				
_	ethylene Barricade Tape pr	inted with the following message:		
•	VEETA HAZABU KEED VANA			

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24