HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 550A0820001
BRIDGE OWNER: McNAIRY COUNTY
ROAD NAME: BEAUTY HILL RD

CROSSING: SULPHUR SPRINGS BRANCH
LATITUDE:: N 35.29000 DEGREES
LONGITUDE: W 88.50383 DEGREES

COUNTY: McNAIRY
ROUTE: 0A082
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 4.36
YEAR BUILT: 1977

		TYPE OF SUPERSTRUCTURE =	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	INDATION	
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
Bridge is sco	our critical: bridge foundations de	etermined to be unstable for cal	culated scour conditions. No scour
	sures are installed but they are n		
		INSPECTION PROCEDURES =	
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert	
			al Maintenance Personnel
		[] THP or Local Law Enf	
Things to c	heck on a bridge during floods	<u>s:</u>	
[] - Span	movement - horizontally as w	ell as vertically	
		•	e rails and outer edge of bridge deck.
	Check for plumb of piers or be		
[] - Chec	k for embankment erosion		
[] - Chec	k for drift build-up on piers or	bents	
	k pier exposure, if possible, ar		ection
	ew the latest bridge inspection	·	
	•	•	
<u>If Closure is</u>	<u>recommended:</u>		
Cour	nty or City Maintenance Persor	nnel. Use Barricade Tape, traf	eured and properly closed by District, ific cones and/or traffic flares as until such time as the bridge may
•	operly closed and barricaded.		undi Such dine as the bridge may
-	act: (1) District Maintenance S		maintained)
	• •		idge is not State maintained)
		atrol and/or local law enforce	•
	(4) TDOT Regional Bridge		
[] - The E	Bridge should remain closed u	ntil the water recedes and a	daylight visual inspection is made

PUBLICATION DATE

by a TDOT bridge inspection team.

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	work with State District maintenance or local highway maintenance route. Any bridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 645-3472		
HWY. CHIEF ADMINISTRATOR'S OFFIC	E (731) 645-3651		
COUNTY SHERIFF'S OFFICE	(731) 645-1000		
The report shall include the date as appropriate, photographs of t	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:			
Suggested List of Equipment to condu	uct the Inspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Che	cklist		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylen	e Barricade Tape printed with the following message:		
SAFETY H	IAZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24