HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 550A5420001 BRIDGE OWNER: McNAIRY COUNTY ROAD NAME: LILLY TAYLOR RD CROSSING: MOSSES CREEK

LATITUDE" N 35.09839 DEGREES

COUNTY: McNAIRY ROUTE: 0A542 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 1 54

LON	IGITUDE: W 88.75642 DEGREES	YEAR BUILT: 1986
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE - STRIN OR GIRDER	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	CONCRETE PILE FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	CONCRETE HAMMERHEAD PIER O	N CONCRETE PILE FOUNDATION
		SCOUR EVALUATION ————————————————————————————————————
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
	·	[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[] Other:
1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	n along curb line, both bridge rails and outer edge of bridge deck. nts.
[] - Stay a Coun temp	ity or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
- Contact: (1) District Maintenance Supervisor(if bridge is State maintained)		
	` '	y Maintenance Official (if bridge is not State maintained)
		atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	•••
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance ridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 645-3472		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 645-3651		
COUNTY SHERIFF'S OFFICE	(731) 645-1000		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Inspec	tion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole A 1000 Foot Roll of yellow Polyethylene Barricade T	and printed with the following massage:		
SAFETY HAZARD KEEP			

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape