HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 570A3360001 BRIDGE OWNER: MADISON COUNTY ROAD NAME: CEDARFIELD RD CROSSING: BEAR CREEK

LATITUDE:: N 35.47936 DEGREES

COUNTY: MADISON ROUTE: 0A336 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 3.71

LON	NGITUDE: W 88.76111 DEGREES	YEAR BUILT: 1982	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE CONTINUOUS - CULVE FRAME CULVERTS)	RT (INCLUDES APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE BOX TYPE ON CONCRE	TE SPREAD FOOTING FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	PIER WALL FOR CONCRETE BOX O	N CONCRETE SPREAD FOOTING FOUNDATION	
		SCOUR EVALUATION	
	our critical; bridge foundations de sures are installed but they are n	termined to be unstable for calculated scour conditions. No scour eeded.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
1. 0 2. 0 [] - Chec [] - Chec	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	n along curb line, both bridge rails and outer edge of bridge deck. ats.	
If Closure is	recommended:		
Coun temp	nty or City Maintenance Person	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may	
-			
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)	
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance by bridge on the selected detour route shall be checked	
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(731) 423-6020	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 422-1651	
COUNTY SHERIFF'S OFFICE	(731) 423-6000	
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:		
Suggested List of Equipment to conduct the Insp	ection:	
Latest Bridge Inspection Report Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade	e Tape printed with the following message:	
SAFETY HAZARD KE		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24