HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 630A6150001 COUNTY: MONTGOMERY

BRIDGE OWNER: MONTGOMERY COUNTY

ROAD NAME: RAWLINGS RD

CROSSING: BLOOMING GROVE CREEK
LATITUDE:: N 36.47987 DEGREES
LONGITUDE: W 87.52302 DEGREES

ROUTE: 0A615
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.67

LON	IGITUDE: W 87.52302 DEGREES		YEAR BUILT: 1976	
		TYPE OF SUPERSTRUCTURE =		
MAIN SPAN:	PRESTRESSED CONCRETE CONTIL STRINGER/MULTI-BEAM OR GIRDE		NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE -		
ABUTMENTS:	MENTS: CONCRETE STUB ABUTMENT ON STEEL PILE FOUNDATION			
BENTS:	NOT APPLICABLE			
PIERS:	CONCRETE HAMMERHEAD PIER O	N CONCRETE SPREAD FOOTING F	OUNDATION	
		SCOUR EVALUATION -		
	our critical; bridge foundations de stalled and is in fair condition. So		culated scour conditions. Rip-rap protection tion system are needed.	
		INSPECTION PROCEDURES =		
What Initiated the Call-out Inspectio		[] BridgeWatch Alert		
		[] TDOT District or Loca	al Maintenance Personnel	
		[] THP or Local Law En		
		[] Other:		
[] - Span 1. C 2. C [] - Chec [] - Chec	heck on a bridge during floods movement - horizontally as we check displacement / deflection check for plumb of piers or bein k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar ew the latest bridge inspection	ell as vertically n along curb line, both bridg nts. bents nd compare to previous insp		
<u>lf Closure is</u>	recommended:			
Coun temp	ity or City Maintenance Persor	nel. Use Barricade Tape, tra	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may	
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State	maintained)	
		•	ridge is not State maintained)	
	• • • • • • • • • • • • • • • • • • • •		ement Officers as appropriate	
	(4) TDOT Regional Bridge			
	ridge should remain closed until the water recedes and a daylight visual inspection is made DOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ishing a detour route. Any b	ate District maintenance or local highway maintenance ridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONN	EL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S C	FFICE	(931) 648-5787		
HWY. CHIEF ADMINI	STRATOR'S OFFICE	(931) 648-5740		
COUNTY SHERIFF'S	OFFICE	(931) 648-0611		
The report shall in as appropriate, pl	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:				
Suggested List of Equi	oment to conduct the Inspec	etion:		
Latest Bridge Inspectio	n Report			
Scour POA Report with	the above Checklist			
Bridge Design Plans, if	available			
Tape measure with wei	ght			
Plumb bob				
Range Pole				
A 1000 Foot Roll of yell	• •	Γape printed with the following message:		
	SAFETY HAZARD KEEI	P AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24