HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 630A6280001

BRIDGE OWNER: MONTGOMERY COUNTY

ROAD NAME: MOODY RD
CROSSING: ANTIOCH CREEK

LATITUDE:: N 36.44202 DEGREES
LONGITUDE: W 87.39195 DEGREES

COUNTY: MONTGOMERY
ROUTE: 0A628
SPECIAL CASE: 0
COUNTY SEQUENCE: 1

LOG MILE: 1.47 YEAR BUILT: 1974

		TYPE OF SUPE	DSTDUCTURE -	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O		APPR. SPAN:	NOT APPLICABLE
		7/25 05 011	OTD. 10T. 1D.F	
ADLITMENTS.	CONCRETE FULL HEIGHT ARLITME	TYPE OF SUB		INC FOLINDATION
	CONCRETE FULL HEIGHT ABUTME	NI ON CONCRE	E SPREAD FOOT	ING FOUNDATION
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EV	ALUATION -	
•	unknown foundations. Risk of sco icant flood events. Monitor bridge			bridge shall be monitored for distress termeasures.
		INSPECTION F	ROCEDURES -	
What Initiat	ed the Call-out Inspection?	[] Bridge	Watch Alert	
				al Maintenance Personnel
				forcement Personnel
Things to c	heck on a bridge during floods	<u>s:</u>		
[] - Snan	movement - horizontally as w	ell as verticall	v	
	•	,		e rails and outer edge of bridge deck.
	Check for plumb of piers or be	_	ine, both bridg	o rano ana oater cage or briage acon.
	k for embankment erosion	113.		
	k for drift build-up on piers or	hents		
	k pier exposure, if possible, ar		provious insp	action
	ew the latest bridge inspection	-		
[] - Revie	ew the latest bridge inspection	report versus	current neid d	conditions
If Closure is	recommended:			
		cross road un	til hridge is seg	cured and properly closed by District,
Cour temp	nty or City Maintenance Persor	nel. Use Barri ists to stay of	cade Tape, tra	ffic cones and/or traffic flares as until such time as the bridge may
-	act: (1) District Maintenance S		bridge is State	e maintained)
	• •	•	_	ridge is not State maintained)
	` ' '	•	•	ement Officers as appropriate
	(4) TDOT Regional Bridge			
[] - The E	``	•	ecedes and a	daylight visual inspection is made
	TDOT bridge inspection team			,

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance bridge on the selected detour route shall be checked			
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 			
CONTACT PERSONNEL:	TELEPHONE NUMBER:			
COUNTY MAYOR'S OFFICE	(931) 648-5787			
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 648-5740			
COUNTY SHERIFF'S OFFICE	(931) 648-0611			
 - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 				
COMMENTS:				
Suggested List of Equipment to conduct the Inspectatest Bridge Inspection Report Securi ROA Report with the characterist	ection:			
Scour POA Report with the above Checklist Bridge Design Plans, if available				
Tape measure with weight				
Plumb bob				
Range Pole				
A 1000 Foot Roll of yellow Polyethylene Barricade	Tape printed with the following message:			
SAFETY HAZARD KE	EP AWAY			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24