HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 660A0220003 BRIDGE OWNER: OBION COUNTY ROAD NAME: WILLIAMS RD.

CROSSING: SOUTH REELFOOT CREEK

ROUTE: 0A022 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 3.40

COUNTY: OBION

	NGITUDE:: N 36.35880 DEGREES NGITUDE: W 89.28097 DEGREES	LOG MILE: 3.49 YEAR BUILT: 2008
LOI	OFFICIAL W 69.20097 DEGREES	TEAR BOILT. 2000
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE - BOX B GIRDERS - MULTIPLE	EAM OR APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTMEN	NT ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		hat extensive scour has occurred at bridge foundations. Immediate action . Monitor bridge in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[] Other:
[] - Span 1. 0 2. 0 [] - Chec [] - Chec	Check for plumb of piers or ben k for embankment erosion k for drift build-up on piers or b k pier exposure, if possible, an	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.
If Closure is	recommended:	
Coun temp	ity or City Maintenance Person	ross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as sts to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)
	(2) City or County Highway	Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



offic		te District maintenance or local highway maintenance idge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONT	ACT PERSONNEL:	TELEPHONE NUMBER:	
COUN	NTY MAYOR'S OFFICE	(731) 885-9611	
HWY.	CHIEF ADMINISTRATOR'S OFFICE	(731) 885-5960	
COUN	ITY SHERIFF'S OFFICE	(731) 885-5832	
The r	eport shall include the date and time of the propriate, photographs of the bridge and	ection to BridgeWatch scour monitoring system. see inspection, a brief summary of findings and, stream channel measurements. If significant copied to Bridge Inspection Headquarters.	
COMMENTS			
<u>Suggested</u>	List of Equipment to conduct the Inspect	ion:	
	ge Inspection Report		
	Report with the above Checklist		
_	ign Plans, if available		
-	ure with weight		
Plumb bob			
Range Pole		one printed with the following message:	
A IUUU FOO	ot Roll of yellow Polyethylene Barricade Ta SAFETY HAZARD KEEP		
	SAFELL HAZARD NEEP	AVAI	

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape