## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 660A0980001 BRIDGE OWNER: OBION COUNTY ROAD NAME: W STATE LINE RD CROSSING: BRANCH

LATITUDE:: N 36.50544 DEGREES

COUNTY: OBION ROUTE: 0A098 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.53

LON	NGITUDE: W 89.20203 DEGREE	S	YEAR BUILT: 1970	
MAIN CDAN	CONCRETE CHANNEL DEAM	TYPE OF SUPERSTRUCTURE	NOT ADDITION F	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE -		
ABUTMENTS:	ENTS: CONCRETE FULL HEIGHT ABUTMENT ON UNKNOWN FOUNDATION			
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EVALUATION		
		cour cannot be determined. The ge in lieu of installing scour coun	bridge shall be monitored for distress termeasures.	
		<ul> <li>INSPECTION PROCEDURES</li> </ul>		
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert		
	•	[ ] TDOT District or Loca	al Maintenance Personnel	
		[ ] THP or Local Law Enf	forcement Personnel	
Things to c	heck on a bridge during flood	<u>ls:</u>		
[ ] - Span	movement - horizontally as v	vell as vertically		
	•	•	e rails and outer edge of bridge deck.	
	Check for plumb of piers or be			
	k for embankment erosion			
	k for drift build-up on piers or	r bents		
	• •	and compare to previous inspe	ection	
Review the latest bridge inspection report versus current field conditions				
<u>If Closure is</u>	recommended:			
Coun temp	ity or City Maintenance Perso	nnel. Use Barricade Tape, traf orists to stay off of the bridge	eured and properly closed by District, ific cones and/or traffic flares as until such time as the bridge may	
[ ] - Conta				
	(2) City or County Highw	ay Maintenance Official ( if br	idge is not State maintained )	
	`, `	Patrol and/or local law enforce	•	
	(4) TDOT Regional Bridg			
[ ] - The E	`,		daylight visual inspection is made	
	TDOT bridge inspection team		, <b>0</b>	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officia		e District maintenance or local highway maintenance dge on the selected detour route shall be checked		
	he bridge can be re-opened only after a TDOT bridge inspection team checks the substructure nits and they are determined to be structurally stable.			
CONTA	ACT PERSONNEL:	TELEPHONE NUMBER:		
COUNT	TY MAYOR'S OFFICE	(731) 885-9611		
HWY. C	CHIEF ADMINISTRATOR'S OFFICE	(731) 885-5960		
COUNT	TY SHERIFF'S OFFICE	(731) 885-5832		
[ ] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.				
COMMENTS:				
Suggested L	List of Equipment to conduct the Inspection	on:		
_	ge Inspection Report			
	Report with the above Checklist			
•	gn Plans, if available			
Plumb bob	re with weight			
Range Pole				
•	Roll of yellow Polyethylene Barricade Ta	pe printed with the following message:		
	SAFETY HAZARD KEEP			
	<b>T D</b> ' '41 ' 1 ''			

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

**TDOT radio directory (State Personnel only)**