HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 85020880003

BRIDGE OWNER: TROUSDALE COUNTY

ROAD NAME: **OLD HWY 25**CROSSING: **SECOND CREEK**

LATITUDE:: N 36.38849 DEGREES LONGITUDE: W 86.20962 DEGREES

COUNTY: TROUSDALE
ROUTE: 02088
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.45

LON	NGHUDE: W 86.20962 DEGREES		YEAR BUILT: 1950
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
	unknown foundations. Risk of scr icant flood events. Monitor bridg		bridge shall be monitored for distress termeasures.
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection		[] BridgeWatch Alert	
		[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
[] - Span 1. 0 2. 0 [] - Chec [] - Chec	heck on a bridge during floods movement - horizontally as we check displacement / deflection check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, and the latest bridge inspection	ell as vertically n along curb line, both bridg nts. bents nd compare to previous inspe	
f Closure is	recommended:		
Cour temp	nty or City Maintenance Persor	nnel. Use Barricade Tape, tra rists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	e maintained)
	(2) City or County Highwa	y Maintenance Official (if bi	ridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed u TDOT bridge inspection team.		daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ork with State District maintenance or local highway maintenance oute. Any bridge on the selected detour route shall be checked		
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(615) 374-2461		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(615) 374-2961		
COUNTY SHERIFF'S OFFICE	(615) 374-2114		
The report shall include the date at as appropriate, photographs of the	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:			
Suggested List of Equipment to conduct	the Inspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Check	dist		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene	Barricade Tape printed with the following message:		
SAFETY HA	ZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24