

**DAVIDSON COUNTY I-440 BRIDGES REPAIRS ESTIMATED QUANTITIES**

<b>BRIDGE NUMBER /CROSSING</b>	<b>BRIDGE ID NO</b>	<b>CONCRETE REPAIR (PARTIAL DEPTH OF APPROACH PVT.) SY</b>	<b>CONCRETE REPAIR (FULLL DEPTH OF APPROACH PVT.) SY</b>	<b>BRIDGE DECK REPAIR (PARTIAL DEPTH OF THE SLAB) SY</b>	<b>BRIDGE DECK REPAIR (FULL DEPTH OF THE SLAB) SY</b>	<b>NOTE</b>
19-I440-0.36 R / CHARLOTTE AVE.	19I04400001	15		30		
19-I440-0.36 L / CHARLOTTE AVE.	19I04400002	10		20		MOST PART OF BOTH APROACH PVTs AND PART OF THE BRIDGE AT ABUT. 1 SIDE ARE COVERED WITH ASPHALT
19-I440-.72 R / CSX	19I04400003	10		10		MOST PART OF BOTH APROACH #2 PVTs and PART OF THE BRIDGE AT ABUT 2 SIDE COVERED WITH ASPHALT
19-I440-.72 L / CSX	19I04400004	50	40	50		APPROACH #1 HAS DEEP BREAKOUTS
19-I440-4.17R / LELAND LANE	19I04400027	20		20		
19-I440-4.17L / LELAND LANE	19I04400028	30		60		THE PATCH IS ON THE BIDGE SIDE
19-I440-4.36 R/ CRAIG AVE	19I04400029	15		10		
19-I440-4.36 L / CRAIG AVE	19I04400030	25		60	2 PANELS AT 2ND & 4TH BAYS (ABUT. # 1) 8 SY	THE PATCH IS ON THE BRIDGE
19-I440-5.44 EBL / BRANDSFORD AVE.	19I4400041	30	40	30		HEAVY CRACKS AT ABUT. 2 AND THE BRIDGE HAS TWO APPROACHES PAVEMENTS ON BOTH SIDES OF ABUTS.
19-I440-5.44 WBL / BRANDSFORD AVE.	19I4400041	100	80	80		HEAVY CRACKS AT ABUT. 1 AND THE BRIDGE HAS TWO APPROACHES PAVEMENTS ON BOTH SIDES OF ABUTS.