



222 Second Avenue South Suite 1400, Nashville, TN 37219

|                 |  |                        |               |
|-----------------|--|------------------------|---------------|
| <b>PROJECT:</b> | TDOT Utility On-Call I-440 -<br>Subsurface Utility Engineering<br>41200.04 | <b>DATE:</b>           | 10/29/2017    |
| <b>SUBJECT:</b> | PIN 125325.00: I-440 SUE<br>Information - Video Submittal 3 (1 of<br>3)    | <b>TRANSMITTAL ID:</b> | 00013         |
| <b>PURPOSE:</b> | For information  | <b>VIA:</b>            | Info Exchange |

**FROM**

| NAME  | COMPANY                        | EMAIL              | PHONE            |
|---|--------------------------------|--------------------|------------------|
| CJ Tong<br>222 Second Avenue South<br>Suite 1400<br>Nashville TN 37219<br>United States | Gresham, Smith and<br>Partners | cj_tong@gspnet.com | 615-770-8247x217 |

**TO**

| NAME                      | COMPANY | EMAIL                     | PHONE |
|---------------------------|---------|---------------------------|-------|
| Philip.Berdis@arcadis.com |         | Philip.Berdis@arcadis.com |       |
| Clint.Butler@arcadis.com  |         | Clint.Butler@arcadis.com  |       |

|                 |   |
|-----------------|---|
| <b>REMARKS:</b> | <p>Philip,</p> <p>This is part 1 of a series of 3 emails for the videos. These videos correspond to locations previously processed and provided to you. The CADD file is an updated version provided to you yesterday.</p> <p>There are several items to note from the videos:</p> <ul style="list-style-type: none"> <li>• Storm 4: JB 10 has a small corrugated pipe stubbed into the structure. This doesn't seem to be in the survey or previous plans.</li> <li>• Storm 4D: JB 16's bottom is a sump.</li> <li>• Storm 5: the full run of pipe could not be completed due to debris at approximately station 1128+46.</li> <li>• Storm 6 to Storm 6A: the full run of pipe could not be completed due to debris at approximately station 1139+55 to 1139+95.</li> </ul> <p>Also, note that on the section WE11 to WE 10, provided yesterday, there is major infiltration at the joints. The video captures flowing water and water squirting from the joints.</p> <p>If you have any questions please let us know.</p> <p>Thank you.</p> |
|-----------------|---|

|                 |            |
|-----------------|------------|
| DATE:           | 10/29/2017 |
| TRANSMITTAL ID: | 00013      |

## DESCRIPTION OF CONTENTS

| QTY | DATED      | TITLE                         | NOTES |
|-----|------------|-------------------------------|-------|
| 1   | 9/13/2017  | I 440-JB 23-JB 22-I 440.mpg   |       |
| 1   | 9/14/2017  | I 440-JB 24-JB 23-I 440.mpg   |       |
| 1   | 9/14/2017  | I 440-JB 25-JB 24-I 440.mpg   |       |
| 1   | 9/14/2017  | I 440-JB 26-JB 25-I 440 .mpg  |       |
| 1   | 9/18/2017  | I 440-JB 30-JB 28-I 440.mpg   |       |
| 1   | 8/30/2017  | I 440-JB7-JB 6-I 440.mpg      |       |
| 1   | 10/26/2017 | I 440-JB15-JB16-I 440.mpg     |       |
| 1   | 10/26/2017 | I 440-WE14-JB15-I 440.mpg     |       |
| 1   | 10/4/2017  | I 440-HPCB 1-JB 26-I 440 .mpg |       |
| 1   | 8/30/2017  | I 440-JB 10-WE12-I440.mpg     |       |

## COPIES:

|                    |   |
|--------------------|---|
| Mark Holloran      | (Gresham, Smith and Partners)                   |
| Cody Crews         | (Gresham, Smith and Partners)                   |
| Wes Stanton        | (Gresham, Smith and Partners)                   |
| Lori Lange         | (Tennessee Department of Transportation (TDOT)) |
| Joe.Deering@tn.gov |   |