

19104400004 19-10440-0.72 LT 1440 LL/CSX RR

BRIDGE MAINTENANCE RECOMMENDATIONS COUNTY: DAVIDSON LOCATION: 19-I0440-00.72-L CO. SEQ.: 1 SPEC. CASE: 0 MILEPOST: 0.63 CROSSING: I440-LL / CSX RR REPA FED. BRIDGE NO.: 19I04400004

MAINT. DIST.: 19

Г



REPAI	IR LIST	NO.:	N
DATE	ADDED:		
REVIS	SED:	04/01	/2010

FACILITY CARRIED:			I440	NUMBER OF MAIN SPANS:	3
HIGHWAY SYSTEM:	02-IN	TERSTATE	URBAN	NUMBER OF APPROACH SPANS:	0
BRIDGE WIDTH (CURB TO CURB):		54 FT	1 IN	BRIDGE LENGTH (FT):	248
BRIDGE WIDTH (OUT TO OUT):		56 FT	1 IN	MAXIMUM SPAN LENGTH (FT):	115
APPROACH ROADWAY (W/SHOULDERS):	54 FT	1 IN	SKEW ANGLE (DEGREES):	52
MAINTAINED BY: MAIN SPAN MATERIAL: MAIN SPAN DESIGN TYPE:		TRESSED GIRDER			
APPROACH SPAN MATERIAL:		OTH	IER OR NOT APPLICABLE		
APPROACH SPAN DESIGN TYPE:			OTH	IER OR NOT APPLICABLE	
	22/2016 08/2014		-	ENERAL CONDITION: TRUCTURALLY DEFICIENT:	FAIR
PPRM PIN NUMBER: H TRUCK RATING @ INV.:		S	UFFICIENCY RATING:	83.0	

No.	RECOMMENDATIONS	REPAIR DATE	REPAIRED BY
1.	REPAIR APPROACH ROADWAY "A" END		
2.	LEVEL APPROACHES		

SUGGESTED ROUTINE MAINTENANCE AND COMMENTS
REMOVE TRASH @ ABUTMENTS
REPAIR SETTLEMENT @ BOTH ABUTMENTS
SEAL CONCRETE WEARING SURFACE
REPAIR EXPANSION JOINT AT APPROACH SLAB "A" END
REPAIR CONCRETE BASE UNDER LIGHT FIXTURE
SEAL BRIDGE PARAPET

GENERAL COMMENTS:

REPAIRED BREAKOUTS AT ABUTMENT # 1 & BREAKOUT ON CONCRETE RAIL OVER ABUT # 1... 04/05/2010 M.H.

STATE OF TENNESSEE

Bridge Condition Coding Form

Revised 02/22/2016

	STATE OF TENNES		Cou	ing ru	County:	19
	F	ORIAIION	101044000041		Route:	I0440
	Bridge Number: Cludes Item 5A)		191044000041		Special Case:	0
Featu	ire Intersected:	I	440-LL / CSX RR		County Sequence:	1
Eva	aluation Status:	CONDI	TION ITEM CHAN	Æ	Log Mile:	0.72
	L		HICH HAVE CHA			
	DESCRIPTION		VALUE		TION CODING GUIDELINES	
90	LAST INSPECT		02/22/2016		or Coding Items 58, 59, 60 and 62)	
20	EARLIEST DAT		12/23/2017			
	NEXT REGULAR INSF	PECTION		N NOT	APPLICABLE	
				9 EXC	CELLENT CONDITION	
10	MINIMUM V.C. DECK	OVER	99 FT. 99 IN	- 8 VER	RY GOOD CONDITION - NO	
	(ROADWAY + SI	HOULDERS) -	FT I	I KO	BLEMS NOTED.	
520	MINIMUM V.C. (EXCLUDES SH		99 FT. 99 I	•	OD CONDITION - SOME MINOR	
	(EACLODES SH		FT IN	DEI	ISFACTORY CONDITION - MIN 'ERIORATION OF STRUCTURA	
36	TRAFFIC SAFE				MENTS.	
	Br. Rail Trans.	Appr. Rail Te 0	erminal SPEED LIM 1 55	5 1111	R CONDITION - ALL PRIMARY UCTURAL ELEMENTS ARE SO	IND RUT
	1 0	Ū	1 55	MAY	Y HAVE MINOR SECTION LOSS,	
					CKING, SPALLING OR SCOUR.	
41	STRC OPEN/CL A K		Α		OR CONDITION - ADVANCED SE IS, DETERIORATION, SPALLING	
				SCO		
58	DECK		5		IOUS CONDITION - LOSS OF SE	
59	SUPERSTRUCT	URE	7	SER	ERIORATION, SPALLING OR S IOUSLY AFFECTED PRIMARY	
					UCTURAL COMPONENTS. LOC LURES ARE POSSIBLE. FATIGU	
60	SUBSTRUCTUR	RE	7	IN S	TEEL OR SHEAR CRACKS IN C	
				MAY	Y BE PRESENT.	
61	CHANL/CHANL	PROTECTION	Ν	_	TICAL CONDITION - ADVANCE	
					ERIORATION OF PRIMARY ST MENTS. FATIGUE CRACKS IN	
62	CULVERT AND	RETAIN WALL	Ν		AR CRACKS IN CONCRETE MA SENT OR SCOUR MAY HAVE R	
				SUB	STRUCTURE SUPPORT. UNLES	SS
71	WATERWAY AD	EQUACY	Ν		DSELY MONITORED IT MAY BE CESSARY TO CLOSE THE BRIDO	
					RECTIVE ACTION IS TAKEN.	
72	APPROACH RD	WY ALIGNMENT	8	1 "IM	MINENT'' FAILURE CONDITIO	N - MA IOR
				DET	ERIORATION OR SECTION LO	SS
521	OVERALL CON	DITION	FAIR		SENT IN CRITICAL STRUCTUR MPONENTS OR OBVIOUS VERT	
					RIZONTAL MOVEMENT AFFEC UCTURAL STABILITY. BRIDG	
16	LATITUDE	17 LONGITUE	E	CLC	SED TO TRAFFIC BUT CORRE	CTIVE
	N 36° 8.8940′	W 86° 49.3390)'	АСТ	TION MAY PUT IT BACK IN LIG	
			_		LED CONDITION - OUT OF SER	VICE AND
			/	BEY	OND CORRECTIVE ACTION.	
Г	TEAM LEADER SI	GNATURE	REVIEW DATE		And its production pursua	unt to a public

document records request does not waive the provisions of §409

Bridge ID#: 19104400004

Date: 02/22/2016




BTM DECK VIEW SP. #2



BENT #1 - BACK VIEW

Bridge ID#: 19104400004

Date: 02/22/2016



SETTLEMENT AT ABUTMENT #2



EXP. PILE W/ CORROSION AT ABUT. #2

Bridge ID#: 19104400004

Date: 02/22/2016



CLEARANCE VIEW LT. SIDE



SETTLEMENT AT ABUTMENT #1

Bridge ID#: 19104400004

Date: 02/22/2016



EXP. PILE W/ PITTING AT ABUT. #1



BRIDGE NO.

Bridge ID#: 19104400004

Date: 02/22/2016



APPROACH "A"



VIEW ACROSS TOP OF WEARING SURFACE

Bridge ID#: 19104400004

Date: 02/22/2016



APPROACH "B"



APPR. "B" END W/ PATCHES

BRIDGE INSPE	ECTION REPORT		Page No
Form BIR 3.0	Field Report No.	20	Date 2/22/2016
(Rev. 9-22-98)	Previous Report No.		Date 2/25/2014
DT-0069	Plans:	DESIG	<u>SN</u>
Bridge No. 19104400004	Bridge Location No.	19 -	10440 - 0.72 L
Eleven Digit No.		Co.	Route Log Mile
I440 over CSX	Crossing	Structu	ure Name (If Named)
Year Constructed 1986 ACTUAL	County Davidson		enance District 37
Year Widened	Year Rehabilitated		
FEATURES			INSPECTORS
Wearing Surface CONCRETE De	epth(in.)	1.	BILLINGSLEY TL
Flared Width NO Median	Width OPEN	2.	VOGEL
Navigational Control NO Bridge	Skew 52 °RT	3.	BROWN
Structure Type (Main Span) HBB		4.	LOVE
Structure Type (Appr.Spans)		5.	
No. Main Spans 3 No. Approach 9	Spans	6.	
Maximum Span Length 114.5' (**.* ft.))	7.	
Total Length 248' (**.* ft.))	8.	
		I	
<u>WIDTHS</u> (*.* ft.) Deck Out-to-Out 56'	CLEARANCES Min. Vertical Clearance ov	or Dool	(2011" (ft in)
			(
Roadway Curb/Curb	Min. Vertical Under Cleara		<u>25'2"</u> (ftin.)
Roadway Rail/Rail 54.0'	Min. Lateral Under Clearar		<u>16.5'</u> (*.* ft.)
Sidewalk Rt. 0 Lt. 0	Min. Lateral Under Clearar	ice Ll.	(*.* ft.)
*Approach Roadway <u>36</u> *(Does Not Include Shoulders)	FRACTURE CRITICAL:	10	
Approach Shoulder Rt. 12'	(If Yes, Include BIR 3.9	9)	
Lt. <u>6'</u>	NBIS Bridge Length (<25 f	t. <u>) OV</u>	ER 25' (ftin.)
UNDERWATER INSPECTION			
To Be Performed By: NA	Date		
Change in Structural Condition: NO M	ajor Repairs Made: NO	BRI	DGE is: OPEN
COMMENTS:			

Form BIR 3.1 (Rev. 9-22-98) DT-0080		Bridg	ge Lo	cation No. 19	<u>- I0440 - 0.72 L</u> Route Log Mile	Page No Date <u>2/22/2016</u>		
PERFORMANCE EVALUATION								
Time of Day Ins			0:30	AM Weathe	er Conditions CLDY 54			
•			0.00					
Vehicles Observ	eu A							
LIVE LOAD BEI	HAVIO	<u> 28</u>						
Substructure		Yes	'No		Comments			
Horiz./ Ver	t. Def	1. YE	s					
Vibration		N	с					
Superstructure	9							
Horiz./ Ver		1. N	0					
Vibration	• •	N						
Vibration								
APPROACH	Rati	ing			Comments			
Alignment	GO	OD						
Slab	PO	OR	MOL	MOD LONGIT AND TRANS 1/16" OPEN CRACKS, A/C PATCHES, HVY SPALLS				
Joints	PO	OR	MOL	O SPALLS & TORN	I FILLER			
Pavement	N	A						
Embankment	PO	OR	MOL	D-HVY EROSION @) 'B' END LT			
Drains	N/	A						
L								
TRAFFIC SAFET	Y FE		RES	Ctondord/				
	-	Rat	ing	Standard/ SubStandard	Comments			
Bridgerailing		GO	OD	STANDARD	LGH. SCALE			
Transitions		GO	OD	SUBSTANDARD	RUB RAIL NON EXIST-INCO	RRECT BLOCKOUTS		
Guardrail	FAIR SUBSTANDARD INCORRECT BLOCKOUTS, MISSING POST @ 'B'				MISSING POST @ 'B' END LT			

One Lane Bridge Signs Other Signs or Plaques:

Vertical Clearance (<14'-6")

GOOD

STNDARD

Yes/ No/ Needed

NO

NO

NO

NO

SIGNING

Guardrail Terminal

Narrow Bridge Signs

Paddleboards

Comments Regarding any Problems with Signing:

NO

Tons

Tons

Tons

Weight Limit Posted

Gross.....

2 Axle.....

3 or more Axles..

	Page No
Bridge	Location No. <u>19 - 10440 - 0.72 L</u> Date <u>2/22/2016</u> Co. Route Log Mile
Rating	Comments
FAIR	MOD TRANS AND HORZ CRACKS 1/16"-1/8" OPEN
GOOD	DECK PANELS- SP #3 BAY 'C' & 'D'- PANEL 7-TRANSV. & LONGIT CRACKS
N/A	
N/A	
N/A	
GOOD	LGH. SCALING ALL SPANS
N/A	
N/A	
N/A	
FAIR	LOSS OF CON UNDER BASE LT SIDE SPAN #2
N/A	
GOOD	
POOR	MISSING FILLER, ADHESION FAIL, A/C PATCHES
	Rating FAIR GOOD N/A N/A N/A GOOD N/A N/A N/A FAIR N/A GOOD

SUPERSTRUCTURE

Bearing Device	s GOOD	
Girders or Bear	ns GOOD	H.L. MAP CRACKS @ ABUTMENTS
Floor Beams	N/A	
Stringers	N/A	
Diaphragms	GOOD	
Bracing	N/A	
Trusses - Gene	ral N/A	
Porta	ls N/A	
Braci	ng N/A	
Paint	N/A	
Alignment of Members	GOOD	

TEXTURE COAT

Condition Rating	NA	Needs Spot Painting	NO
Overall Appearance		Needs Repainting	NO
Staining Rating		Comments	
Fading Rating		Comments	
Scaling Rating			

Form BIR 3.3							Page No
(Rev. 9-22-98)	Bridge Location No.	19 -	10440	-	0.72	L	Date 2/22/2016
DT-0082		Co.	Route		Log Mile	;	

SUBSTRUCTURE

ABUTMENTS	Rating	Comments
Caps	GOOD	
Breastwall	N/A	
Wings	GOOD	
Backwall	N/A	
Plumb	GOOD	
Footing	N/A	
Piles	GOOD	5 EXP.
Embankment	FAIR	SETTLEMENT @ ABUT #1 WITH 3 EXP PILES, 2 EXP. @ ABUT. #2
Bearing Surface	GOOD	
Slope Paving	N/A	
Rip Rap	GOOD	

<u>PIERS</u>

Caps	NA	
Columns		
Plumb Footings Piles		
Footings		
Piles		
Bearing Surface		

BENTS

Caps	GOOD	
Columns	GOOD	
Plumb	GOOD	
Footings	N/V	
Piles	N/V	
Bearing Surface	GOOD	

Piles Need Replacement: NO

Piles To Be Replaced:

SUMMARY 19-I440-0.72 LT 2/22/2016

I440/C.S.X. R.R 3 Span/B.B.

This bridge was inspected and found to be in **fair** condition. Approach alignment is good. Approach embankment at 'B' end left is fair with moderate-heavy erosion. Approach slabs are poor with moderate scale, cracks ¹/₂" open, A/C patches, and spalls upto 3.5' long x 1.5' wide x 2" deep. Approach guardrail and transitions are good but substandard with impact damage and missing post at 'B' end left. Bridge parapet rail is good and standard. End terminals are standard and good.


The concrete wearing surface is fair with moderate to heavy longitudinal and transverse cracks and moderate scaling. Expansion joints are poor with failing filler and breakouts.

Beams and bearings are good.


Abutments and bents are good. Abutment #1 has moderate settlement with two exposed piles. Abutment #2 has moderate settlement with two exposed piles with light rust.

The minimum distance from the centerline of track to the nearest bent is 16'. The crash barriers are in place and good.


Geremy Billingsley




DECK	FAIR	CONCRETE- MOD - HVY TRANSV. & LONGIT CRACKS 1/8" OPEN,	
		MOD. SCALE, AGG POPOUTS	
PARAPET	GOOD	STANDARD-LGH SCALE, AGG POPOUTS, LONGIT CRACKS	
		1/16" OPEN	
JOINTS	POOR	OPEN TYPE W/ FILLER LOSS OF FILLER, A/C PATCHES	




DECK	FAIR	CONCRETE-MOD - HVY TRANSV. & LONGIT CRACKS 1/8" OPEN,	
		MOD. SCALE	
PARAPET	GOOD	STANDARD-LGH SCALE, LONGIT CRACKS 1/16" OPEN	





DECK	FAIR	CONCRETE-MOD - HVY TRANSV. & LONGIT CRACKS 1/8" OPEN,	
		MOD. SCALE,& AGG. POPOUTS	
PARAPET	GOOD	STANDARD-LGH. SCALE, AGG POPOUTS	
JOINTS	FAIR	FILLER LOSS, ADHESIVE FAILURES	







DECK	GOOD	
DIAPHRAGMS	GOOD	
BEAMS	GOOD	H.L. MAP CRACKS ALL BEAMS @ ABUT.
OVERHANG	GOOD	





DECK	GOOD	SOOT STAINS
DIAPHRAGMS	GOOD	
BEAMS	GOOD	SOOT STAINS
OVERHANG	GOOD	







DECK	GOOD	TRANSV./LONGIT. H.C.'S PANEL #7, BAYS 'C' & 'D'
DIAPHRAGMS	GOOD	
BEAMS	GOOD	H.L. MAP CRACKS ALL BEAMS @ ABUT.
OVERHANG	GOOD	





Date 2/22/2016 JV





BACKWALL	GOOD	RANDING H.C.'S
CAP	GOOD	
WINGS	GOOD	
BEARINGS	GOOD	
EMBANKMENT	FAIR	(1) SETTLEMENT 6" DP X 2.5' UNDER X 16' L W/ 2 EXPOSED PILES
		HVY TRASH BLD. UP, (2) SETTLEMENT 4"DP X 2.5' UNDER X 12'L
		W/1 EXP. PILE
PILES	GOOD	LIGHT CORR. (3 EXPOSED)







CAP	GOOD	H.C.'S		
COLUMNS	GOOD			
FOOTINGS	NV			
	0000			
BEARINGS	GOOD			
			PRODUCED PURSUAN	ТО
CRASH WALL	GOOD	(1) 1/8" OPEN VERT. CRACK FULL HEIGHT	PUBLIC RECORDS REQ	UEST
			This document is covered by 23 And its production pursuant t	
			document records request d waive the provisions of §	oes not




Date 2/22/2016 JV







CAP	GOOD			
COLUMNS	GOOD			
FOOTINGS	NV			
BEARINGS	GOOD			
			PRODUCED PURSUANT TO	
CRASH WALL	GOOD	(1) 1/8" VERT. OPEN CRACK	PUBLIC RECORDS REQUEST This document is covered by 23 USC §4 And its production pursuant to a public	
			document records request does not waive the provisions of §409	UC .



Date 2/22/2016 JV






BACKWALL	GOOD	
CAP	GOOD	
WINGS	GOOD	
BEARINGS	GOOD	
EMBANKMENT	FAIR	(1) SETTLEMENT 3" H X 2' UNDER X 6' L W/ 1 EXPOSED PILE
		(2) SETTLEMENT 3" H X 1' UNDER X 25' L , HVY TRASH BLD-UP
		(3) SETTLEMENT 3' L X 4" H X 2' UNDER W/ 1 EXPOSED PILE
PILES	GOOD	(1) & (3) LIGHT CORR. (2 EXPOSED)

CLEARANCE SKETCH

Bridge Location No. <u>19</u> <u>I440</u> <u>0.72 LT.</u> County Route Log Mile





S.S. R.R.