HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 060A2010001 BRIDGE OWNER: BRADLEY COUNTY ROAD NAME: SAMPLES CHAPEL RD

CROSSING: MILL CREEK

COUNTY: BRADLEY ROUTE: 0A867 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	TITUDE:: N 35.02502 DEGREES IGITUDE: W 84.77443 DEGREES	
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE CONTINUOUS - CULVE FRAME CULVERTS)	RT (INCLUDES APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
	MASONRY OR CONCRETE BLOCK	ABUTMENTS ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	CONCRETE SOLID SHAFT PIER ON	UNKNOWN FOUNDATION
		SCOUR EVALUATION ————————————————————————————————————
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
_	heck on a bridge during floods movement - horizontally as w	
		n along curb line, both bridge rails and outer edge of bridge deck.
2. 0	Check for plumb of piers or be	nts.
[] - Chec	k for embankment erosion	
	k for drift build-up on piers or	
		nd compare to previous inspection
[] - Revie	w the latest bridge inspection	report versus current field conditions
lf Closure is	recommended:	
Coun temp	ty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	., .	y Maintenance Official (if bridge is not State maintained)
		atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	-
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance ridge on the selected detour route shall be checked		
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 			
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 728-7141		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 728-7006		
COUNTY SHERIFF'S OFFICE	(423) 728-7301		
The report shall include the date and time of the as appropriate, photographs of the bridge and	Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to conduct the Inspec	tion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade T	ape printed with the following message:		
SAFETY HAZARD KEEP	PAWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

17-Apr-19