HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: MADISON

BRIDGE ID NUMBER: 570A1830001
BRIDGE OWNER: MADISON COUNTY
ROAD NAME: STANFILL RD
CROSSING: BRANCH

ROUTE: 0A183
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.11

	TITUDE:: N 35.72653 DEGREES	
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	WOOD OR TIMBER - STRINGER/MU GIRDER	
		TYPE OF SUBSTRUCTURE
	TIMBER CAP ON TIMBER PILE FOL	
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
Things to c	heck on a bridge during flood	<u>s:</u>
	movement - horizontally as w	-
	<u>-</u>	n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	nts.
	k for embankment erosion k for drift build-up on piers or	honte
		nd compare to previous inspection
		report versus current field conditions
[]	in the latest bridge mopestion	Toport Volcae carroit flora containent
If Closure is	recommended:	
Coun temp	ity or City Maintenance Persoi	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	-
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



official		tate District maintenance or local highway maintenance bridge on the selected detour route shall be checked	
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTAC	T PERSONNEL:	TELEPHONE NUMBER:	
COUNTY	MAYOR'S OFFICE	(731) 423-6020	
HWY. CH	HEF ADMINISTRATOR'S OFFICE	(731) 422-1651	
COUNTY	SHERIFF'S OFFICE	(731) 423-6000	
The rep] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
- COMMENIS: _			
Suggested Li	st of Equipment to conduct the Inspe	ection:	
Latest Bridge	Inspection Report		
Scour POA R	eport with the above Checklist		
Bridge Desigi	n Plans, if available		
Tape measure	e with weight		
Plumb bob			
Range Pole			
A 1000 Foot F	• •	Tape printed with the following message:	
	SAFETY HAZARD KEE	EP AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24