HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 610A3400001
BRIDGE OWNER: MEIGS COUNTY
ROAD NAME: HALL CIR
CROSSING: DECATUR CREEK

LATITUDE:: N 35.50215 DEGREES
LONGITUDE: W 84.77198 DEGREES

COUNTY: MEIGS
ROUTE: 0A340
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.04
YEAR BUILT: 1960

LOIN	NOTIODE: W 04.77190 DEGREES	•	TEAR BOILT. 1900
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	MASONRY OR CONCRETE BLOCK	ABUTMENTS ON ROCK FOUNDATION	ON
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
	our critical; field review indicates o provide scour countermeasure		red at bridge foundations. Immediate action alling scour countermeasures.
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection		[] BridgeWatch Alert	
	·	•	al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
Things to c	heck on a bridge during floods	<u>s:</u>	
[] - Span	movement - horizontally as w	ell as vertically	
		•	e rails and outer edge of bridge deck.
	Check for plumb of piers or be		
	k for embankment erosion		
	k for drift build-up on piers or	bents	
	k pier exposure, if possible, ar		ection
	ew the latest bridge inspection		
f Closure is	recommended:		
Coun temp	ity or City Maintenance Persor	nnel. Use Barricade Tape, tra rists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	maintained)
	(2) City or County Highwa	y Maintenance Official (if br	ridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	- -
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



official	•	ate District maintenance or local highway maintenance oridge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTAC	CT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY	MAYOR'S OFFICE	(423) 334-5850	
HWY. CI	HIEF ADMINISTRATOR'S OFFICE	(423) 334-5157	
COUNTY	SHERIFF'S OFFICE	(423) 334-5268	
The rep	oort shall include the date and time of copriate, photographs of the bridge an	pection to BridgeWatch scour monitoring system. the inspection, a brief summary of findings and, d stream channel measurements. If significant be copied to Bridge Inspection Headquarters.	
COMMENTS:			
Suggested Li	ist of Equipment to conduct the Inspec	ction:	
_	Inspection Report		
	eport with the above Checklist		
•	n Plans, if available		
•	e with weight		
Plumb bob			
Range Pole	Della Carella de Balancia de La Barrio de La Carella d	The surface during the College's	
A 1000 Foot F	• •	Tape printed with the following message:	
	SAFETY HAZARD KEE	PAWAY	

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape