




LOUDON COUNTY

Loc. No. 53-I-75-14.24L
SB I-75
Over Old Highway 95
ID No. 53I00750034





① PRE-STRESSED STAND EXPOSED

7'-6" 23' ϕ BENT 1


SPALL DUE TO COLLISION DAMAGE
ALL DISTANCES ARE ESTIMATED
BEAM A SPAN 2

STATE OF TENNESSEE
DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGE INSPECTION
AND REPAIR

BRIDGE NO. 53 - I 75 - 14.28 LT
CROSSING: U.P. 53 - 1247 - 2.68

COUNTY: LOUDON

DRAWN <u>LAY</u>	REVISION _____
DATE <u>5-17-94</u>	DATE _____



REPAIRED THIS INSPECTION
9-3-98 Joseph Edmond

STATE OF TENNESSEE
DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGE INSPECTION
AND REPAIR


SPALLS BEAM A SPAN 2
DUE TO COLLISION

BRIDGE NO. 53-I75-14.28 LT
CROSSING: U.P. 53-1247-2.68


COUNTY: LOUDON

DRAWN LAH
DATE 5-17-94
8-29-96

REVISION _____
DATE _____



A - A SECTION



① PRE-STRESSED STRAND EXPOSED

7'-6" 23'
 & BENT 1SPALL DUE TO COLLISION DAMAGE
ALL DISTANCES ARE ESTIMATED

BEAM A SPAN 2

STATE OF TENNESSEE
DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGE INSPECTION
AND REPAIRBRIDGE NO. 53 - I 75 - 14.28 LT
CROSSING: U.P. 53 - 1247 - 2.68

COUNTY: LOUDON

DRAWN LAY
DATE 5-17-94
9-13-94 BW
REVISION
DATE

FOR PLANS SEE:

53I00756033- INFO