HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 27015850005
BRIDGE OWNER: GIBSON COUNTY
ROAD NAME: SALEM CHURCH RD.
CROSSING: OVERFLOW

COUNTY: GIBSON
ROUTE: 01585
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.36

LA	TITUDE:: N 35.95806 DEG	REES LOG MILE: 1.36
LON	IGITUDE: W 88.73797 DEG	REES YEAR BUILT: 1971
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	TIMBER CAP ON TIMBER PIL	FOUNDATION
BENTS:	TIMBER PILE BENT ON PILE	OUNDATION
PIERS:	NOT APPLICABLE	
		CCOUR EVALUATION
Delales le con	and the state of t	SCOUR EVALUATION
	our critical; bridge foundations sures are installed but they	ns determined to be unstable for calculated scour conditions. No scour are needed.
		INSPECTION PROCEDURES ————————————————————————————————————
What Initiat	ed the Call-out Inspectior	? [] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
1. C 2. C [] - Chec [] - Chec	Check for plumb of piers on the combankment erosion in the combankment erosion in the combankment erosion in the combank for drift build-up on piers	ection along curb line, both bridge rails and outer edge of bridge deck. r bents.
[] - Revie	ew the latest bridge inspe	tion report versus current field conditions
[] - Stay		ed across road until bridge is secured and properly closed by District,
temp		rsonnel. Use Barricade Tape, traffic cones and/or traffic flares as ottorists to stay off of the bridge until such time as the bridge may ded.
[] - Conta	act: (1) District Maintenai	ce Supervisor (if bridge is State maintained)
	(2) City or County Hig	hway Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highw	ay Patrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional B	idge Engineer
	Bridge should remain clos TDOT bridge inspection to	ed until the water recedes and a daylight visual inspection is made am.

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	•	ate District maintenance or local highway maintenance ridge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
<u>!</u>	CONTACT PERSONNEL:	TELEPHONE NUMBER:	
	COUNTY MAYOR'S OFFICE	(731) 855-7611	
I	HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 855-7684	
(COUNTY SHERIFF'S OFFICE	(731) 855-1121	
T a	The report shall include the date and time of t	ection to BridgeWatch scour monitoring system. he inspection, a brief summary of findings and, d stream channel measurements. If significant he copied to Bridge Inspection Headquarters.	
COMIME	ENTS:		
<u>Sugge</u>	sted List of Equipment to conduct the Inspec	etion:	
Latest	Bridge Inspection Report		
Scour	POA Report with the above Checklist		
Bridge	Design Plans, if available		
•	neasure with weight		
Plumb			
Range			
A 1000	Foot Roll of yellow Polyethylene Barricade T	Tape printed with the following message:	
	SAFETY HAZARD KEEF	PAWAY	

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)