## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 020A0940001
BRIDGE OWNER: BEDFORD COUNTY
ROAD NAME: ANDERTON RD
CROSSING: NORTH FORK CREEK
LATITUDE:: N 35.62673 DEGREES
LONGITUDE: W 86.46474 DEGREES

COUNTY: BEDFORD
ROUTE: 0A094
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.28
YEAR BUILT: 1957

		TYPE	OF SUPERSTRUCTURE =	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O			NOT APPLICABLE
		<b>T</b> 1/D		
ADUTMENTO			E OF SUBSTRUCTURE =	NO FOUNDATION
	CONCRETE FULL HEIGHT ABUTME	NI ON	CONCRETE SPREAD FOOTI	NG FOUNDATION
BENTS:	NOT APPLICABLE	001101		LIND ATION
PIERS:	CONCRETE SOLID SHAFT PIER ON	CONC	RETE SPREAD FOOTING FO	UNDATION
		S	COUR EVALUATION -	
	unknown foundations. Risk of sco icant flood events. Monitor bridge			bridge shall be monitored for distress termeasures.
		INSP	ECTION PROCEDURES =	
What Initiat	ed the Call-out Inspection?	r 1	BridgeWatch Alert	
		1 1	_	al Maintenance Personnel
		1 1	THP or Local Law Enf	
		11		
Things to c	heck on a bridge during floods	<u>::</u>		
[ ] - Snan	movement - horizontally as we	all as v	vertically	
	· · · · · · · · · · · · · · · · · · ·		•	e rails and outer edge of bridge deck.
	Check for plumb of piers or ber		g cars into, sour strag	o rano ana oator oago or briago acom
	k for embankment erosion	113.		
	k for drift build-up on piers or	hents		
	k pier exposure, if possible, ar		nnare to previous inspe	ection
	ew the latest bridge inspection		•	
[ ] - Kevic	w the latest bridge mapection	Герог	t versus current neia c	onditions
lf Closure is	recommended:			
Coun temp	nty or City Maintenance Person	nel. U	se Barricade Tape, traf	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	uperv	isor ( if bridge is State	maintained )
	(2) City or County Highwa	y Mair	ntenance Official ( if br	ridge is not State maintained )
	(3) Tennessee Highway Pa	atrol a	nd/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engir	neer	
	ridge should remain closed until the water recedes and a daylight visual inspection is made			

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in esta		State District maintenance or local highway maintenance y bridge on the selected detour route shall be checked			
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>				
CONTACT PERSON	INEL:	TELEPHONE NUMBER:			
COUNTY MAYOR'S	OFFICE	(931) 684-7944			
COUNTY SHERIFF	S OFFICE	(931) 836-3232			
HWY. CHIEF ADMII	NISTRATOR'S OFFICE	(931) 684-4651			
- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.					
COMMENTS:					
Suggested List of Equ	uipment to conduct the Insp	pection:			
Latest Bridge Inspect	ion Report				
Scour POA Report wit	th the above Checklist				
Bridge Design Plans,	if available				
Tape measure with we	eight				
Plumb bob					
Range Pole					
A 1000 Foot Roll of ye	llow Polyethylene Barricade	e Tape printed with the following message:			
	SAFETY HAZARD KE	EEP AWAY			

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24