HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 030A1510001
BRIDGE OWNER: BENTON COUNTY

ROAD NAME: SMITH RD

CROSSING: LITTLE CROOKED CREEK
LATITUDE:: N 36.22939 DEGREES
LONGITUDE: W 87.97056 DEGREES

COUNTY: BENTON
ROUTE: 0A151
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.08

LON	IGITUDE: W 87.97056 DEGREES	YEAR BUILT: 1975
		TYPE OF SUPERSTRUCTURE -
MAIN SPAN:	ALUMINUM, WROUGHT OR CAST IF STRINGER/MULTI-BEAM OR GIRDE	
		TYPE OF SUBSTRUCTURE -
ABUTMENTS:	STEEL CAP ON STEEL PILE FOUND	DATION
BENTS:	STEEL PILE BENT ON STEEL MUDS	SILL FOUNDATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection		[] BridgeWatch Alert
	•	[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
[] - Span 1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or being the combankment erosion in the combankment erosion is for drift build-up on piers or the combank pier exposure, if possible, are combank in the combank is possible, are combank is possible.	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.
<u>If Closure is</u>	recommended:	
Coun temp	at bridge with vehicle pulled across road until bridge is secured and properly closed by District, nty or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as porary measures to warn motorists to stay off of the bridge until such time as the bridge may properly closed and barricaded.	
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ork with State District maintenance or local highway maintenance oute. Any bridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 584-6011		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 584-6145		
COUNTY SHERIFF'S OFFICE	(731) 584-4632		
The report shall include the date a as appropriate, photographs of the	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:			
Suggested List of Equipment to conduc	t the Inspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Check	dist		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene	Barricade Tape printed with the following message:		
SAFETY HA	ZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24