HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 030A1830001 BRIDGE OWNER: BENTON COUNTY ROAD NAME: WILSON RD

CROSSING: BEAVERDAM CREEK

COUNTY: BENTON ROUTE: 0A183 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	TITUDE:: N 36.10965 DEGREE IGITUDE: W 88.04705 DEGREE		LOG MILE: 0.93 YEAR BUILT: 2004
		 TYPE OF SUPERSTRUCTURE 	
MAIN SPAN:	PRESTRESSED CONCRETE - BOX GIRDERS - MULTIPLE	BEAM OR APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE -	
	TIMBER CAP ON TIMBER PILE FO	UNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
		cour cannot be determined. The ge in lieu of installing scour coun	bridge shall be monitored for distress termeasures.
0 0		INSPECTION PROCEDURES	
What Initiate	ed the Call-out Inspection?	[] BridgeWatch Alert	
vviiat iiiitiat	cu the oun-out mapeenon:	•	al Maintenance Personnel
		[] THP or Local Law Enf	
Things to cl	heck on a bridge during flood	ls:	
[] - Span	movement - horizontally as v	vell as vertically	
		•	e rails and outer edge of bridge deck.
2. 0	check for plumb of piers or be	ents.	
[] - Checl	k for embankment erosion		
[] - Checl	k for drift build-up on piers o	bents	
[] - Checl	k pier exposure, if possible, a	and compare to previous inspe	ection
[] - Revie	w the latest bridge inspection	n report versus current field c	onditions
f Clasura ia			
	recommended:		
Coun	ty or City Maintenance Perso	nnel. Use Barricade Tape, traf	cured and properly closed by District, ffic cones and/or traffic flares as
-	orary measures to warn moto operly closed and barricaded	-	until such time as the bridge may
-	• •	Supervisor (if bridge is State	maintained)
	• •	ay Maintenance Official (if br	•
		Patrol and/or local law enforce	•
	(4) TDOT Regional Bridge		· · ·
	ne Bridge should remain closed until the water recedes and a daylight visual inspection is made		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ork with State District maintenance or local highway maintenance oute. Any bridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 584-6011		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 584-6145		
COUNTY SHERIFF'S OFFICE	(731) 584-4632		
The report shall include the date a as appropriate, photographs of the	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:			
Suggested List of Equipment to conduc	t the Inspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Check	dist		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene	Barricade Tape printed with the following message:		
SAFETY HA	ZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24