HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 05038030001
BRIDGE OWNER: CITY OF MARYVILLE

ROAD NAME: **BEST ST**CROSSING: **PISTOL CREEK**

LATITUDE:: N 35.73807 DEGREES
LONGITUDE: W 83.97815 DEGREES

COUNTY: BLOUNT
ROUTE: 03803
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.14

LON	IGITUDE: W 83.97815 DEGREES		YEAR BUILT: 1965
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION -	
	ınknown foundations. Risk of sco icant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.
		INSPECTION PROCEDURES -	
What Initiate	ed the Call-out Inspection?	[] BridgeWatch Alert	
	•	[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law Ent	forcement Personnel
		[] Other:	
Things to c	<u>heck on a bridge during floods</u>	<u>s:</u>	
1. C 2. C	Check for plumb of piers or be	n along curb line, both bridge	e rails and outer edge of bridge deck.
	k for embankment erosion	_	
	k for drift build-up on piers or		
	k pier exposure, if possible, ar	•	
[] - Revie	w the latest bridge inspection	report versus current field c	onditions
f Closure is	recommended:		
Coun temp	ity or City Maintenance Persor	nnel. Use Barricade Tape, traf	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	supervisor (if bridge is State	maintained)
	(2) City or County Highwa	y Maintenance Official (if br	ridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	- -
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a d	daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance bridge on the selected detour route shall be checked		
	ge can be re-opened only after a TDOT bridge inspection team checks the substructure d they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(865) 981-1300		
CITY ENGINEER'S OFFICE	(865) 273-3504		
POLICE OFFICE	(865) 273-3800		
PUBLIC WORKS DIRECTOR	(865) 273-3504		
as appropriate, photographs of the bridge a	f the inspection, a brief summary of findings and, and stream channel measurements. If significant be copied to Bridge Inspection Headquarters.		
Suggested List of Equipment to conduct the Inspe	ection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade	Tape printed with the following message:		
SAFETY HAZARD KE	EP AWAY		
A Barricade Tape Dispenser with serrated cutter			

PUBLICATION DATE

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

07-Nov-24