HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 050A5320001 BRIDGE OWNER: BLOUNT COUNTY ROAD NAME: ELLEJOY RD CROSSING: PITNER CREEK

LATITUDE:: N 35.81147 DEGREES

COUNTY: BLOUNT ROUTE: 0A660 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.72

LON	NGITUDE: W 83.76832 DEGREES	YEAR BUILT: 1931
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE CONTINUOUS - CULVE FRAME CULVERTS)	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE BOX TYPE ON CONCRE	TE SPREAD FOOTING FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	PIER WALL FOR CONCRETE BOX O	ON CONCRETE SPREAD FOOTING FOUNDATION
		SCOUR EVALUATION ————————————————————————————————————
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
	·	[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
1. 0 2. 0 [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	n along curb line, both bridge rails and outer edge of bridge deck. nts.
If Closure is	recommended:	
Coun temp	ity or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance y bridge on the selected detour route shall be checked		
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(865) 273-5700		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(865) 982-4652		
COUNTY SHERIFF'S OFFICE	(865) 273-5000		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Ins	pection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricac	le Tape printed with the following message:		
SAFETY HAZARD K	EEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

17-Apr-19