HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 050A8680001
BRIDGE OWNER: BLOUNT COUNTY
ROAD NAME: BIG ELM RD
CROSSING: NINE MILE CREEK

LATITUDE:: N 35.60648 DEGREES
LONGITUDE: W 84.17302 DEGREES

COUNTY: BLOUNT
ROUTE: 0A868
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.02
YEAR BUILT: 1930

LON	NGITUDE: W 84.17302 DEGREES		YEAR BUILT: 1930
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE SOLID SHAFT PIER ON	UNKNOWN FOUNDATION	
		SCOUR EVALUATION	
Bridge has u	inknown foundations. Risk of sci	our cannot be determined. The	bridge shall be monitored for distress
	icant flood events. Monitor bridg		
		 INSPECTION PROCEDURES 	
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert	
		[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
Things to c	heck on a bridge during flood	<u>s:</u>	
[] - Span	movement - horizontally as w	ell as vertically	
1. 0	Check displacement / deflectio	n along curb line, both bridge	e rails and outer edge of bridge deck.
2. 0	Check for plumb of piers or be	nts.	
	k for embankment erosion		
	k for drift build-up on piers or		
	k pier exposure, if possible, a		
[] - Revie	ew the latest bridge inspection	report versus current field c	onditions
f Closure is	recommended:		
		arace road until bridge is see	cured and properly closed by District,
Coun temp	nty or City Maintenance Persor	nnel. Use Barricade Tape, trat rists to stay off of the bridge	ffic cones and/or traffic flares as until such time as the bridge may
-	act: (1) District Maintenance S		maintained)
[] - Conta	` '	• •	ridge is not State maintained)
	() ,	•	ement Officers as appropriate
	(4) TDOT Regional Bridge		mont officers as appropriate
[].The F	,,	-	daylight visual inspection is made
	TDOT bridge inspection team.		adyngin visuai mepoolion is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ill work with State District maintenance or local highway maintenance our route. Any bridge on the selected detour route shall be checked ute.		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(865) 273-5700		
HWY. CHIEF ADMINISTRATOR'S OFF	FICE (865) 982-4652		
COUNTY SHERIFF'S OFFICE	(865) 273-5000		
The report shall include the da as appropriate, photographs o	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:			
Suggested List of Equipment to con	duct the Inspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above C	hecklist		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
	ene Barricade Tape printed with the following message:		
SAFETY	Y HAZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24