## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 05S24230003

BRIDGE OWNER: BLOUNT COUNTY

ROAD NAME: BIG SPRINGS RD

CROSSING: GALLAGHER CREEK

LATITUDE:: N 35.74970 DEGREES

COUNTY: BLOUNT
ROUTE: 05551
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.25
YEAR BUILT: 1930

LON	NGITUDE: W 84.12120 DEGREES	YEAR BUILT: 1930
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - CULVERT (INCLUDES CULVERTS)	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE BOX TYPE ON CONCR	ETE SPREAD FOOTING FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
	our critical; bridge foundations de ling scour countermeasures.	etermined to be unstable for calculated scour conditions. Monitor bridge in
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
	·	[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
1. C 2. C [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	n along curb line, both bridge rails and outer edge of bridge deck. nts.
[ ] - Stay a Coun temp	nty or City Maintenance Person	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
-	• •	Supervisor ( if bridge is State maintained )
. ,	` '	y Maintenance Official ( if bridge is not State maintained )
	,,,,	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	• • •
	` '	ntil the water recedes and a daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	will work with State District maintenance or local highway maintenance tour route. Any bridge on the selected detour route shall be checked oute.		
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(865) 273-5700		
HWY. CHIEF ADMINISTRATOR'S O	FFICE (865) 982-4652		
COUNTY SHERIFF'S OFFICE	(865) 273-5000		
The report shall include the cas appropriate, photographs	] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to co	·		
Scour POA Report with the above	Checklist		
Bridge Design Plans, if available Tape measure with weight			
Plumb bob			
Range Pole			
_	ylene Barricade Tape printed with the following message:		
	TY HAZARD KEEP AWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)