	HWAY BRIDGE SCOUR N OF ACTION REPORT	TN TDOT Department of Transportation			
BRIDGE ID NUMBER: 060A3670001 BRIDGE OWNER: CITY OF CLEVELAND		COUNTY: BRADLEY Route: 0A367			
ROAD NAME: MAPLETON DR CROSSING: SOUTH MOUSE CREEK LATITUDE:: N 35.23180 DEGREE LONGITUDE: W 84.84367 DEGREE		SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.39 YEAR BUILT: 1960			
TYPE OF SUPERSTRUCTURE					
MAIN SPAN: STEEL - STRINGER/MULTI-BEAM	DR GIRDER APPR. SPAN:	NOT APPLICABLE			
	- TYPE OF SUBSTRUCTURE -				
ABUTMENTS:CONCRETE FULL HEIGHT ABUTMBENTS:NOT APPLICABLEPIERS:NOT APPLICABLE	ENT ON UNKNOWN FOUNDATION				
	SCOUR EVALUATION				
Bridge is scour critical, but countermeasure event. Deterioration of channel protection of been installed and is in good condition.					
	INSPECTION PROCEDURES =				
What Initiated the Call-out Inspection?	[] BridgeWatch Alert [] TDOT District or Loca [] THP or Local Law Enf	I Maintenance Personnel orcement Personnel			

Things to check on a bridge during floods:

- [] Span movement horizontally as well as vertically
 - 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck.

[] Other:

- 2. Check for plumb of piers or bents.
- [] Check for embankment erosion
- [] Check for drift build-up on piers or bents
- [] Check pier exposure, if possible, and compare to previous inspection
- [] Review the latest bridge inspection report versus current field conditions

If Closure is recommended:

- [] Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.
- [] Contact: (1) District Maintenance Supervisor (if bridge is State maintained)
 - (2) City or County Highway Maintenance Official (if bridge is not State maintained)
 - (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate
 - (4) TDOT Regional Bridge Engineer
- [] The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.

PUBL	ICATION	DATE

07-Nov-24



- [] The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.
- [] The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.

CONTACT PERSONNEL:	TELEPHONE NUMBER:
CITY MAYOR'S OFFICE	(423) 472-4551
CITY ENGINEER'S OFFICE	(423) 479-8153

[] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.

COMMENTS:

Suggested List of Equipment to conduct the Inspection:

Latest Bridge Inspection Report Scour POA Report with the above Checklist Bridge Design Plans, if available Tape measure with weight Plumb bob Range Pole A 1000 Foot Roll of yellow Polyethylene Barricade Tape printed with the following message: SAFETY HAZARD KEEP AWAY A Barricade Tape Dispenser with serrated cutter A roll of Duct Tape Traffic Cones - Minimum of four (4) Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)

PUBLICA	TION	DATE
	-	

07-Nov-24