HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 100A6180001
BRIDGE OWNER: CARTER COUNTY
ROAD NAME: PAUL BLEVINS RD
CROSSING: TIGER CREEK

LATITUDE:: N 36.19078 DEGREES
LONGITUDE: W 82.18717 DEGREES

COUNTY: CARTER
ROUTE: 0A618
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.03
YEAR BUILT: 1970

LON	NGITUDE: W 82.18717 DEGREES	i	YEAR BUILT: 1970
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	TYPE OF SUPERSTRUCTURE • R GIRDER APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
	CONCRETE FULL HEIGHT ABUTME	NT ON SOIL FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
event. Deter			the risk of bridge failure during a flood DOT for assessment. Monitor bridge in lieu
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
			al Maintenance Personnel
		[] THP or Local Law En	
1. 0 2. 0 [] - Chec [] - Chec [] - Chec	movement - horizontally as we Check displacement / deflection Check for plumb of piers or beach of the k for embankment erosion of the k for drift build-up on piers or the k pier exposure, if possible, are we the latest bridge inspection	n along curb line, both bridg nts. bents nd compare to previous insp	
lf Closure is	recommended:		
Coun temp	nty or City Maintenance Persor	nnel. Use Barricade Tape, tra	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	supervisor (if bridge is State	e maintained)
	(2) City or County Highwa	y Maintenance Official (if b	ridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any br prior to signing the detour route.	idge on the selected detour route shall be checked		
	dge can be re-opened only after a TDOT bridge inspection team checks the substructure nd they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 542-1801		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 543-2331		
COUNTY SHERIFF'S OFFICE	(423) 543-2211		
as appropriate, photographs of the bridge and scouring has occurred, the report shall also be	e copied to Bridge Inspection Headquarters.		
Suggested List of Equipment to conduct the Inspect	ion:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta			
SAFETY HAZARD KEEP	AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24