HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 110A0610001
BRIDGE OWNER: CHEATHAM COUNTY
ROAD NAME: LEO BAKER RD
CROSSING: RACCOON CREEK

LATITUDE:: N 36.39002 DEGREES
LONGITUDE: W 87.17660 DEGREES

COUNTY: CHEATHAM
ROUTE: 0A061
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.45
YEAR BUILT: 1960

LON	IGHUDE: W 87.17660 DEGREES	•	YEAR BUILT: 1960
		TYPE OF SUPERSTRUCTURE -	
MAIN SPAN:	CONCRETE CONTINUOUS - CULVE FRAME CULVERTS)	RT (INCLUDES APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE =	
ABUTMENTS:	CONCRETE BOX TYPE ON CONCRETE SPREAD FOOTING FOUNDATION		
BENTS:	NOT APPLICABLE		
PIERS:	PIER WALL FOR CONCRETE BOX O	ON CONCRETE SPREAD FOOTING F	OUNDATION
		SCOUR EVALUATION =	
	our critical; bridge foundations de ing scour countermeasures.		culated scour conditions. Monitor bridge in
		INSPECTION PROCEDURES =	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
	•	•	al Maintenance Personnel
		[] THP or Local Law Ent	forcement Personnel
		[] Other:	
1. C 2. C [] - Chec [] - Chec	movement - horizontally as we Check displacement / deflection Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar ew the latest bridge inspection	n along curb line, both bridgents. bents nd compare to previous inspe	
If Closure is	recommended:		
Coun temp	ity or City Maintenance Person	nel. Use Barricade Tape, traf	eured and properly closed by District, ific cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State	maintained)
	(2) City or County Highwa	y Maintenance Official (if br	idge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



	officials in establishing a detour route. Any be prior to signing the detour route.	oridge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructurally stable.		
	CONTACT PERSONNEL:	TELEPHONE NUMBER:	
	COUNTY MAYOR'S OFFICE	(615) 792-4316	
	HWY. CHIEF ADMINISTRATOR'S OFFICE	(615) 792-4240	
	COUNTY SHERIFF'S OFFICE	(615) 792-4341	
\$	as appropriate, photographs of the bridge an	the inspection, a brief summary of findings and, d stream channel measurements. If significant be copied to Bridge Inspection Headquarters.	
<u>Sugge</u>	ested List of Equipment to conduct the Inspec	ction:	
Latest	Bridge Inspection Report		
Scour	POA Report with the above Checklist		
Bridge	e Design Plans, if available		
•	neasure with weight		
Plumb			
Range			
A 1000	Foot Roll of yellow Polyethylene Barricade		
	SAFETY HAZARD KEE	P AWAY	

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)