HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 11S61500001

BRIDGE OWNER: CHEATHAM COUNTY ROAD NAME: LOCKERTSVILLE RD CROSSING: SYCAMORE CREEK

LATITUDE:: N 36.32410 DEGREES

COUNTY: CHEATHAM ROUTE: 00979 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 3.82

LONGITUDE: W 87.09308 DEGREES		YEAR BUILT: 1949
		TYPE OF SUPERSTRUCTURE -
MAIN SPAN:	PRESTRESSED CONCRETE - STRIF OR GIRDER	IGER/MULTI-BEAM APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON S	STEEL PILE FOUNDATION
BENTS:	CONCRETE COLUMN TWO POST B	ENT ON CONCRETE SPREAD FOOTING FOUNDATION
PIERS:	NOT APPLICABLE	
		CCOUR EVALUATION
D.1		SCOUR EVALUATION
	our critical; bridge foundations de ling scour countermeasures.	etermined to be unstable for calculated scour conditions. Monitor bridge in
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
	·	[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	n along curb line, both bridge rails and outer edge of bridge deck. nts.
If Closure is	recommended:	
Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Contact: (1) District Maintenance Super		supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance bridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(615) 792-4316		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(615) 792-4240		
COUNTY SHERIFF'S OFFICE	(615) 792-4341		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Inspe	ection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade			
SAFETY HAZARD KE	EP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24