HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: CHESTER

BRIDGE ID NUMBER: 120A3270001 BRIDGE OWNER: CHESTER COUNTY ROAD NAME: KISE CREEK ROAD CROSSING: KISE CREEK

LATITUDE: N 35 28700 DEGREES

ROUTE: 0A407 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.37

LON	NGITUDE: W 88.76472 DEGREES	YEAR BUILT: 1993
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	WOOD OR TIMBER - STRINGER/MU GIRDER	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	INDATION
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION
PIERS:	NOT APPLICABLE	
		COOLID EVALUATION
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
	·	[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[] Other:
1. 0 2. 0 [] - Chec [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar	n along curb line, both bridge rails and outer edge of bridge deck. nts.
[] - Stay a Coun temp	ity or City Maintenance Persor orary measures to warn motor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
-	operly closed and barricaded.	Supervisor (if bridge is State maintained)
[] - Conta	` '	y Maintenance Official (if bridge is not State maintained)
	` , , ,	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	• • •
[] _ The 9	` '	_
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State I officials in establishing a detour route. Any bridg prior to signing the detour route. 			
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 989-5672		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 989-7311		
COUNTY SHERIFF'S OFFICE	(731) 989-2787		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	<u>):</u>		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Tape	e printed with the following message:		
SAFETY HAZARD KEEP AV			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24