HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 12S80580001
BRIDGE OWNER: CHESTER COUNTY
ROAD NAME: GARLAND RD
CROSSING: OVERFLOW

COUNTY: CHESTER
ROUTE: 00926
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.35
YEAR BUILT: 2002

	TITUDE:: N 35.48186 DEGREES NGITUDE: W 88.64739 DEGREES	LOG MILE: 2.35 YEAR BUILT: 2002
	TYPE	OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE - STRINGER/M OR GIRDER	ULTI-BEAM APPR. SPAN: NOT APPLICABLE
		E OF SUBSTRUCTURE
	CONCRETE STUB ABUTMENT ON STEEL F	
BENTS:	STEEL PILE BENT ON STEEL PILE FOUND	ATION
PIERS:	NOT APPLICABLE	
	s	COUR EVALUATION
event. Deteri		been installed to reduce the risk of bridge failure during a flood should be reported to TDOT for assessment. Rip-rap protection has
	INSP	ECTION PROCEDURES -
What Initiated the Call-out Inspection?		BridgeWatch Alert
	[]	TDOT District or Local Maintenance Personnel
	[]	THP or Local Law Enforcement Personnel
	[]	Other:
-		
•	heck on a bridge during floods:	
	movement - horizontally as well as	•
	·	g curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or bents.	
	k for embankment erosion	
	k for drift build-up on piers or bents k pier exposure, if possible, and con	anara to provious inspection
	ew the latest bridge inspection repor	
[] - IVEVIC	w the latest bridge inspection repor	t versus current neid conditions
<u>lf Closure is </u>	recommended:	
Coun temp	nty or City Maintenance Personnel. U	road until bridge is secured and properly closed by District, se Barricade Tape, traffic cones and/or traffic flares as stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance Superv	isor(if bridge is State maintained)
	(2) City or County Highway Maiı	ntenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Patrol a	nd/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge Engir	neer
	Bridge should remain closed until the TDOT bridge inspection team.	e water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	n State District maintenance or local highway maintenance ny bridge on the selected detour route shall be checked		
	bridge can be re-opened only after a TDOT bridge inspection team checks the substructure s and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 989-5672		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 989-7311		
COUNTY SHERIFF'S OFFICE	(731) 989-2787		
	and stream channel measurements. If significant so be copied to Bridge Inspection Headquarters.		
Suggested List of Equipment to conduct the Ins	spection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricae SAFETY HAZARD K			
A Barricade Tape Dispenser with serrated cutter			
A roll of Duct Tape			
•			
• •	t of electronic warning flashers		
Traffic Cones - Minimum of four (4) Traffic Safety Flares - Minimum of four (4) or set	t of electronic warning flashers		

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)