HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 12SR0050001

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: US45

CROSSING: SUGAR CREEK

COUNTY: CHESTER ROUTE: SR005

SPECIAL CASE: 0

COUNTY SEQUENCE: 2

	.TITUDE:: N 35.42911 DEGREES IGITUDE: W 88.64281 DEGREES		LOG MILE: 4.70 YEAR BUILT: 1979		
		TYPE OF SUPERSTRUCTURE =			
MAIN SPAN:	PRESTRESSED CONCRETE CONTIN STRINGER/MULTI-BEAM OR GIRDE		NOT APPLICABLE		
		TYPE OF SUBSTRUCTURE -			
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	ONCRETE PILE FOUNDATION			
BENTS:	CONCRETE COLUMN TWO POST BI	TE COLUMN TWO POST BENT ON PILE FOUNDATION			
PIERS:	NOT APPLICABLE				
		SCOUR EVALUATION =			
•	our critical; bridge foundations de ing scour countermeasures.	termined to be unstable for cal	culated scour conditions. Monitor bridge in		
		INSPECTION PROCEDURES =			
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert			
	•	[] TDOT District or Loca	Il Maintenance Personnel		
		[] THP or Local Law Enf	orcement Personnel		
		[] Other:			
[] - Span 1. 0 2. 0 [] - Chec [] - Chec	heck on a bridge during floods movement - horizontally as we check displacement / deflection check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, an ew the latest bridge inspection	ell as vertically n along curb line, both bridge nts. bents nd compare to previous inspe			
<u>If Closure is</u>	recommended:				
Coun temp	ity or City Maintenance Person	nel. Use Barricade Tape, traf	ured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may		
-	act: (1) District Maintenance S	maintained)			
	(2) City or County Highway Maintenance Official (if bridge is not State maintained)				
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ment Officers as appropriate		
	(4) TDOT Regional Bridge	Engineer			
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 				

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



offic	•	e District maintenance or local highway maintenance dige on the selected detour route shall be checked	
	he bridge can be re-opened only after a TDOT bridge inspection team checks the substructure nits and they are determined to be structurally stable.		
CON	TACT PERSONNEL:	TELEPHONE NUMBER:	
REGI	ON BRIDGE ENGINEER	(731) 234-9561	
DIST	RICT MAINTENANCE SUPERVISOR	(731) 694-6673	
TENN	NESSEE HIGHWAY PATROL	(731) 423-6635	
The i	report shall include the date and time of the	etion to BridgeWatch scour monitoring system. e inspection, a brief summary of findings and, etream channel measurements. If significant copied to Bridge Inspection Headquarters.	
COMMENTS	S:		
Suggested	List of Equipment to conduct the Inspection	on:	
Latest Brid	dge Inspection Report		
Scour POA	A Report with the above Checklist		
•	sign Plans, if available		
•	sure with weight		
Plumb bob			
Range Pol			
A 1000 Foo	ot Roll of yellow Polyethylene Barricade Tap		
	SAFETY HAZARD KEEP A	AWAY	

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape