HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 12SR0050006

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: US45

CROSSING: TURKEY CREEK

LATITUDE:: N 35.46725 DEGREES
LONGITUDE: W 88.68617 DEGREES

COUNTY: CHESTER
ROUTE: SR005
SPECIAL CASE: 0
COUNTY SEQUENCE: 2
LOG MILE: 8.50
YEAR BUILT: 1934

TYPE OF SUPERSTRUCTURE MAIN SPAN-**CONCRETE - TEE BEAM** APPR. SPAN: NOT APPLICABLE TYPE OF SUBSTRUCTURE ABUTMENTS: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION BENTS: **CONCRETE PILE BENT ON PILE FOUNDATION** PIERS: CONCRETE COLUMNS WITH SOLID WEB WALL (DUMB BELL) ON TIMBER PILE FOUNDATION SCOUR EVALUATION Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. **INSPECTION PROCEDURES** What Initiated the Call-out Inspection? [] BridgeWatch Alert [1 TDOT District or Local Maintenance Personnel [] THP or Local Law Enforcement Personnel [] Other: _ Things to check on a bridge during floods: [] - Span movement - horizontally as well as vertically 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck. 2. Check for plumb of piers or bents. [] - Check for embankment erosion [] - Check for drift build-up on piers or bents [] - Check pier exposure, if possible, and compare to previous inspection [] - Review the latest bridge inspection report versus current field conditions If Closure is recommended: [] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded. [] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained) (2) City or County Highway Maintenance Official (if bridge is not State maintained) (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate (4) TDOT Regional Bridge Engineer [] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made

PUBLICATION DATE

by a TDOT bridge inspection team.

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	th State District maintenance or local highway maintenance Any bridge on the selected detour route shall be checked
[] - The bridge can be re-opened only after a units and they are determined to be stru	a TDOT bridge inspection team checks the substructure cturally stable.
CONTACT PERSONNEL:	TELEPHONE NUMBER:
REGION BRIDGE ENGINEER	(731) 234-9561
DISTRICT MAINTENANCE SUPERVISOR	(731) 694-6673
TENNESSEE HIGHWAY PATROL	(731) 423-6635
[] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.	
COMMENTS:	
Suggested List of Equipment to conduct the In	nspection:
Latest Bridge Inspection Report	
Scour POA Report with the above Checklist	
Bridge Design Plans, if available Tape measure with weight	
Plumb bob	
Range Pole	
A 1000 Foot Roll of yellow Polyethylene Barrica	ade Tane printed with the following message:
SAFETY HAZADD	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24